PREPARED 4/24/08, 14:02:59

INSPECTION TICKET

PAGE

Harnett County

INSPECTOR: IVR

DATE 4/25/08

ADDRESS . : 87867 *UNASSIGNED

SUBDIV: CIDAR POR PHONE: (919) 552-3875

CONTRACTOR : VUNCANNON WILLIAM WADE

PHONE :

PARCEL . .: 05-0633- - -0112- -04-

OWNER . . : DENNING ANDREW & PAIGE

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: 401N TOWARDS KIPLING RD, LEFT ON

KIPLING RD, AT STOP SIGN GO STRAIGHT ACROSS ONTO COKESBURY RD, APPROX 1/2 -

3/4 MILE DOWN ON LEFT.

T/S: 01/03/2008 04:48 PM VBROWN ----

LAND NOTES: BPMN 2/05/07 Per Finance form, the above returned

check has been taken care of on 020107.

Customer can now proceed. djohnson

BPRC 11/02/06 Returned check sent to me on 11-2-06.

Until we have verification from Finance

customer cannot begin the permit

process for this parcel.

Nov 02, 2006 11:39 AM DJOHNSON -----

4/01/04 301.91 ac prince LXMN

STRUCTURE: 000 000 80X80 4BDR 4.5BATH

FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

REQUESTED INSP

DESCRIPTION

TYP/SO

COMPLETED RESULT RESULTS/COMMENTS

B101 01

R*BLDG FOOTING / TEMP SVC POLE VRU #: 001598952

INSPECTOR: IVR

DATE

5/02/08

ADDRESS . : 87867 *UNASSIGNED SUBDIV:

CONTRACTOR: VUNCANNON WILLIAM WADE

PHONE: (919) 552-3875

PHONE :

OWNER . . : DENNING ANDREW & PAIGE

PARCEL . .: 05-0633- - -0112- -04-

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD) DIRECTIONS: 401N TOWARDS KIPLING RD, LEFT ON

KIPLING RD, AT STOP SIGN GO STRAIGHT ACROSS ONTO COKESBURY RD, APPROX 1/2 -

3/4 MILE DOWN ON LEFT.

T/S: 01/03/2008 04:48 PM VBROWN ----

LAND NOTES: BPMN 2/05/07 Per Finance form, the above returned

check has been taken care of on 020107.

Customer can now proceed. djohnson

BPRC 11/02/06 Returned check sent to me on 11-2-06.

Until we have verification from Finance

customer cannot begin the permit

process for this parcel.

Nov 02, 2006 11:39 AM DJOHNSON -----

4/01/04 301.91 ac prince

STRUCTURE: 000 000 80X80 4BDR 4.5BATH

FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/25/08 4/25/08	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001598952
A814 01	5/02/08	TI.	ADDRESS CONFIRMATION VRU #: 001602382
B103 01	5/02/08 5-2-0	APBS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001602390 WILL BE A POURED CONCRETE FOUNDATION.

PREPARED 5/07/08, 14:01:43
Harnett County Harnett County

INSPECTION TICKET INSPECTOR: IVR

PHONE: (919) 552-3875

PAGE DATE

5/08/08

18

ADDRESS . : 87867 *UNASSIGNED SUBDIV:

CONTRACTOR : VUNCANNON WILLIAM WADE

OWNER . . : DENNING ANDREW & PAIGE PHONE :

PARCEL . . : 05-0633- - -0112- -04-

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD) DIRECTIONS: 401N TOWARDS KIPLING RD, LEFT ON

KIPLING RD, AT STOP SIGN GO STRAIGHT ACROSS ONTO COKESBURY RD, APPROX 1/2 -

3/4 MILE DOWN ON LEFT.

T/S: 01/03/2008 04:48 PM VBROWN ----

LAND NOTES: BPMN 2/05/07 Per Finance form, the above returned

check has been taken care of on 020107.

Customer can now proceed. djohnson

BPRC 11/02/06 Returned check sent to me on 11-2-06.

Until we have verification from Finance

customer cannot begin the permit

process for this parcel.

Nov 02, 2006 11:39 AM DJOHNSON -----

LXMN 4/01/04 301.91 ac prince

STRUCTURE: 000 000 80X80 4BDR 4.5BATH

FLOOD ZONE . . . : FLOOD ZONE X

SEPTIC - EXISTING? . . . : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/25/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001598952
	4/25/08	AP	i
B103 01	5/02/08	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001602390
	5/02/08	AP	WILL BE A POURED CONCRETE FOUNDATION. need premise number to release power for t pole
7014 01	E /00 /00	m T	-
A814 01	5/08/08	TI	ADDRESS CONFIRMATION VRU #: 001605849
B113 01	5/08/08	TI	R*BLDG WATER/DAMP PROOFING VRU #: 001605831
	5.8.08	APBS_	

----- COMMENTS AND NOTES -----------



MOISTURE OUT. CONFIDENCE IN:

TUFF-N-DRI SYSTEM APPLICATION

TUFF-N-DRI® is North America's #1 brand of waterproofing for new basements. It protects against three main sources of moisture from basement walls: - leaks, seepage and interior condensation.

Installed by select applicators. TUFF-N-DRI Basement Waterproofing System is installed only by Barrier Solutions Contractors. These contractors undergo training to ensure the highest quality application.

Surface preparation. The wall surface should be smooth and monolithic. Remove loose aggregate and sharp protrusions from the wall. Voids, spalled areas and exposed aggregate should be patched with a suitable mastic before spraying. TUFF-N-DRI membrane does not require any priming or special preparation.

System application. TUFF-N-DRI membrane is sprayed evenly over the entire foundation wall. WARM-N-DRI* Foundation Board is applied over the waterproofing membrane as it cures.

TUFF-N-DRI Basement Waterproofing System can be applied when ambient temperatures are as low as 20°F, allowing for fewer construction delays. TUFF-N-DRI membrane may be applied on poured concrete and block foundations. On poured concrete basements, TUFF-N-DRI can be applied as soon as the forms are removed, and on block basements, as soon as the mortar is dry.

Foundation board performance. WARM-N-DRI Foundation Board keeps foundation wall temperatures closer to the air temperature of the basement, which helps reduce interior condensation. Reduced condensation ensures less humid, more comfortable basement space. The placement of the foundation board on the wall's exterior also helps reduce the risk of damage due to freeze/thaw cycles, particularly if the foundation board is extended to the sill plate.

In addition, the foundation board protects TUFF-N-DRI membrane from damage during backfilling or damage from other construction trades. The compressibility of the foundation board will also absorb moderate soil expansion and help protect the basement wall.


To assist drainage, WARM-N-DRI Foundation Board should extend to the footing and connect to a functioning perimeter drainage system, such as DrainStar® Stripdrain. The foundation board is required for all warranted TUFF-N-DRI Basement Waterproofing System installations.

Model Energy Code. Computer analysis of home energy use indicates that a considerable portion of a typical home's energy loss comes from heated, uninsulated basements. By installing the foundation board to the sill plate, the entire basement wall is insulated, and energy efficiency is maximized. Many states have adopted the Model Energy Code. Because WARM-N-DRI Foundation Board provides insulating performance, it assists with compliance to this code.

Environmentally responsible. TUFF-N-DRI membrane uses a non-flammable, water-based carrier that meets VOC limits in all 50 U.S. states. It has been thoroughly tested by independent labs using Federal EPA standards for leaching. The results prove that no harmful leaching of the TUFF-N-DRI membrane occurs.

Availability and cost. TUFF-N-DRI Basement Waterproofing System is competitively priced and available through your local Barrier Solutions Contractor. For details, contact your local Barrier Solutions Contractor, call 800-DRY-BSMT or visit TUFF-N-DRI.com.

TUFF:N-DRI features a reliable system to control moisture from basement walls:



(A) Affectblewaterprofingmembrane is gray applied to seamlessly span front at insulation wall settling cracks and seal and waterpenetration.

(B) WARM-MERI foundation Board costs is drainage and insulates basement walls to reduce interference and insulates basement.

(Q) Shownwith optional Dratistur Stiffed in Instantial Confederation of the Confederation of





ICC Evaluation Service, Inc.

www.icc-es.org

Business/Regional Office ■ 5360 Workman Mill Road, Whittier, California 90601 ■ (562) 699-05 Regional Office ■ 900 Montclair Road, Suite A, Birmingham, Alabama 35213 ■ (205) 599-98 Regional Office ■ 4051 West Flossmoor Road, Country Club Hills, Illinois 60478 ■ (708) 799-23

The Subcommittee on Evaluation has reviewed the data submitted for compliance with the Standard Building Code©, the Standard Plumbing Code©, the Florida Building Code Building, the International Private Sewage Disposal Code, and the International One and Two Family Dwelling Code and submits to the Building Official or other authority having jurisdiction the following report. The Subcommittee on Evaluation, and ICC-ES and its staff are not responsible for any errors or omissions to any documents, calculations, drawings, specifications, tests or summaries prepared and submitted by the design professional or preparer of record that are listed in the Substantiating Data Section of this report.

REPORT NO.: 2226

EXPIRES: See the current EVALUATION REPORT INDEX

CATEGORY: FOUNDATION SYSTEMS

SUBMITTED BY:

RING INDUSTRIAL GROUP EZ FLOW BRANDS 65 INDUSTRIAL PARK ROAD OAKLAND, TENNESSEE 38060

- PRODUCT TRADE NAME
- 1.1 EZflow 0701
- 1.2 EZflow 1001
- 1.3 EZflow 1201

2. SCOPE OF EVALUATION

Footing drain and septic tank drain lines

USES

Footing and foundation drainage and septic tank drain lines.

4. DESCRIPTION

4.1 EZflow 0701

The EZflow 0701 is a prefabricated drainage system designed to replace stone aggregated subsurface drains. It consists of a 3 inch (51 mm) diameter perforated corrugated plastic pipe surrounded by 2 inches (51 mm) of aggregate. The aggregate is an expanded polystyrene (EPS) and is held in place with a polyethylene netting. The aggregate is treated with calcium sterate. It is supplied in 10 foot (3 m) long sections.

4.2 EZflow 1001

The EZflow 1001 is a prefabricated drainage system designed replace stone aggregated subsurface drains. I consists of a inch (102 mm) diameter perforated corrugated plastic pi surrounded by 3 inches (76 mm) of aggregate. The aggregation and expanded polystyrene and is held in place with polyethylene or geo-textile netting. The aggregate is treated we calcium sterate. It is supplied in 10 foot (3 m) long sections.

4.3 EZflow 1201

The EZflow 1201 is a prefabricated drainage system designed replace stone aggregated subsurface drains. It consists of a inch (102 mm) diameter perforated corrugated plastic p surrounded by 4 inches (102 mm) of aggregate. The aggreg is an expanded polysytrene and is held in place with polyethylene or geo-textile netting. The aggregate is treated v calcium sterate. It is supplied in 10 foot (3 m) long sections.

4.4 Septic Tank Drain Lines

EZflow 1001 and EZflow 1201 may be used for septic tank dr lines. When used as septic tank drain lines, one or m bundles of only EPS aggregate are placed in the trench with drain lines.

5. INSTALLATION

5.1 General

The manufacturer's published installation instructions shall strictly adhered to and a copy of these instructions shall available at all times on the jobsite during installation.

5.2 Foundation Drains

The EZflow 0701 is installed on foundation walls that are u five concrete masonry units high [42 inches (1067 mm)]. maximum allowable length of the drain is 220 feet (67 m).

The EZflow 1001 is installed on foundation walls that are up to concrete masonry units high [170 inches (4318 mm)].

The EZflow 1201 is installed on foundation walls that are gre than 20 concrete masonry units high [170 inches (4318 mr

5.3 Septic Tank Drain Lines

See the manufacturer's installation instructions to determine required length of the drain for the applicable installa configuration.

ICC-ES legacy reports are not to be construed as representing aesthetics or any other attributes not specifically addressed, nor are they to be construed as an endorsement of the softhe report or a recommendation for its taxy. There is no wavranty by ICC Evaluation Service, lites, express or implied, as to any finding or other matter in this report, or as to any property by the covered by the cover.

٦ إسعور والخمر ا

SUBSTANTIATING DATA 6.

- Manufacturer's specifications, drawings, and installation 6.1 instructions.
- Engineering calculations titled "Flow Calculations for a Twelve-Inch Gravel Trench and EZflow 1201, 1001, and 6.2 601", dated January 18, 2002, signed and sealed by Robert A. Beem, P.É.
- Technical paper titled "Sizing of a Geosynthetic Drainage System Used in Septic Tank Drainfields", by J.P. Giroud, 6.3 K.L. Soderman, and K.O. Pankow; signed and sealed by K.O. Pankow, P.E.

CODE REFERENCES 7.

Standard Building Code - 1999 Edition

Alternate Materials and Methods Section 103.7 Dampproofing Protection from Termite Damage Section 1814.3 Section 2603.3

Standard Plumbing Code - 1994 Edition with 1995/1996/ 1997 Revisions

Alternate Materials and Methods Section 103.7 Disposal Fields Section E106

International Private Sewage Disposal Code - 1997 Edition

Methods and Alternate Materials, Section 105.2 Equipment Distribution Pipe

Section 505.1.1 Conventional Soil Installation of Section 605

Absorption Systems

International One and Two Family Dwelling Code - 1998 Edition

Alternate Materials and Systems Section 108 Termite Damage Section 317.5 Foam Plastic Protection Section 323.4 Drainage Section 401.3 Foundation Drainage Section 405 Drain Lines Section 3808

Florida Building Code, Building - 2001 Edition

Alternate Materials and Methods Section 103.7 Dampproofing Section 1814.3 Protection from Termite Damage Section 2603.3

COMMITTEE FINDINGS 8.

The Subcommittee on Evaluation in review of the data submifinds that, in their opinion, EZflow 0701, EZflow 1001, and EZ 1201 as described in this report conform with or are suita alternates to that specified in the Standard Building Code, Standard Plumbing Code, the Florida Building Code - Build the International Private Sewage Disposal Code, and International One and Two Family Dwelling Code Supplements thereto.

LIMITATIONS 9.

- An approved filter membrane shall be used with E. foundation drain systems in accordance with the c
- Where required by Section 2603.3 of the Sta. Building Code, an approved method of protectin 92 foam plastic from subterranean termite damage st provided.
- An untreated 60 lb kraft paper shall be used with (9.3 septic tank drain line systems.
- Calculations shall be submitted to the authority jurisdiction showing that the septic tank drain line: 9.4 provides the required drainage field area when a for permit.

IDENTIFICATION 10.

All packaging of EZflow 0701, EZflow 1001, and EZflc shall bear the manufacturer's name and/or trademark, the Public Safety Testing and Evaluation Service, Inc. initials PST & ESI) or seal, and the number of this report identification.

PERIOD OF ISSUANCE 11.

SEE THE CURRENT EVALUATION REPORT IND STATUS OF THIS LEGACY EVALUATION REPORT.

For information on this report contact: Woods McRoy, P.E. 205/599-9800


$\mathbf{EZ}flow_{\mathrm{o}}$ Drainage Products



Ring Industrial Group's **EZ**flow Drainage System is the leading geosynthetic aggregate pipe system for use in drainage applications. Manufactured from recycled polystyrene, **EZ**flow evacuates up to five times more water than standard gravel and pipe drainage systems. **EZ**flow provides maximum system life and performance, lower system costs, and an environmentally friendly alternative.

PRODUCT DESCRIPTION

EZflow drain product is 10 feet in length with a slotted pipe surrounded by polystyrene aggregate and



enclosed in geotextile mesh. Configurations are available in 10" OD bundles with a 4" pipe and 15" OD bundles with a 6" pipe.


FEATURES AND BENEFITS

- Ease of Installation. Convenient 10' sections are easy to connect by using internal couplers.
 EZflow products can be easily transported and installed by a single worker which dramatically reduces labor costs.
- Performance. EZflow has a superior flow rate with up to five times the flow rate of gravel, which products quick evacuation of water in the system. EZflow has high storage capacity created by the engineered flow channels in the aggregate.
- Flexibility. EZflow's aggregate pipe combination and aggregate only bundles can easily bend around corners and other obstacles to conform to your project needs.
- Environmentally Friendly. Using EZflow recycled polystyrene aggregate prevents millions of pounds of waste from filling landfills.
- Reliability. Using EZflow drainage products means fewer call backs.

APPLICATIONS

Foundation Drains. Relieves ground water

pressure around the basement or foundation. **EZ**-flow drainage products are approved by the SBCCI and the ICC Evaluation



Service, Inc. Report #2226 dated August 1, 2006

- French Drains. EZflow french drains or curtain drains are used for dewatering soils where water saturation is a problem. Standing water or muddy soil can be eliminated by installing EZflow french drains or curtain drains to gather unwanted or standing water and move it to a downstream outlet.
- Landscape Drains. Excessive and standing water in or around landscaped areas can be rem-

edied by using



EZflow drainage system's 10" products. The product should be laid around the perimeter of the landscaped area

and/or through the landscaped area with outlet point relatively lower than the inlet areas.

- Retaining Wall Drains. EZflow drainage system's 10" products are installed at the bottom of the wall with a downward outlet which relieves pressure that water may exert on the wall.
- **Interceptor Drains. EZ***flow* drainage system's 10" products can be used to intercept groundwater movement toward an area where water table control is essential. Elevation must be lower than protected area.
- Roof Run-off Drains. Rainwater run-off can be collected from roof by way of guttering and stored in an EZflow drainfield until it can be perked into soil, helping to restore ground water.


100' of **EZ***flow* replaces 5 tons of gravel for a quick and clean job!

Solve your dewatering problems

est drainage problems vide everything you need to solve the toughimply -- EASY TO INSTALL. Our systems pro-The proven **EZ**flow systems are just what they

Use the **EZ**flow systems for:

- Foundation drains -- eliminates the need for gravel and meets all building codes
- Rainwater run-off -- provides collection beds to percolate rain water into the soil
- French drains -- controls ground water
- Landscaping -- less site disruption
- Retaining walls -- reduces hydraulic pres-



Product Description

and 7", 10", 12" or 14" in diameter. or 4" drainpipe. The units are 10' in length capsulated with strong netting around a 3 weight, geosynthetic aggregate that is en-**EZ**flow systems are made of tough light-



Consistent Shape

Engineered

Flow Channels

Product Benefits

- The best contouring product available
- Over 50% void area for greater water movement
- Reduces man hours


Saves landscaping during installation


- Will not crush
- Will not degrade
- Will not breakdown! EZ/low


RINGINDUSTRIAL

EZflow Product Sizes

0701F







4" Pipe

$\mathbf{E}\mathbf{Z}_{flow}$ Accessories

- 3" and 4" Internal Couplers
- 3" and 4" Internal End Caps
- 3" and 4" Internal Tees
- 3" and 4" Internal Wyes



Contact Us!

For more information contact **EZ**flow a (800) 649-0253 or www.ringindustrial.com.

PREPARED 5/15/08, 15:10:12 Harnett County

INSPECTION TICKET INSPECTOR: IVR

SUBDIV:

PHONE :

PHONE: (919) 552-3875

PAGE DATE

ADDRESS . : 87867 *UNASSIGNED CONTRACTOR : VUNCANNON WILLIAM WADE

OWNER . . : DENNING ANDREW & PAIGE
PARCEL . : 05-0633- - -0112--04APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)

	SF 00 CP * REQUESTED COMPLETED	SFD INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/25/08 4/25/08	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001598952
B103 01	5/02/08 5/02/08	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001602390 WILL BE A POURED CONCRETE FOUNDATION. need premise number to release power for t pole
B113 01	5/08/08 5/08/08	BS AP	R*BLDG WATER/DAMP PROOFING VRU #: 001605831
A814 01	5/08/08 5/13/08	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001605849 360 CEDAR ROCK TRL LOT 2
P309 01	5/15/08 3/5:08	TI	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001610799
			COMMENTS AND NOTES

PREPARED 5/21/08, 9:55:38 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE

ADDRESS . : 354 CEDAR ROCK TRL

SUBDIV:

PHONE: (919) 552-3875 PHONE :

CONTRACTOR: VUNCANNON WILLIAM WADE
OWNER . .: DENNING ANDREW & PAIGE
PARCEL . .: 05-0633- - -0112- -04APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)

PERMIT: CI	PSF 00 CP *		
		INSP	DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B101 01	4/25/08 4/25/08	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001598952
B103 01	5/02/08 5/02/08	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001602390 WILL BE A POURED CONCRETE FOUNDATION. need premise number to release power for t pole
B113 01	5/08/08 5/08/08	BS AP	R*BLDG WATER/DAMP PROOFING VRU #: 001605831
A814 01	5/08/08 5/13/08	TI DA	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001605849 360 CEDAR ROCK TRL LOT 2
P309 01	5/15/08 5/15/08	BS AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001610799
A814 02	5/20/08 5/20/08	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001612456 354 CEDAR ROCK TRL LOT 2
P309 02	5/21/08 5/21/08	BS CA	R*PLUMB UNDER SLAB VRU #: 001612712 wrong inspection called in
B111 01	5/21/08 5:21-08	40BS	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001613082
			COMMENTS AND NOTES

PREPARED 6/13/08, 14:01:14
Harnett County

INSPECTION TICKET

INSPECTION TICKET

PAGE

DATE 6/16/08

ADDRESS . : 354 CEDAR ROCK TRL

SUBDIV:

CONTRACTOR : VUNCANNON WILLIAM WADE PHONE : (919) 552-3875

OWNER . . : DENNING ANDREW & PAIGE

PHONE :

PARCEL . . : 05-0633- - -0112- -04-

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)
DIRECTIONS: 401N TOWARDS KIPLING RD, LEFT ON
KIPLING RD, AT STOP SIGN GO STRAIGHT

KIPLING RD, AT STOP SIGN GO STRAIGHT ACROSS ONTO COKESBURY RD, APPROX 1/2 -

3/4 MILE DOWN ON LEFT.

T/S: 01/03/2008 04:48 PM VBROWN ----

LAND NOTES: BPMN 2/05/07 Per Finance form, the above returned

check has been taken care of on 020107.

Customer can now proceed. djohnson

BPRC 11/02/06 Returned check sent to me on 11-2-06.

Until we have verification from Finance

customer cannot begin the permit

process for this parcel.

Nov 02, 2006 11:39 AM DJOHNSON -----

LXMN 4/01/04 301.91 ac prince

STRUCTURE: 000 000 80X80 4BDR 4.5BATH

FLOOD ZONE . . . : FLOOD ZONE X

PERMIT:	PERMIT: CPSF 00 CP * SFD					
	REQUESTED	INSP	DESCRIPTION			
TYP/SQ	COMPLETED R	ESULT	RESULTS/COMMENTS			
B101 01	4/25/08 B:	s	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001598952			
	4/25/08 A	P				
B103 01	5/02/08 B	S	R*BLDG FOUND & TEMP SVC POLE VRU #: 001602390			
	5/02/08 A	P	WILL BE A POURED CONCRETE FOUNDATION.			
			need premise number to release power for t pole			
B113 01	5/08/08 B	s	R*BLDG WATER/DAMP PROOFING VRU #: 001605831			
	5/08/08 A	P				
A814 01	5/08/08 T	I	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001605849			
	5/13/08 D	A	360 CEDAR ROCK TRL LOT 2			
P309 01	5/15/08 B	s	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001610799			
	5/15/08 A	P				
A814 02	5/20/08 TI	W	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001612456			
	5/20/08 A	P	354 CEDAR ROCK TRL LOT 2			
P309 02	5/21/08 B	s	R*PLUMB UNDER SLAB VRU #: 001612712			
	5/21/08 C	A	wrong inspection called in			
B111 01	5/21/08 B	S	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001613082			
	5/21/08 A	P				
B105 01	6/16/08 T	Į , ,	R*OPEN FLOOR TIME: 17:00 VRU #: 001625813			
	10-14:08 A	HUKS				

PREPARED 9/10/08, 13:59:51 INSPECTION TICKET PAGE 5 Harnett County INSPECTOR: IVR DATE 9/11/08

ADDRESS . : 354 CEDAR ROCK TRL SUBDIV:

CONTRACTOR : VUNCANNON WILLIAM WADE PHONE: (919) 552-3875

OWNER . . : DENNING ANDREW & PAIGE PHONE :

PARCEL . .: 05-0633- - -0112- -04-

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD) DIRECTIONS: 401N TOWARDS KIPLING RD, LEFT ON KIPLING RD, AT STOP SIGN GO STRAIGHT ACROSS ONTO COKESBURY RD, APPROX 1/2 -

3/4 MILE DOWN ON LEFT.

T/S: 01/03/2008 04:48 PM VBROWN ----

LAND NOTES: BPMN 2/05/07 Per Finance form, the above returned

check has been taken care of on 020107.

Customer can now proceed. djohnson

BPRC 11/02/06 Returned check sent to me on 11-2-06.

Until we have verification from Finance

customer cannot begin the permit

process for this parcel.

Nov 02, 2006 11:39 AM DJOHNSON -----

LXMN 4/01/04 301.91 ac prince

STRUCTURE: 000 000 80X80 4BDR 4.5BATH

FLOOD ZONE . . . : FLOOD ZONE X

4/25/08 BS

4/25/08 AP

BEDROOMS : 4.00 PROPOSED USE : SFD

SEPTIC - EXISTING? . . . : NEW

B101 01

PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION COMPLETED RESULT RESULTS/COMMENTS TYP/SQ ______

R*BLDG FOOTING / TEMP SVC POLE VRU #: 001598952

5/02/08 BS B103 01 R*BLDG FOUND & TEMP SVC POLE VRU #: 001602390 5/02/08 AP WILL BE A POURED CONCRETE FOUNDATION. need premise number to release power for t pole B113 01 5/08/08 BS R*BLDG WATER/DAMP PROOFING VRU #: 001605831

5/08/08 AP A814 01 5/08/08 TI ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001605849

DA 360 CEDAR ROCK TRL 5/13/08 LOT 2

P309 01 5/15/08 BS R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001610799

5/15/08 AP A814 02 5/20/08 TW ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001612456 AP 5/20/08 354 CEDAR ROCK TRL LOT 2

P309 02 5/21/08 BS R*PLUMB UNDER SLAB VRU #: 001612712

5/21/08 CA wrong inspection called in

B111 01 5/21/08 BS R*BLDG SLAB INSP TIME: 17:00 VRU #: 001613082 AP 5/21/08

> 6/16/08 BS

B105 01 R*OPEN FLOOR TIME: 17:00 VRU #: 001625813 6/16/08 ΑP

R427 01 9/11/08 FOUR TRADE ROUGH IN >2500 VRU #: 001675164 TI 9-11-8

----- COMMENTS AND NOTES ------

PREPARED 9/12/08, 13:59:46 Harnett County

INSPECTION TICKET

INSPECTOR: IVR

PAGE

919.427-6745

DATE

ADDRESS . : 354 CEDAR ROCK TRL CONTRACTOR : VUNCANNON WILLIAM WADE PHONE: (919) 552-3875

OWNER . . : DENNING ANDREW & PAIGE PHONE :

PARCEL . .: 05-0633- - -0112- -04-

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: 401N TOWARDS KIPLING RD, LEFT ON

KIPLING RD, AT STOP SIGN GO STRAIGHT ACROSS ONTO COKESBURY RD, APPROX 1/2 -

3/4 MILE DOWN ON LEFT.

T/S: 01/03/2008 04:48 PM VBROWN ----

LAND NOTES: BPMN 2/05/07 Per Finance form, the above returned

check has been taken care of on 020107.

Customer can now proceed. djohnson

BPRC 11/02/06 Returned check sent to me on 11-2-06.

Until we have verification from Finance

customer cannot begin the permit

process for this parcel.

Nov 02, 2006 11:39 AM DJOHNSON ----

LXMN 4/01/04 301.91 ac prince

STRUCTURE: 000 000 80X80 4BDR 4.5BATH

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 4.00 PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW

PERMIT:	PERMIT: CPSF 00 CP * SFD				
	REQUESTED		DESCRIPTION		
TYP/SQ			RESULTS/COMMENTS		
	4/25/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001598952		
	4/25/08	AP			
B103 01	5/02/08	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001602390		
	5/02/08	AP	WILL BE A POURED CONCRETE FOUNDATION.		
			need premise number to release power for t pole		
B113 01	5/08/08	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001605831		
	5/08/08	AP			
A814 01	5/08/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001605849		
	5/13/08	DA	360 CEDAR ROCK TRL LOT 2		
P309 01	5/15/08	BS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001610799		
	5/15/08	AP			
A814 02	5/20/08	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001612456		
	5/20/08	AP	354 CEDAR ROCK TRL LOT 2		
P309 02	5/21/08	BS	R*PLUMB UNDER SLAB VRU #: 001612712		
	5/21/08	CA	wrong inspection called in		
B111 01	5/21/08	BS	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001613082		
	5/21/08	AP			
B105 01	6/16/08	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 001625813		
	6/16/08	AP			
R427 01	9/11/08	BS_	FOUR TRADE ROUGH IN >2500 VRU #: 001675164		
	9/11/08 /	DP)	Nail ledger at rear deck / porch. 12. Cannot use lags for		
	(. /	deck/porch band support. Must be 1/2 inch through bolts.3.		
			Bond gas line at supply connection. Sheet inside garage		
			walls with osb (1st floor and basement). 45. Need engineers		
			repair on missing bolts in garage bottom plate. Code		
			requires embedded bolts.6. Need tempered glass at rear		

door. Weed hurricane ties at rear porch roof. 8. Need

PREPARED 9/12/08, 13:59:46 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE

9/15/08

ADDRESS . : 354 CEDAR ROCK TRL

SUBDIV:

PHONE :

CONTRACTOR : VUNCANNON WILLIAM WADE

PHONE: (919) 552-3875

OWNER . . : DENNING ANDREW & PAIGE

PARCEL . . : 05-0633- - -0112- -04-

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)

REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

nail plates at refridgerationm lines at upstairs bath wall.9.. Plumbing nail plate at upstairs bedroom wall bottom plate.10 Need engineers design on hearth (masonry) supported by wood wall and TJI floor system below .11. Need

hangers above garage entry door. Do not insulate

FOUR TRADE ROUGH IN >2500 VRU #: 001676550

R427 02

Leake Associates

Consulting Structural Engineers

875 Walnut Street, Suite 250 Cary, North Carolina 27511 LLeake@LeakeAssociates.com Office: [919] 460-1301 Fax: (919) 460-3168

Date: September 14, 2008 **Client:** Andy & Paige Denning

Project: Denning Residence

Lot 42, Cedar Rock Subdivision Harnett County, North Carolina

Vuncannon Designs Denning Residence Custom Plan

1. Vuncannon Designs – Denning Residence Custom Plan


Via Email: Andy and Paige Denning [adenning001@nc.rr.com]

Field Change Request

Dear Andy & Paige:


At your request, I have examined two framing conditions that were recently noted by the Harnett County Inspections process. This letter presents the results of my examination.

1) Framing at fireplace hearth – The photo below depicts the framing condition at the fireplace hearth, including the steel angle framing that provides support for the poured concrete hearth. The first floor joist has been headed off into single headers, that frame between the outside wall and the second floor joist. All members are connected with steel joist hangers. This condition is acceptable as framed, including the steel framing for the fireplace hearth, and no modification is required.



Framing at Fireplace

2) Anchor bolts at front wall of garage – Due to misplacement of the cast-in-place anchor bolts by the foundation contractor, it was necessary to replace them with drilled "Red Head" expansion anchors. The anchors are ½" diameter by 6" long. The picture below depicts the installation of one of these anchor bolts. This condition is not acceptable, as there is minimal embedment of the anchor bolt in the concrete masonry. These should be re-worked, so that there is at least 3½" embedment of each bolt in concrete. Once the bolts are re-worked to this specification, then I can certify that the substitution of "Red Head" anchor bolts, ½" diameter x 6" long is an acceptable condition.



Garage Anchor Bolts



Lawrence R. Leake, P. E. Leake Associates

Brad I've REWORKed the bolts.

Thanks WADE

w/o Attachments

PREPARED 9/18/08, 14:08:28
Harnett County

INSPECTION TICKET

INSPECTOR: IVR

PAGE

DATE

9/19/08

ADDRESS . : 354 CEDAR ROCK TRL SUBDIV:

CONTRACTOR : VUNCANNON WILLIAM WADE PHONE : (919) 552-3875

OWNER . . : DENNING ANDREW & PAIGE PHONE :

PARCEL . . : 05-0633- - -0112--04- wads - 429-6745

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)
DIRECTIONS: 401N TOWARDS KIPLING RD, LEFT ON
KIPLING RD, AT STOP SIGN GO STRAIGHT
ACROSS ONTO COKESBURY RD, APPROX 1/2 -

3/4 MILE DOWN ON LEFT.

T/S: 01/03/2008 04:48 PM VBROWN ----

LAND NOTES: BPMN 2/05/07 Per Finance form, the above returned

check has been taken care of on 020107. Customer can now proceed. djohnson

BPRC 11/02/06 Returned check sent to me on 11-2-06.

Until we have verification from Finance

customer cannot begin the permit

process for this parcel.

Nov 02, 2006 11:39 AM DJOHNSON -----

LXMN 4/01/04 301.91 ac prince

STRUCTURE: 000 000 80X80 4BDR 4.5BATH

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 4.00 PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW

PERMIT:	CPSF 00 CP *	=	
	REQUESTED		DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B101 01	4/25/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001598952
	4/25/08	AP	
B103 01	5/02/08	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001602390
	5/02/08	AP	WILL BE A POURED CONCRETE FOUNDATION.
			need premise number to release power for t pole
B113 01	5/08/08	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001605831
	5/08/08	AP	
A814 01	5/08/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001605849
	5/13/08	DA	360 CEDAR ROCK TRL LOT 2
P309 01	5/15/08	BS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001610799
	5/15/08	AP	
A814 02	5/20/08	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001612456
	5/20/08	AP	354 CEDAR ROCK TRL LOT 2
P309 02	5/21/08	BS	R*PLUMB UNDER SLAB VRU #: 001612712
	5/21/08	CA	wrong inspection called in
B111 01	5/21/08	BS	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001613082
	5/21/08	AP	
B105 01	6/16/08	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 001625813
	6/16/08	AP	
R427 01	9/11/08	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001675164
	9/11/08	/ DP)	1. Nail ledger at rear deck / porch. 2. Cannot use lags for
			deck/porch band support. Must be 1/2 inch through bolts.3.
			Bond gas line at supply connection. 4. Sheet inside garage
			walls with osb (1st floor and basement). 5. Need engineers
			repair on missing bolts in garage bottom plate. Code
			requires embedded bolts.6. Need tempered glass at rear
			door. 7. Need hurricane ties at rear porch roof. 8. Need

PREPARED 9/18/08, 14:08:28 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 9/19/08

ADDRESS . : 354 CEDAR ROCK TRL

SUBDIV:

CONTRACTOR : VUNCANNON WILLIAM WADE

PHONE: (919) 552-3875

OWNER . . : DENNING ANDREW & PAIGE

PHONE :

PARCEL . . : 05-0633- - -0112- -04-

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R427 02	9/15/08	BS	nail plates at refridgerationm lines at upstairs bath wall.9 Plumbing nail plate at upstairs bedroom wall bottom plate.10 Need engineers design on hearth (masonry) supported by wood wall and TJI floor system below .11. Need hangers above garage entry door. Do not insulate FOUR TRADE ROUGH IN >2500 VRU #: 001676550
R427 U2	9/15/08	DA	1. Nail plate for hvac upstairs not installed. Must be a structural nail plate, this is a load wall. 2. Need hangers above entry to dining room. ok to insulate. CHECK TEMPERED GLASS AT FINAL
I129 01	9/19/08 9:18: 28	DARS	R*INSULATION INSPECTION VRU #: 001679851
R427 03	3/19/08	APRS	FOUR TRADE ROUGH IN >2500 VRU #: 001679844

PREPARED 12/23/08, 14:02:53 INSPECTION TICKET PAGE 1
Harnett County INSPECTOR: IVR DATE 12/29/08

ADDRESS . : 354 CEDAR ROCK TRL SUBDIV:

CONTRACTOR: VUNCANNON WILLIAM WADE PHONE: (919) 552-3875

OWNER : DENNING ANDREW & PAIGE PHONE :

PARCEL . . : 05-0633- - -0112- -04-

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : 401N TOWARDS KIPLING RD, LEFT ON

KIPLING RD, AT STOP SIGN GO STRAIGHT ACROSS ONTO COKESBURY RD, APPROX 1/2 -

3/4 MILE DOWN ON LEFT.

T/S: 01/03/2008 04:48 PM VBROWN ----

LAND NOTES: BPMN 2/05/07 Per Finance form, the above returned

check has been taken care of on 020107.

Customer can now proceed. djohnson

BPRC 11/02/06 Returned check sent to me on 11-2-06.

Until we have verification from Finance

customer cannot begin the permit

process for this parcel.

Nov 02, 2006 11:39 AM DJOHNSON -----

LXMN 4/01/04 301.91 ac prince

STRUCTURE: 000 000 80X80 4BDR 4.5BATH

FLOOD ZONE . . . : FLOOD ZONE X

SEPTIC - EXISTING? . . . : NEW

PERMIT: (CPSF 00 CP *	SFD INSP	DESCRIPTION
marp /ao	REQUESTED		
TYP/SQ	COMPLETED	RESULI	RESOLIS/ COMMENTS
B101 01	4/25/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001598952
	4/25/08	AP	
B103 01	5/02/08	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001602390
	5/02/08	AP	WILL BE A POURED CONCRETE FOUNDATION.
			need premise number to release power for t pole
B113 01	5/08/08	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001605831
	5/08/08	AP	
A814 01	5/08/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001605849
	5/13/08	DA	360 CEDAR ROCK TRL LOT 2
P309 01	5/15/08	BS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001610799
	5/15/08	AP	
A814 02	5/20/08	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001612456
	5/20/08	AP	354 CEDAR ROCK TRL LOT 2
P309 02	5/21/08	BS	R*PLUMB UNDER SLAB VRU #: 001612712
	5/21/08	CA	wrong inspection called in
B111 01	5/21/08	BS	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001613082
	5/21/08	AP	
B105 01	6/16/08	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 001625813
	6/16/08	AP	
R427 01	9/11/08	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001675164
	9/11/08	DP	1. Nail ledger at rear deck / porch. 2. Cannot use lags for
			deck/porch band support. Must be 1/2 inch through bolts.3.
			Bond gas line at supply connection. 4. Sheet inside garage
			walls with osb (1st floor and basement). 5. Need engineers
			repair on missing bolts in garage bottom plate. Code
			requires embedded bolts.6. Need tempered glass at rear

----- CONTINUED ONTO NEXT PAGE -----

PREPARED 12/23/08, 14:02:53

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 12/29/08 Harnett County

ADDRESS . : 354 CEDAR ROCK TRL

SUBDIV:

CONTRACTOR : VUNCANNON WILLIAM WADE PHONE: (919) 552-3875

OWNER . . : DENNING ANDREW & PAIGE

PHONE :

PARCEL . . : 05-0633- - -0112- -04-

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED		DESCRIPTION RESULTS/COMMENTS
			door. 7. Need hurricane ties at rear porch roof. 8. Need nail plates at refridgerationm lines at upstairs bath wall.9. Plumbing nail plate at upstairs bedroom wall bottom plate.10 Need engineers design on hearth (masonry) supported by wood wall and TJI floor system below .11. Need hangers above garage entry door. Do not insulate
R427 02	9/15/08	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001676550
	9/15/08	DA	1. Nail plate for hvac upstairs not installed. Must be a structural nail plate, this is a load wall. 2. Need hangers above entry to dining room. ok to insulate. CHECK TEMPERED GLASS AT FINAL
I129 01	9/19/08	BS	R*INSULATION INSPECTION VRU #: 001679851
	9/19/08	DA	Must insulate floor joists above mechanical room in basement. will check at final. Ceiling to be acoustical
R427 03	9/19/08	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001679844
	9/19/08	AP	
R431 01	12/19/08	TI	FOUR TRADE FINAL >2500 VRU #: 001719533
	12/18/08	CA	CANCELLED FINAL INSPECTION FOR 12/19/08. NO OPERATIONS PERMIT. N-TART
R431 02	12/29/08	DO MA	FOUR TRADE FINAL >2500 VRU #: 001720994

------ COMMENTS AND NOTES ------

HARNETT COUNTY

Building Inspections Dept. 108 E. Front St. Lillington, NC 27546 910-893-7525

DO NOT REMOVE

DATE:12/29/08

7 m

PERMIT# 08-50019128

ADDRESS: 354 Cedar rock Trl.

VIOLATIONS:

- 1. Caulk around all toilets
- 2. Install all smoke detectors
- 3. Light missing in storage area in front bedroom
- 4. NEC 410.10(D) no part of a cord connected light fixture can be within 3' horiz. And 8' vert. of bathtub rims
- 5. Area under house adjacent to garage door must have a 20 min. rated ceiling
- 6. Handrail needed at front steps when more than 3 steps are installed
- 7. Outside receptacle required at rear of house accessible from ground
- 8. Install two ground rod system to main panel box
- 9. Bond the gas pipe system from the entrance to building to main disconnect box
- 10. \$Fee 50.00

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

PREPARED 12/29/08, 14:11:11

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 12/30/08

ADDRESS . : 354 CEDAR ROCK TRL

CONTRACTOR : VUNCANNON WILLIAM WADE

OWNER . . : DENNING ANDREW & PAIGE

PHONE: (919) 552-3875 PHONE :

SUBDIV:

PARCEL . . : 05-0633- - -0112- -04-

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			door. 7. Need hurricane ties at rear porch roof. 8. Need nail plates at refridgerationm lines at upstairs bath wall.9 Plumbing nail plate at upstairs bedroom wall bottom plate.10 Need engineers design on hearth (masonry) supported by wood wall and TJI floor system below .11. Need hangers above garage entry door. Do not insulate
R427 02	9/15/08	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001676550
	9/15/08	DA	1. Nail plate for hvac upstairs not installed. Must be a structural nail plate, this is a load wall. 2. Need hangers above entry to dining room. ok to insulate. CHECK TEMPERED GLASS AT FINAL
I129 01	9/19/08	BS	R*INSULATION INSPECTION VRU #: 001679851
	9/19/08	DA	Must insulate floor joists above mechanical room in basement. will check at final. Ceiling to be acoustical
R427 03	9/19/08	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001679844
	9/19/08	AP	
R431 01	12/19/08	TI	FOUR TRADE FINAL >2500 VRU #: 001719533
	12/18/08	CA	CANCELLED FINAL INSPECTION FOR 12/19/08. NO OPERATIONS PERMIT. N-TART
H824 01	12/23/08	OT Y	√ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001721372
	12/23/08	AP	
R431 02	12/29/08	MR	FOUR TRADE FINAL >2500 VRU #: 001720994
	12/29/08	DP	caulk around all toilets
			2. install all smoke detectors
			3. light missing in storage area in front bedroom
			nec 410.10.D requires 3' horic. and 8' vert clearance
			to a cord connected fixture from tub rim
			'S, area under house adjacent to garage door must have a 20min. rated ceiling
			handrail neededat front steps
			outside rec. required at rear of house accessible from grade
			8 install two ground rod system to main disc/ meter
			9 bond gas pipe system to main panel / ground sys.
R431 03	12/30/08	TI	FOUR TRADE FINAL >2500 VRU #: 001721570
		AP-M	R

----- COMMENTS AND NOTES -----

PREPARED 12/29/08, 14:11:11

INSPECTION TICKET

SUBDIV:

PAGE 1 DATE 12/30/08

Harnett County INSPECTOR: IVR DATE 12/30/08

ADDRESS . : 354 CEDAR ROCK TRL

CONTRACTOR : VUNCANNON WILLIAM WADE PHONE : (919) 552-3875

OWNER . . : DENNING ANDREW & PAIGE PHONE :

PARCEL . . : 05-0633- - -0112- -04-

APPL NUMBER: 08-50019128 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: 401N TOWARDS KIPLING RD, LEFT ON

KIPLING RD, AT STOP SIGN GO STRAIGHT ACROSS ONTO COKESBURY RD, APPROX 1/2 -

3/4 MILE DOWN ON LEFT.

T/S: 01/03/2008 04:48 PM VBROWN ----

LAND NOTES: BPMN 2/05/07 Per Finance form, the above returned

check has been taken care of on 020107.

Customer can now proceed. djohnson

BPRC 11/02/06 Returned check sent to me on 11-2-06.

Until we have verification from Finance

customer cannot begin the permit

process for this parcel.

Nov 02, 2006 11:39 AM DJOHNSON -----

LXMN 4/01/04 301.91 ac prince

STRUCTURE: 000 000 80X80 4BDR 4.5BATH


FLOOD ZONE : FLOOD ZONE $\mathbf X$

SEPTIC - EXISTING? : NEW

PERMIT:	PRRMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION					
			RESULTS/COMMENTS			
	4/25/08		R*BLDG FOOTING / TEMP SVC POLE VRU #: 001598952			
D101 01		AP	,			
B103 01		BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001602390			
2103 01	•	AP	WILL BE A POURED CONCRETE FOUNDATION.			
	0, 02, 00		need premise number to release power for t pole			
B113 01	5/08/08	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001605831			
5115 01	-,,	AP				
A814 01	-,, -	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001605849			
	• •	DA	360 CEDAR ROCK TRL LOT 2			
P309 01		BS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001610799			
		AP				
A814 02		TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001612456			
		AP	254 CEDAR ROCK TRL LOT 2			
P309 02		BS	V _{R*PLUMB} UNDER SLAB VRU #: 001612712			
	• •	CA	wrong inspection called in			
B111 01	• •	BS	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001613082			
	• •	AP				
B105 01	`. · · · · · · · · · · · · · · · · · · ·	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 001625813			
	* .	AP				
R427 01		BS	FOUR TRADE ROUGH IN >2500 VRU #: 001675164			
		DP	1. Nail ledger at rear deck / porch. 2. Cannot use lags for			
			deck/porch band support. Must be 1/2 inch through bolts.3.			
			Bond gas line at supply connection. 4. Sheet inside garage			
			walls with osb (1st floor and basement). 5. Need engineers			
			repair on missing bolts in garage bottom plate. Code			
			requires embedded bolts.6. Need tempered glass at rear			









December 29, 2008

Project Location:

354 Cedar Rock Trail

Fuquay Varina, NC 27526

Contractor:

Vuncannon Construction

To Whom it may concern:

The Suspended Ceiling installed in the above named property meets a minimum 1 hour Fire Rating as required by the current building code and as tested by Underwriters Laboratories. The ceiling grid is USG Donn DX/DXL Fire Rated Ceiling Grid and the ceiling tiles are USG ½" fire code panels.

Acoustical Ceilings • VCT • Sheet Vinyl • Commercial Carpet • Ceramic Tile • Computer Access Flooring • Laminates • Hardwood

P.O. Box 1688 • Fuquay-Varina, NC 27526 Phone: (919) 567-3370 • Fax (919) 567-3373

Sheetrock Lay-In Ceiling Panel ClimaPlus

Web Sites: usg.com usgdesígnstudío.com sustainablecellings.com seismiccellings.com

Technical Service 800 USG.4YOU Samples/Literature 688 874.2450 Samples/Literature Fax 888 874.2348 product information, Customer Service 800 950.3839

See usg.com for the most up-to-date

	Edge	Panel Size	Class ²	Item No.	(h) UL Classified							
, alisa Os. (§) Tuller Tun System Vistrania So violale sap					NRC ³	CAC Min.	LR'	Color	Abuse- Resistant	Grid Options	Recycled Content ⁵	Panel Cost
									4			
SHEETROCK Lay-In Ceiling Panel CLIMAPLUS, Vinyl	SQ	2'x2'x1/2"	0	3260	_	35	.77	White	4	A, B, C, D,	23%	\$
		2'x4'x1/2"	0	3270	_	40	.77	White	4	A.B, C,D,	23%	\$
SHEETROCK Lay-In Ceiling Panel <i>CumaPlus,</i> Clean Room ^s	S0	2'x4'x1/2"	0	3200	_	40	.77	White	4	A,B, C,D,	23%	\$\$
	A Donn ^a DX [®] /DXL [™]	B C ZXLA**	D Donn Cl	77		-1	•		•			
Grid Profile Options												

Physical Data/ Footnotes

Product literature Data sheet: SC1820

ASTM E1264 classification Type XX, Pattern G

ASTM EB4 surface burning characteristics Class A

Vinyl Flame spread: 25 Smoke developed: 50 CLEAN ROOM Flame spread: 25

Weight

 $1/2^{N} \approx 2.00$ fb /sq. ft.

Thermal resistance $1/2^{\prime\prime}\approx$ up to R-0.45

Maximum backloading See Warranty for details

Maintenance

Can be cleaned easily with a damp sponge. Use mild detergent and water – do not use acetate, ammonia or high concentration of chlorine, bromide or other harsh chemicals

U.S. Coast Guard acceptance

Approved for use on merchant ships.

Footnotes
1. Dependent on location; see Sustamability selector. 2. Fire-raled items: see UL design

3. NRC rating is .10, USG does not consider a ceiling panel to be acoustically rated if NRC is less than .50

4. LR values are shown as averages.
 5 for details, see Sustainability.

selector.
6 Field-cut edges of CLEAN Room panels must be sealed with white latex paint. 7. Clean-room-rated applications require a suspension system with gasketed fee flanges such as Dona CE.



COUNTY OF HARNETT DEPARTMENT OF BUILDING INSPECTION AND PLANNING/DEVELOPMENT CERTIFICATE OF OCCUPANCY

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: 2-3	PERMIT NUMB	<u>ERS</u>
Owner: Denuing	Building Permit No.: 28-	50019126
911 Address:	Electrical Permit No.:	-
354 Codar Rock	Insulation Permit No.:	t ;
	Plumbing Permit No.:	J. V
State: Zip Code:	Mech. Permit No.:	1.
Date: 12-30-8	MFG. Home:	
- Mil Roan	·	
Building Official	*	