

COMMENTS: _____

3/30/2009 BM met with Wayne Jones Backhoe Service on
Lot 6. It was determined that the entire drainfield was
saturated. Also that the connection of the inlet pipe to the
tank was not sealed & water was running into the septic tank.
Mr. Jones said he would call when the problem with the pipe was
corrected.