

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Gregory Inc

Address: 26 Saddle Ln
Lillington, NC 27546

Date: 1-27-17

Building Official: [Signature]

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: 08-50019235

MFG Home: _____

ADDRESS : 26 SADDLE LN
CONTRACTOR : GREGORY INC
OWNER : GREGORY, INC. #2
PARCEL : 11-0661- - -0100- -02-
APPL NUMBER: 08-50019235 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : JOHNSON FARMS SUB DIV LOT #2
HWY 210N, LEFT ON BRUCE JOHNSON RD, GO
APPROX 1/2 MILE, RIGHT ON SADDLE LN,
LOT 2 ON RIGHT.
T/S: 01/22/2008 10:43 AM VBROWN ----

SUBDIV: JOHNSON FARMS 34 LOTS
PHONE : (919) 639-7001
PHONE : (919) 422-8130

STRUCTURE: 000 000 55X55 3BDR 2BATH SFD

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW SEPTIC

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/29/16 9/29/16	DT AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002878270 T/S: 09/28/2016 08:40 AM JFORBES T/S: 09/29/2016 01:48 PM DETAYLOR
A814 01	10/03/16 10/03/16	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002879724 26 SADDLE LN LILLINGTON 27546 T/S: 10/03/2016 08:49 AM SBENNETT
B103 01	10/03/16 10/03/16	DT AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002879716 T/S: 09/30/2016 11:21 AM DJOHNSON T/S: 10/03/2016 03:24 PM DETAYLOR
B105 01	10/05/16 10/05/16	DT AP	R*OPEN FLOOR TIME: 17:00 VRU #: 002881043 T/S: 10/04/2016 01:56 PM LBENNETT T/S: 10/05/2016 03:37 PM DETAYLOR
R425 01	10/26/16 10/26/16	KS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002889749 T/S: 10/25/2016 01:06 PM LBENNETT T/S: 10/26/2016 03:06 PM KSLATTUM 1. House wrap not complete. Install over bare osb. 2. Air barrier missing beneath stairs and behind fire place. 3. Wing wall washers shall be 2x2 by 3/16 thick. OK to insulate but not side.
I129 01	10/28/16 10/28/16	DT AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002890606 T/S: 10/27/2016 08:36 AM JBROCK T/S: 10/28/2016 03:23 PM DETAYLOR
R425 02	10/28/16 10/28/16	DT AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002890614 T/S: 10/27/2016 08:36 AM JBROCK T/S: 10/28/2016 03:23 PM DETAYLOR
E209 01	12/06/16 12/06/16	MR AP	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002906899 T/S: 12/05/2016 01:37 PM JBROCK T/S: 12/06/2016 12:53 PM MREARIC prem# 87557510
H824 01	1/26/17 1/26/17	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002924819 T/S: 01/26/2017 10:18 AM KHINSON T/S: 01/26/2017 10:18 AM KHINSON
R429 01	1/27/17 1/27/17	TI AP	FOUR TRADE FINAL TIME: 17:00 VRU #: 002924801 T/S: 01/26/2017 10:14 AM LBENNETT

COMMENTS AND NOTES