
ADDRESS : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER : G S LANGDON INC
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 10/16/2009 12:04 PM VBROWN -----
CAROLINA OAKS #40, NORDICA COURT IN
CUL-DA-SAC, 210S, LEFT ON ELLIOT BRIDGE
RD, LEFT ON WILL LUCAS RD, SUB DIV WILL
BE ON RIGHT SIDE ABOUT 1/2MI DOWN.

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

STRUCTURE: 000 000 53X55 4BDR 2BATH SFD WITH PORCH SLAB

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00
SEPTIC - EXISTING? : NEW SEPTIC
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/10/09 <i>11-10</i>	TI <i>AP</i>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001848571

COMMENTS AND NOTES

ADDRESS : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER : G S LANGDON INC
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 10/16/2009 12:04 PM VBROWN ----
CAROLINA OAKS #40, NORDICA COURT IN
CUL-DA-SAC, 210S, LEFT ON ELLIOT BRIDGE
RD, LEFT ON WILL LUCAS RD, SUB DIV WILL
BE ON RIGHT SIDE ABOUT 1/2MI DOWN.

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

STRUCTURE: 000 000 53X55 4BDR 2BATH SFD WITH PORCH SLAB

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : NEW SEPTIC

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/10/09 11/10/09	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001848571 Tpoles not up at time of inspection T/S: 11/10/2009 11:58 AM KSLATTUM
B103 01	11/18/09 <u>11-18-09</u>	TI <u>DA JH</u>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001851767

COMMENTS AND NOTES

ADDRESS : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER : G S LANGDON INC
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 10/16/2009 12:04 PM VBROWN ----
CAROLINA OAKS #40, NORDICA COURT IN
CUL-DA-SAC, 210S, LEFT ON ELLIOT BRIDGE
RD, LEFT ON WILL LUCAS RD, SUB DIV WILL
BE ON RIGHT SIDE ABOUT 1/2MI DOWN.

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

STRUCTURE: 000 000 53X55 4BDR 2BATH SFD WITH PORCH SLAB

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW SEPTIC

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/10/09 11/10/09	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001848571 Tpoles not up at time of inspection T/S: 11/10/2009 11:58 AM KSLATTUM -----
B103 01	11/18/09 11/18/09	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001851767 No projection on back of garage wall, need engineer letter for repair. I know the difference between mortar mix & concrete.
B103 02	11/25/09 <u>11/25/09</u>	TI AP DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001854988

----- COMMENTS AND NOTES -----

ADDRESS : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER : G S LANGDON INC
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

DIRECTIONS : T/S: 10/16/2009 12:04 PM VBROWN ----
CAROLINA OAKS #40, NORDICA COURT IN
CUL-DA-SAC, 210S, LEFT ON ELLIOT BRIDGE
RD, LEFT ON WILL LUCAS RD, SUB DIV WILL
BE ON RIGHT SIDE ABOUT 1/2MI DOWN.

STRUCTURE: 000 000 53X55 4BDR 2BATH SFD WITH PORCH SLAB

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW SEPTIC

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/10/09	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001848571
	11/10/09	AP	Tpoles not up at time of inspection
B103 01	11/18/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001851767
	11/18/09	DA	No projection on back of garage wall, need engineer letter for repair. I know the difference between mortar mix & concrete.
B103 02	11/25/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001854988
	11/25/09	AP	T-pole passed.
A814 01	12/07/09	TI	T/S: 11/25/2009 10:31 AM DETAYLOR ----- ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001858265
P309 01	12/07/09	TI	T/S: 12/04/2009 01:19 PM VBROWN ----- R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001858349
	12/7/09	AP DT	T/S: 12/04/2009 02:01 PM NTART -----

COMMENTS AND NOTES

ADDRESS : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER : G S LANGDON INC
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

DIRECTIONS : T/S: 10/16/2009 12:04 PM VBROWN ----
CAROLINA OAKS #40, NORDICA COURT IN
CUL-DA-SAC, 210S, LEFT ON ELLIOT BRIDGE
RD, LEFT ON WILL LUCAS RD, SUB DIV WILL
BE ON RIGHT SIDE ABOUT 1/2MI DOWN.

STRUCTURE: 000 000 53X55 4BDR 2BATH SFD WITH PORCH SLAB

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/10/09 11/10/09	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001848571 Tpoles not up at time of inspection T/S: 11/10/2009 11:58 AM KSLATTUM -----
B103 01	11/18/09 11/18/09	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001851767 No projection on back of garage wall, need engineer letter for repair. I know the difference between mortar mix & concrete.
B103 02	11/25/09 11/25/09	DT AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001854988 T-pole passed. T/S: 11/25/2009 10:31 AM DETAYLOR -----
A814 01	12/07/09 12/08/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001858265 41 NORDICA CT LOT 40 ----- LINDEN 28356 ----- T/S: 12/08/2009 01:07 PM TWARD -----
P309 01	12/07/09 12/07/09	DT AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001858349 T/S: 12/04/2009 02:01 PM NTART -----
B111 01	12/14/09 <i>12-14-09</i>	TI <i>AP JH</i>	R*BLDG SLAB INSP VRU #: 001861177

COMMENTS AND NOTES

ADDRESS : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER : G S LANGDON INC
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 10/16/2009 12:04 PM VBROWN ----
CAROLINA OAKS #40, NORDICA COURT IN
CUL-DA-SAC, 210S, LEFT ON ELLIOT BRIDGE
RD, LEFT ON WILL LUCAS RD, SUB DIV WILL
BE ON RIGHT SIDE ABOUT 1/2MI DOWN.

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

STRUCTURE: 000 000 53X55 4BDR 2BATH SFD WITH PORCH SLAB

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00
SEPTIC - EXISTING? : NEW SEPTIC
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/10/09	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001848571
	11/10/09	AP	Tpoles not up at time of inspection
B103 01	11/18/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001851767
	11/18/09	DA	No projection on back of garage wall, need engineer letter for repair. I know the difference between mortar mix & concrete.
B103 02	11/25/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001854988
	11/25/09	AP	T-pole passed.
A814 01	12/07/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001858265
	12/08/09	AP	41 NORDICA CT LOT 40 LINDEN 28356
			T/S: 12/08/2009 01:07 PM TWARD
P309 01	12/07/09	DT	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001858349
	12/07/09	AP	T/S: 12/04/2009 02:01 PM NTART
B111 01	12/14/09	JH	R*BLDG SLAB INSP VRU #: 001861177
	12/15/09	AP	
R425 01	1/28/10	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001876697
	1-28-10	DA JV	T/S: 01/27/2010 08:34 AM RDCONTE

COMMENTS AND NOTES

ADDRESS : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER : G S LANGDON INC
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 10/16/2009 12:04 PM VBROWN ----
CAROLINA OAKS #40, NORDICA COURT IN
CUL-DA-SAC, 210S, LEFT ON ELLIOT BRIDGE
RD, LEFT ON WILL LUCAS RD, SUB DIV WILL
BE ON RIGHT SIDE ABOUT 1/2MI DOWN.

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

STRUCTURE: 000 000 53X55 4BDR 2BATH SFD WITH PORCH SLAB

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00
SEPTIC - EXISTING? : NEW SEPTIC
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/10/09 11/10/09	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001848571 Tpoles not up at time of inspection T/S: 11/10/2009 11:58 AM KSLATTUM -----
B103 01	11/18/09 11/18/09	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001851767 No projection on back of garage wall, need engineer letter for repair. I know the difference between mortar mix & concrete.
B103 02	11/25/09 11/25/09	DT AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001854988 T-pole passed. T/S: 11/25/2009 10:31 AM DETAYLOR -----
A814 01	12/07/09 12/08/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001858265 41 NORDICA CT LOT 40 LINDEN 28356 T/S: 12/08/2009 01:07 PM TWARD -----
P309 01	12/07/09 12/07/09	DT AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001858349 T/S: 12/04/2009 02:01 PM NTART -----
B111 01	12/14/09 12/15/09	JH AP	R*BLDG SLAB INSP VRU #: 001861177 -----
R425 01	1/28/10 1/28/10	JH DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001876697 T/S: 01/27/2010 08:34 AM RDCONTE ----- 1)Nail lvl @ garage door per drawings.2)Missing nuts & washerson anchor bolts throughout house & need anchor bolts 1foot from ends & every 6 feet.3)Nail loose osb garage rightside, right of widow in living room,@ master bed door &@ bottom plate to right of window in master bedroom.4)Add king stud @ header for porch & nail beam.5)Bond faucet to motor @ tub in master bath.6)Missing nails in roof truss hangers in master bath.7)Nail 2ply truss in master bed per drawings.8)Fire caulk door bell wire in hall @ top plate.9)Missing anchor bolts on load bearing wall in master bed.10)Brace B1GE truss per truss drawings.11)Need uplift clips per D3-2ply truss drawings.
R425 02	2/01/10 2/02/10	DT DP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001878404 T/S: 01/29/2010 11:11 AM RDCONTE ----- D3-2ply truss still not strapped for uplift in accordance with truss documents.

ADDRESS . . : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER . . . : G S LANGDON INC
PARCEL . . . : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			\$50 re-inspection fee
			T/S: 02/02/2010 09:39 AM DETAYLOR-----
R425 03	2/09/10	TI	FOUR TRADE ROUGH IN VRU #: 001880673
	2/09/10	CA	T/S: 02/09/2010 08:10 AM NTART -----
R425 04	2/11/10	TI	FOUR TRADE ROUGH IN VRU #: 001881253
	<u>2/11/10</u>	<u>APDT</u>	

----- COMMENTS AND NOTES -----

ADDRESS : 41 NORDICA CT SUBDIV: CAROLINA OAKS 64 LOTS
 CONTRACTOR : G S LANGDON INC PHONE : (910) 527-8898
 OWNER : G S LANGDON INC PHONE :
 PARCEL : 01-0544- - -0012- -40-
 APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 10/16/2009 12:04 PM VBROWN ----
 CAROLINA OAKS #40, NORDICA COURT IN
 CUL-DA-SAC, 210S, LEFT ON ELLIOT BRIDGE
 RD, LEFT ON WILL LUCAS RD, SUB DIV WILL
 BE ON RIGHT SIDE ABOUT 1/2MI DOWN.

STRUCTURE: 000 000 53X55 4BDR 2BATH SFD WITH PORCH SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/10/09	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001848571
	11/10/09	AP	Tpoles not up at time of inspection
B103 01	11/18/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001851767
	11/18/09	DA	No projection on back of garage wall, need engineer letter for repair. I know the difference between mortar mix & concrete.
B103 02	11/25/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001854988
	11/25/09	AP	T-pole passed.
A814 01	12/07/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001858265
	12/08/09	AP	41 NORDICA CT LOT 40 LINDEN 28356
P309 01	12/07/09	DT	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001858349
	12/07/09	AP	T/S: 12/04/2009 02:01 PM NTART
B111 01	12/14/09	JH	R*BLDG SLAB INSP VRU #: 001861177
	12/15/09	AP	
R425 01	1/28/10	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001876697
	1/28/10	DA	T/S: 01/27/2010 08:34 AM RDCONTE 1)Nail lvl @ garage door per drawings.2)Missing nuts & washerson anchor bolts throughout house & need anchor bolts 1foot from ends & every 6 feet.3)Nail loose osb garage rightside, right of widow in living room,@ master bed door &@ bottom plate to right of window in master bedroom.4)Add king stud @ header for porch & nail beam.5)Bond faucet to motor @ tub in master bath.6)Missing nails in roof truss hangers in master bath.7)Nail 2ply truss in master bed per drawings.8)Fire caulk door bell wire in hall @ top plate.9)Missing anchor bolts on load bearing wall in master bed.10)Brace BlGE truss per truss drawings.11)Need uplift clips per D3-2ply truss drawings.
R425 02	2/01/10	DT	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001878404
	2/02/10	DP	T/S: 01/29/2010 11:11 AM RDCONTE D3-2ply truss still not strapped for uplift in accordance with truss documents.

ADDRESS : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER : G S LANGDON INC
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			\$50 re-inspection fee
R425 03	2/09/10	TI	T/S: 02/02/2010 09:39 AM DETAYLOR----- FOUR TRADE ROUGH IN VRU #: 001880673
	2/09/10	CA	T/S: 02/09/2010 08:10 AM NTART -----
R425 04	2/11/10	DT	FOUR TRADE ROUGH IN VRU #: 001881253
	2/11/10	AP	
I129 01	2/26/10	TI	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001887777 T/S: 02/25/2010 11:20 AM VBROWN -----
	<i>2-26-10</i>	<i>AP JH</i>	<i>no permit card in box</i> COMMENTS AND NOTES

ADDRESS : 41 NORDICA CT SUBDIV: CAROLINA OAKS 64 LOTS
 CONTRACTOR : G S LANGDON INC PHONE : (910) 527-8898
 OWNER : G S LANGDON INC PHONE :
 PARCEL : 01-0544- - -0012- -40-
 APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 10/16/2009 12:04 PM VBROWN ----
 CAROLINA OAKS #40, NORDICA COURT IN
 CUL-DA-SAC, 210S, LEFT ON ELLIOT BRIDGE
 RD, LEFT ON WILL LUCAS RD, SUB DIV WILL
 BE ON RIGHT SIDE ABOUT 1/2MI DOWN.

STRUCTURE: 000 000 53X55 4BDR 2BATH SFD WITH PORCH SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/10/09 11/10/09	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001848571 Tpoles not up at time of inspection T/S: 11/10/2009 11:58 AM KSLATTUM -----
B103 01	11/18/09 11/18/09	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001851767 No projection on back of garage wall, need engineer letter for repair. I know the difference between mortar mix & concrete.
B103 02	11/25/09 11/25/09	DT AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001854988 T-pole passed. T/S: 11/25/2009 10:31 AM DETAYLOR -----
A814 01	12/07/09 12/08/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001858265 ✓ 41 NORDICA CT LOT 40 LINDEN 28356 T/S: 12/08/2009 01:07 PM TWARD -----
P309 01	12/07/09 12/07/09	DT AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001858349 T/S: 12/04/2009 02:01 PM NTART -----
B111 01	12/14/09 12/15/09	JH AP	R*BLDG SLAB INSP VRU #: 001861177 -----
R425 01	1/28/10 1/28/10	JH DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001876697 T/S: 01/27/2010 08:34 AM RDCONTE ----- 1)Nail lvl @ garage door per drawings.2)Missing nuts & washerson anchor bolts throughout house & need anchor bolts 1foot from ends & every 6 feet.3)Nail loose osb garage rightside, right of widow in living room,@ master bed door &@ bottom plate to right of window in master bedroom.4)Add king stud @ header for porch & nail beam.5)Bond faucet to motor @ tub in master bath.6)Missing nails in roof truss hangers in master bath.7)Nail 2ply truss in master bed per drawings.8)Fire caulk door bell wire in hall @ top plate.9)Missing anchor bolts on load bearing wall in master bed.10)Brace B1GE truss per truss drawings.11)Need uplift clips per D3-2ply truss drawings.
R425 02	2/01/10 2/02/10	DT DP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001878404 T/S: 01/29/2010 11:11 AM RDCONTE ----- D3-2ply truss still not strapped for uplift in accordance with truss documents.

ADDRESS : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER : G S LANGDON INC
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			\$50 re-inspection fee
R425 03	2/09/10	TI	T/S: 02/02/2010 09:39 AM DETAYLOR----- FOUR TRADE ROUGH IN VRU #: 001880673
	2/09/10	CA	T/S: 02/09/2010 08:10 AM NTART -----
R425 04	2/11/10	DT	FOUR TRADE ROUGH IN VRU #: 001881253
	2/11/10	AP	
I129 01	2/26/10	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001887777
	2/26/10	AP	T/S: 02/25/2010 11:20 AM VBROWN ----- no permit card in box3 PM JHALL ----- T/S: 03/02/2010 04:12 PM NTART -----
H824 01	3/17/10	OT	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001897552
	3/17/10	AP	T/S: 03/19/2010 10:22 AM SSTEWARD ----- T/S: 03/19/2010 10:22 AM SSTEWARD -----
R431 01	4/23/10	TI	FOUR TRADE FINAL >2500 VRU #: 001914218
	4/23/10	CA	T/S: 04/23/2010 10:01 AM NTART -----
R429 01	4/30/10	TI	FOUR TRADE FINAL VRU #: 001918090

4.30.10 DPBS

----- COMMENTS AND NOTES -----

ADDRESS : 41 NORDICA CT SUBDIV: CAROLINA OAKS 64 LOTS
 CONTRACTOR : G S LANGDON INC PHONE : (910) 527-8898
 OWNER : G S LANGDON INC PHONE :
 PARCEL : 01-0544- - -0012- -40-
 APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 10/16/2009 12:04 PM VBROWN ----
 CAROLINA OAKS #40, NORDICA COURT IN
 CUL-DA-SAC, 210S, LEFT ON ELLIOT BRIDGE
 RD, LEFT ON WILL LUCAS RD, SUB DIV WILL
 BE ON RIGHT SIDE ABOUT 1/2MI DOWN.

STRUCTURE: 000 000 53X55 4BDR 2BATH SFD WITH PORCH SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/10/09	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001848571
	11/10/09	AP	Tpoles not up at time of inspection T/S: 11/10/2009 11:58 AM KSLATTUM -----
B103 01	11/18/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001851767
	11/18/09	DA	No projection on back of garage wall, need engineer letter for repair. I know the difference between mortar mix & concrete.
B103 02	11/25/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001854988
	11/25/09	AP	T-pole passed. T/S: 11/25/2009 10:31 AM DETAYLOR -----
A814 01	12/07/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001858265
	12/08/09	AP	✓ 41 NORDICA CT LOT 40 LINDEN 28356 ----- T/S: 12/08/2009 01:07 PM TWARD -----
P309 01	12/07/09	DT	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001858349
	12/07/09	AP	T/S: 12/04/2009 02:01 PM NTART -----
B111 01	12/14/09	JH	R*BLDG SLAB INSP VRU #: 001861177
	12/15/09	AP	-----
R425 01	1/28/10	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001876697
	1/28/10	DA	T/S: 01/27/2010 08:34 AM RDCONTE ----- 1)Nail lvl @ garage door per drawings.2)Missing nuts & washerson anchor bolts throughout house & need anchor bolts 1foot from ends & every 6 feet.3)Nail loose osb garage rightside, right of widow in living room,@ master bed door &@ bottom plate to right of window in master bedroom.4)Add king stud @ header for porch & nail beam.5)Bond faucet to motor @ tub in master bath.6)Missing nails in roof truss hangers in master bath.7)Nail 2ply truss in master bed per drawings.8)Fire caulk door bell wire in hall @ top plate.9)Missing anchor bolts on load bearing wall in master bed.10)Brace BlGE truss per truss drawings.11)Need uplift clips per D3-2ply truss drawings.
R425 02	2/01/10	DT	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001878404
	2/02/10	DP	T/S: 01/29/2010 11:11 AM RDCONTE ----- D3-2ply truss still not strapped for uplift in accordance with truss documents.

ADDRESS : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER : G S LANGDON INC
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			\$50 re-inspection fee
R425 03	2/09/10	TI	T/S: 02/02/2010 09:39 AM DETAYLOR----- FOUR TRADE ROUGH IN VRU #: 001880673
	2/09/10	CA	T/S: 02/09/2010 08:10 AM NTART -----
R425 04	2/11/10	DT	FOUR TRADE ROUGH IN VRU #: 001881253
	2/11/10	AP	
I129 01	2/26/10	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001887777
	2/26/10	AP	T/S: 02/25/2010 11:20 AM VBROWN ----- no permit card in box3 PM JHALL ----- T/S: 03/02/2010 04:12 PM NTART -----
H824 01	3/17/10	OT	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001897552
	3/17/10	AP	T/S: 03/19/2010 10:22 AM SSTEWARD ----- T/S: 03/19/2010 10:22 AM SSTEWARD -----
R431 01	4/23/10	TI	FOUR TRADE FINAL >2500 VRU #: 001914218
	4/23/10	CA	T/S: 04/23/2010 10:01 AM NTART -----
R429 01	4/30/10	BS	FOUR TRADE FINAL VRU #: 001918090
	4/30/10	DP	House incomplete. Compressor unit not set/wired. Rear porch roof not supported on final posts.no cleanout outside of foundation Inspection stopped. \$50 re fee
			T/S: 05/21/2010 08:31 AM NTART -----
R429 02	5/24/10	TI	FOUR TRADE FINAL VRU #: 001930890

5-24-10 DP JH

----- COMMENTS AND NOTES -----

ADDRESS : 41 NORDICA CT SUBDIV: CAROLINA OAKS 64 LOTS
CONTRACTOR : G S LANGDON INC PHONE : (910) 527-8898
OWNER : G S LANGDON INC PHONE :
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 10/16/2009 12:04 PM VBROWN ----
CAROLINA OAKS #40, NORDICA COURT IN
CUL-DA-SAC, 210S, LEFT ON ELLIOT BRIDGE
RD, LEFT ON WILL LUCAS RD, SUB DIV WILL
BE ON RIGHT SIDE ABOUT 1/2MI DOWN.

STRUCTURE: 000 000 53X55 4BDR 2BATH SFD WITH PORCH SLAB

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/10/09	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001848571
	11/10/09	AP	Tpoles not up at time of inspection T/S: 11/10/2009 11:58 AM KSLATTUM -----
B103 01	11/18/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001851767
	11/18/09	DA	No projection on back of garage wall, need engineer letter for repair. I know the difference between mortar mix & concrete.
B103 02	11/25/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001854988
	11/25/09	AP	T-pole passed. T/S: 11/25/2009 10:31 AM DETAYLOR -----
A814 01	12/07/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001858265
	12/08/09	AP	41 NORDICA CT LOT 40 ----- LINDEN 28356 ----- T/S: 12/08/2009 01:07 PM TWARD -----
P309 01	12/07/09	DT	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001858349
	12/07/09	AP	T/S: 12/04/2009 02:01 PM NTART -----
B111 01	12/14/09	JH	R*BLDG SLAB INSP VRU #: 001861177
	12/15/09	AP	-----
R425 01	1/28/10	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001876697
	1/28/10	DA	T/S: 01/27/2010 08:34 AM RDCONTE ----- 1)Nail lvl @ garage door per drawings.2)Missing nuts & washerson anchor bolts throughout house & need anchor bolts 1foot from ends & every 6 feet.3)Nail loose osb garage rightside, right of widow in living room,@ master bed door &@ bottom plate to right of window in master bedroom.4)Add king stud @ header for porch & nail beam.5)Bond faucet to motor @ tub in master bath.6)Missing nails in roof truss hangers in master bath.7)Nail 2ply truss in master bed per drawings.8)Fire caulk door bell wire in hall @ top plate.9)Missing anchor bolts on load bearing wall in master bed.10)Brace B1GE truss per truss drawings.11)Need uplift clips per D3-2ply truss drawings.
R425 02	2/01/10	DT	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001878404
	2/02/10	DP	T/S: 01/29/2010 11:11 AM RDCONTE ----- D3-2ply truss still not strapped for uplift in accordance

ADDRESS : 41 NORDICA CT
CONTRACTOR : G S LANGDON INC
OWNER : G S LANGDON INC
PARCEL : 01-0544- - -0012- -40-
APPL NUMBER: 09-50023062 CP NEW RESIDENTIAL (SFD)

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (910) 527-8898
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			with truss documents. \$50 re-inspection fee
R425 03	2/09/10	TI	T/S: 02/02/2010 09:39 AM DETAYLOR----- FOUR TRADE ROUGH IN VRU #: 001880673
	2/09/10	CA	T/S: 02/09/2010 08:10 AM NTART -----
R425 04	2/11/10	DT	FOUR TRADE ROUGH IN VRU #: 001881253
	2/11/10	AP	
I129 01	2/26/10	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001887777
	2/26/10	AP	T/S: 02/25/2010 11:20 AM VBROWN ----- no permit card in box3 PM JHALL ----- T/S: 03/02/2010 04:12 PM NTART -----
H824 01	3/17/10	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001897552
	3/17/10	AP	T/S: 03/19/2010 10:22 AM SSTEWARD ----- T/S: 03/19/2010 10:22 AM SSTEWARD -----
R431 01	4/23/10	TI	FOUR TRADE FINAL >2500 VRU #: 001914218
	4/23/10	CA	T/S: 04/23/2010 10:01 AM NTART -----
R429 01	4/30/10	BS	FOUR TRADE FINAL VRU #: 001918090
	4/30/10	DP	House incomplete. Compressor unit not set/wired. Rear porch roof not supported on final posts.no cleanout outside of foundation Inspection stopped. \$50 re fee
			T/S: 05/21/2010 08:31 AM NTART -----
R429 02	5/24/10	JH	FOUR TRADE FINAL VRU #: 001930890
	5/24/10	DP	1)Seal holes in sheetrock @ water heater & range receptacle. 2)Need cover for attic access. 3)Condensing unit not wired. 4)Fill in all holes around house so you will have your 6" in 10'.
R429 03	5/25/10	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 001932128
	<i>5-25-10</i>	<i>APJV</i>	T/S: 05/25/2010 09:15 AM NTART -----

----- COMMENTS AND NOTES -----

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: ___ Occupancy:

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: CoS Langdon INC

Address: 41 Nordica Ct

Date: 5-25-10

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

Building Official: Jammy T Hall

09-500362
0905005-60