

COMMENTS: Bm 9/22/2010 Received a call from Johnathan
Turlington at 595 McHam Blvd. about an odor "rotten eggs" in his water.
I spoke with him about taking samples & that I would speak with
the well regional specialist. 9/30/2010 went with the regional specialist
David Eddy to the Turlingtons property. We looked at the well head
also dug beside the casing to check the grout. After digging a hole
it seemed that the well was not properly grouted. I was not able to be
present for the well grout. Explained ^{Mrs. Turlington} to the ~~lady~~ of the house what
we were doing & that we would need to come back the following week
ground was saturated. Mrs. Turlington was given a pamphlet on
disinfecting wells. 10/1/2010 spoke with Mr. Turlington about disinfecting
the well & the possible problem & solutions. Also told him to use 1.2 oz. of
~~HTH~~ HTH disinfectant. Also explained to Mrs. Turlington that
the entry point for the power was not sealed & that they could
seal it or call the well co. that dug the well.

COMMENTS:

I took samples of the water even though the completion permit had not been issued because the Turlingtons were using the well.

The house obtained a Completion of Occupancy (CO) without the well completion permit.

10/22/10 - Brought to Attn of Donna Johnson by phone that CO issued prior to completion issued for well.