
ADDRESS . . : 1523 BILL AVERY RD
 CONTRACTOR :
 OWNER . . : HOLMES VIRGINIA M
 PARCEL . . : 07-0691- - -0033- - -
 APPL NUMBER: 09-50023174 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/03/2009 09:37 AM DJOHNSON --
 NORTH ON MAIN ST RIGHT ONTO US 421
 TOWARDS DUNN GO 3.4 MILES LEFT ON
 LESLIE CAMPBELL AVENUE ON 27 GO 2.9
 MILES LEFT ON BILL AVERY RD GO 1.5
 MILES DESTINATION ON LEFT.

STRUCTURE: 000 000 73X45 3BR CRAWL AND GARAGE BACK PORCH

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/29/10 3/29/10	BS CA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001901099 No temporary service pole...using existing service on site T/S: March 29, 2010 11:36 AM BSUTTON -----
B101 02	4/01/10 <u>4-1</u>	TI <u>AP</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001903111 No temporary service pole...using existing service on site

COMMENTS AND NOTES -----

ADDRESS . . : 1523 BILL AVERY RD
CONTRACTOR :
OWNER . . . : HOLMES VIRGINIA M
PARCEL . . . : 07-0691- - -0033- - -
APPL NUMBER: 09-50023174 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 11/03/2009 09:37 AM DJOHNSON --
NORTH ON MAIN ST RIGHT ONTO US 421
TOWARDS DUNN GO 3.4 MILES LEFT ON
LESLIE CAMPBELL AVENUE ON 27 GO 2.9
MILES LEFT ON BILL AVERY RD GO 1.5
MILES DESTINATION ON LEFT.

SUBDIV:
PHONE :
PHONE : (910) 897-5210

STRUCTURE: 000 000 73X45 3BR CRAWL AND GARAGE BACK PORCH

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/29/10 3/29/10	BS CA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001901099 No temporary service pole...using existing service on site T/S: March 29, 2010 11:36 AM BSUTTON -----
B101 02	4/01/10 4/01/10	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001903111 No temporary service pole...using existing service on site
B103 01	4/16/10 <u>4-16</u>	TI <u>AP</u>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001910587

----- COMMENTS AND NOTES -----

ADDRESS . : 1523 BILL AVERY RD SUBDIV:
CONTRACTOR : PHONE :
OWNER . . : HOLMES VIRGINIA M PHONE : (910) 897-5210
PARCEL . . : 07-0691- - -0033- - -
APPL NUMBER: 09-50023174 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 11/03/2009 09:37 AM DJOHNSON --
NORTH ON MAIN ST RIGHT ONTO US 421
TOWARDS DUNN GO 3.4 MILES LEFT ON
LESLIE CAMPBELL AVENUE ON 27 GO 2.9
MILES LEFT ON BILL AVERY RD GO 1.5
MILES DESTINATION ON LEFT.

STRUCTURE: 000 000 73X45 3BR CRAWL AND GARAGE BACK PORCH
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/29/10 3/29/10	BS CA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001901099 No temporary service pole...using existing service on site T/S: March 29, 2010 11:36 AM BSUTTON -----
B101 02	4/01/10 4/01/10	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001903111 No temporary service pole...using existing service on site
B103 01	4/16/10 4/16/10	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001910587
B105 01	4/21/10 <u>4-21-10</u>	TI <u>APBS</u>	R*OPEN FLOOR VRU #: 001913243

----- COMMENTS AND NOTES -----

ADDRESS : 1547 BILL AVERY RD
CONTRACTOR :
OWNER : HOLMES VIRGINIA M
PARCEL : 07-0691- - -0033- - -
APPL NUMBER: 09-50023174 CP NEW RESIDENTIAL (SFD)

SUBDIV:
PHONE :
PHONE : (910) 897-5210

DIRECTIONS : T/S: 11/03/2009 09:37 AM DJOHNSON --
NORTH ON MAIN ST RIGHT ONTO US 421
TOWARDS DUNN GO 3.4 MILES LEFT ON
LESLIE CAMPBELL AVENUE ON 27 GO 2.9
MILES LEFT ON BILL AVERY RD GO 1.5
MILES DESTINATION ON LEFT.

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/29/10 3/29/10	BS CA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001901099 No temporary service pole...using existing service on site T/S: March 29, 2010 11:36 AM BSUTTON -----
B101 02	4/01/10 4/01/10	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001903111 No temporary service pole...using existing service on site
B103 01	4/16/10 4/16/10	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001910587
B105 01	4/21/10 4/21/10	BS AP	R*OPEN FLOOR VRU #: 001913243 T/S: April 21, 2010 11:25 AM BSUTTON -----
A814 01	5/24/10 5/24/10	FB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001931138 T/S: 05/21/2010 11:33 AM JBROCK ----- T/S: 05/24/2010 04:47 PM FBURGESS ----- 1547 BILL AVERY RD COATS, NC 27521
R427 01	<u>7/14/10</u>	BS <u>DABS</u>	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001953686 T/S: 07/14/2010 08:09 AM NTART -----

----- COMMENTS AND NOTES -----

ADDRESS : 1547 BILL AVERY RD
 CONTRACTOR :
 OWNER : HOLMES VIRGINIA M
 PARCEL : 07-0691- - -0033- - -
 APPL NUMBER: 09-50023174 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/03/2009 09:37 AM DJOHNSON --
 NORTH ON MAIN ST RIGHT ONTO US 421
 TOWARDS DUNN GO 3.4 MILES LEFT ON
 LESLIE CAMPBELL AVENUE ON 27 GO 2.9
 MILES LEFT ON BILL AVERY RD GO 1.5
 MILES DESTINATION ON LEFT.

STRUCTURE: 000 000 73X45 3BR CRAWL AND GARAGE BACK PORCH
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/29/10 3/29/10	BS CA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001901099 No temporary service pole...using existing service on site T/S: March 29, 2010 11:36 AM BSUTTON
B101 02	4/01/10 4/01/10	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001903111 No temporary service pole...using existing service on site
B103 01	4/16/10 4/16/10	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001910587
B105 01	4/21/10 4/21/10	BS AP	R*OPEN FLOOR VRU #: 001913243 T/S: April 21, 2010 11:25 AM BSUTTON
A814 01	5/24/10 5/24/10	FB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001931138 T/S: 05/21/2010 11:33 AM JBROCK T/S: 05/24/2010 04:47 PM FBURGESS 1547 BILL AVERY RD COATS, NC 27521
R427 01	7/14/10 7/14/10	BS DA	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001953686 T/S: 07/14/2010 08:09 AM NTART 1. Need housewrap installed(fanfold is to be used according to homeowner. will be installed w/ siding) 2. Nail garage LVL from both sides 3.Ridge/Valley over garage needs to be supported back to a load wall. 4. Sheath inside garage wall at door openings with OSB. Ok to insulate, DO NOT SIDE
I129 01	7/30/10 <u>7/30/10</u>	TI <u>ADBS</u>	R*INSULATION INSPECTION VRU #: 001961358 Also scheduling inspection for corrections made after original rough-in inspection.
R427 02	7/30/10 <u>7/30/10</u>	TI <u>↓</u>	FOUR TRADE ROUGH IN >2500 VRU #: 001961341 Also scheduling insulation inspection at same visit.

COMMENTS AND NOTES

ADDRESS : 1547 BILL AVERY RD
 CONTRACTOR :
 OWNER : HOLMES VIRGINIA M
 PARCEL : 07-0691- - -0033- - -
 APPL NUMBER: 09-50023174 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/03/2009 09:37 AM DJOHNSON --
 NORTH ON MAIN ST RIGHT ONTO US 421
 TOWARDS DUNN GO 3.4 MILES LEFT ON
 LESLIE CAMPBELL AVENUE ON 27 GO 2.9
 MILES LEFT ON BILL AVERY RD GO 1.5
 MILES DESTINATION ON LEFT.

STRUCTURE: 000 000 73X45 3BR CRAWL AND GARAGE BACK PORCH
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/29/10 3/29/10	BS CA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001901099 No temporary service pole...using existing service on site T/S: March 29, 2010 11:36 AM BSUTTON -----
B101 02	4/01/10 4/01/10	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001903111 No temporary service pole...using existing service on site
B103 01	4/16/10 4/16/10	KS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001910587
B105 01	4/21/10 4/21/10	BS AP	R*OPEN FLOOR VRU #: 001913243 T/S: April 21, 2010 11:25 AM BSUTTON -----
A814 01	5/24/10 5/24/10	FB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001931138 T/S: 05/21/2010 11:33 AM JBROCK ----- T/S: 05/24/2010 04:47 PM FBURGESS -----
R427 01	7/14/10 7/14/10	BS DA	✓ 1547 BILL AVERY RD COATS, NC 27521 FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001953686 T/S: 07/14/2010 08:09 AM NTART ----- 1. Need housewrap installed(fanfold is to be used according to homeowner. will be installed w/ siding) 2. Nail garage LVL from both sides 3.Ridge/Valley over garage needs to be supported back to a load wall. 4. Sheath inside garage wall at door openings with OSB. Ok to insulate, DO NOT SIDE
I129 01	7/30/10 7/30/10	BS AP	R*INSULATION INSPECTION VRU #: 001961358 Also scheduling inspection for corrections made after original rough-in inspection. T/S: July 30, 2010 11:17 AM BSUTTON -----
R427 02	7/30/10 7/30/10	BS AP	FOUR TRADE ROUGH IN >2500 VRU #: 001961341 Also scheduling insulation inspection at same visit. T/S: July 30, 2010 11:17 AM BSUTTON -----
H824 01	10/15/10 10/15/10	JM AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001996602 T/S: 10/20/2010 10:06 AM SZIMMER ----- T/S: 10/20/2010 10:07 AM SZIMMER -----
R431 01	12/16/10	TI	FOUR TRADE FINAL >2500 VRU #: 002019297 Could be a duplicate scheduling. I thought I had this scheduled for 12/14/10.

COMMENTS AND NOTES

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: ___ Occupancy: X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Permit Numbers

Name: Virginia M Holmes

Building: 09-50023174

Electrical: 09-50023174

Address: 1547 Bill Avery Road

Insulation: 09-50023174

Coats NC 27521

Plumbing: 09-50023174

Mechanical: 09-50023174

MFG Home: NANANANANA

Date: 12-16-2010

Building Official: BSutton