PREPARED 10/08/10, 9:41:15 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 10/08/10 ADDRESS . : 126 SAW GRASS CT SUBDIV: WALNUT GROVE 37LOTS CONTRACTOR : PALMETTO BUILDING INC. PHONE : (919) 795-0211 OWNER . . : EVEN PAR DEVELOPMENT LLC PHONE : PARCEL . .: 01-0525- - -0062- -32-APPL NUMBER: 10-50023757 CP NEW RESIDENTIAL (SFD) ______ DIRECTIONS : T/S: 02/10/2010 10:47 AM RDCONTE ---126 SAW GRASS / WALNUT GROVE #23 TAKE 210S. GO APROX 9MI, T/L ON LASATER RD. GO APROX 1/4MI, T/L INTO WALNUT GROVE ON SAW GRASS. LOT IS ON THE RIGHT ***SOUTH RIVER*** STRUCTURE: 000 000 42X63 CRAWL 4BD/3BA W/GAR, FIN BN RM FLOOD ZONE . . . : FLOOD ZONE X # BEDROOMS : 4.00 PROPOSED USE : SFD WATER SUPPLY : COUNTY REQUESTED INSP DESCRIPTION

---- COMMENTS AND NOTES ------

PREPARED 10/13/10, 14:05:57 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 10/14/10 ______ ADDRESS . : 126 SAW GRASS CT SUBDIV: WALNUT GROVE 37LOTS CONTRACTOR : PALMETTO BUILDING INC. PHONE: (919) 795-0211 OWNER . . : EVEN PAR DEVELOPMENT LLC PHONE : PARCEL . .: 01-0525- - -0062- -32-APPL NUMBER: 10-50023757 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 02/10/2010 10:47 AM RDCONTE ---126 SAW GRASS / WALNUT GROVE #23 TAKE 210S. GO APROX 9MI, T/L ON LASATER RD. GO APROX 1/4MI, T/L INTO WALNUT GROVE ON SAW GRASS. LOT IS ON THE RIGHT ***SOUTH RIVER*** STRUCTURE: 000 000 42X63 CRAWL 4BD/3BA W/GAR, FIN BN RM FLOOD ZONE . . . : FLOOD ZONE X # BEDROOMS : 4.00 PROPOSED USE SFD SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY : COUNTY PERMIT: CPSF 00 CP * SFD REOUESTED INSP

----- COMMENTS AND NOTES -----

TNO PECTION LICKEL PAGE Harnett County INSPECTOR: IVR DATE 10/19/10 -----. : 126 SAW GRASS CT ADDRESS SUBDIV: WALNUT GROVE 37LOTS CONTRACTOR : PALMETTO BUILDING INC. PHONE: (919) 795-0211 OWNER . . : EVEN PAR DEVELOPMENT LLC PHONE : PARCEL . .: 01-0525- - -0062- -32-APPL NUMBER: 10-50023757 CP NEW RESIDENTIAL (SFD) DIRECTIONS : T/S: 02/10/2010 10:47 AM RDCONTE ---126 SAW GRASS / WALNUT GROVE #23 TAKE 210S. GO APROX 9MI, T/L ON LASATER RD. GO APROX 1/4MI, T/L INTO WALNUT GROVE ON SAW GRASS. LOT IS ON THE RIGHT ***SOUTH RIVER*** ______ STRUCTURE: 000 000 42X63 CRAWL 4BD/3BA W/GAR, FIN BN RM FLOOD ZONE . . . : FLOOD ZONE X # BEDROOMS 4.00 PROPOSED USE : SFD SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY : COUNTY ______ PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS ______ B101 01 10/08/10 KS R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001991926 10/08/10 AP 10/14/10 FB 10/15/10 AP T/S: 10/08/2010 09:41 AM NTART -----A814 01 ADDRESS CONFIRMATION VRU #: 001993906

T/S: 10/15/2010 04:17 PM FBURGESS -----

T/S: 10/18/2010 11:24 AM RDCONTE -----

126 SAW GRASS CT BUNNLEVEL, NC 28323 LOT 23

R*OPEN FLOOR TIME: 17:00 VRU #: 001995737

------ COMMENTS AND NOTES -----

R*BLDG FOUND & TEMP SVC POLE VRU #: 001993914

B103 01

B105 01

10/14/10 JH 10/14/10 AP

ΤI

10/19/10

10/19/10



1 919 773-1200 = # 919 773-9658 69 Shipwash Drive • Garner • North Carolina • 27529 www.tyndallengineering.com

October 18, 2010

Stancil Builders, Inc. 466 Stancil Rd. Angier, NC 27501

Reference:

Bedroom 3 Cantilever Floor Framing

Plan:

1795 Stock Plan

Project No.

10GAR-R0444

To Whom It May Concern:

A representative of Tyndall Engineering & Design, PA analyzed items for the above referenced project. Specifically, the following items listed were analyzed:

1) Required framing for cantilevered floor system at Bedroom 3.

The following conclusions and recommendations were presented for the abovementioned items:


1) Based on our plan review and analysis, the proposed framing for the 2'-0" cantilever shall be constructed in general accordance with the attached diagrams.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information please do not hesitate to contact us.

Sincerely,

Tyndall Engineering & Design, PA


Alan W. Lewis, P 10GAR-R0444





t 919 773-1200 + # 919 773-9658 69 Shipwash Drive + Garner + North Carolina + 27529 www.tyndallenginoering.com

JOB 10 GAR-ROYYY	
LOCATION PARTIAL FIRST	FLOOR
CALCULATED BY ALL	DATE 10-18-10
SHEET NO.	OF
SCALE NTS	





¥919773-1200 + ₹919773-9658 89 Shipwash Drive + Garner + North Carolina + 27529 www.tyndallengineering.com

JOB_ 10GAR-ROY	44
LOCATION PARTIAL	SECOND FLOUR
CALCULATED BY Am.	DATE 10 18:10
SHEET NO.	OF
SCALE NIS	

PREPARED 11/04/10, 14:01:18 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 11/05/10

ADDRESS . : 126 SAW GRASS CT SUBDIV: WALNUT GROVE 37LOTS

CONTRACTOR : PALMETTO BUILDING INC. PHONE: (919) 795-0211

OWNER . . : EVEN PAR DEVELOPMENT LLC PHONE :

PARCEL . . : 01-0525- - -0062- -32-

APPL NUMBER: 10-50023757 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: T/S: 02/10/2010 10:47 AM RDCONTE ---

126 SAW GRASS / WALNUT GROVE #23

TAKE 210S. GO APROX 9MI, T/L ON LASATER RD. GO APROX 1/4MI, T/L INTO WALNUT GROVE ON SAW GRASS. LOT IS ON THE RIGHT

SOUTH RIVER

STRUCTURE: 000 000 42X63 CRAWL 4BD/3BA W/GAR, FIN BN RM

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS 4.00 PROPOSED USE : SFD WATER SUPPLY : COUNTY SEPTIC - EXISTING? . . . : NEW TANK

PERMIT:	CPSF	00	CP	±	SFD	

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/08/10	KS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001991926
	10/08/10	AP	T/S: 10/08/2010 09:41 AM NTART
A814 01	10/14/10	FB	ADDRESS CONFIRMATION VRU #: 001993906
	10/15/10	AP	T/S: 10/15/2010 04:17 PM FBURGESS
			126 SAW GRASS CT BUNNLEVEL, NC 28323 LOT 23
B103 01	10/14/10	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001993914
	10/14/10	AP	
B105 01	10/19/10	DT	R*OPEN FLOOR TIME: 17:00 VRU #: 001995737
	10/19/10	AP	T/S: 10/18/2010 11:24 AM RDCONTE
R425 01	11/04/10	JH	FOUR TRADE ROUGH IN VRU #: 002002251
	11/04/10	DA	1)Missing nuts & washers on anchor bolts in garage.
			2)Replace all notched stdus in garage, notch iis at bottom
			plate. 3) Need repair on 2 x 10 beam over master bedroom
			door where holes have been drilled through. 4) Fire caulk
			refridgerant lines @ top plate & floor in kitchen. 5)Add 2
			studs under lvls in kitchen @ bar. 6)Missing double joist
			inkitchen to left of window on end wall. 7) Missing studs in
			garage to left of lvls on right side. 8) Frame wall @ front
			door per 2 story plans note on plans. 9) Need letter for
			catalever on back if its not in file.
R425 02	11/05/10	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002003010
	11-5-10	DAGS	T/S: 11/04/2010 12:01 PM RDCONTE



1 919 773-1200 • 9 919 773-9658 69 Shipwash Drive • Garner • North Carolina • 27529 www.tyndallengineering.com

November 4, 2010

Palmetto Design Build
122 W. Savannah Ridge Road
Holly Springs, NC 27540

Email: hankmccullough@aol.com

Reference: Engineering Services

Lot 23, Walnut Grove Harnett County, NC

Project No.: 10GAR-R0444a

To Whom It May Concern:

A representative of Tyndall Engineering & Design (TE&D) analyze the following items:

1) Electrical penetration in the (2) 2x10 flush beam at the master bedroom closet.

The following conclusions and recommendation were noted:

1) Based on our analysis and review of the builder provided data, the existing (2) 2x10 header is adequate as constructed to support the anticipated loading conditions.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information please do not hesitate to contact us.

Sincerely,

Tyndall Engineering & Design, PA

Sean M. Holmes

SMH/10GAR-R0444a

PREPARED 11/03/10, 14:05:40 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 11/04/10 -----ADDRESS . : 126 SAW GRASS CT SUBDIV: WALNUT GROVE 37LOTS CONTRACTOR : PALMETTO BUILDING INC. PHONE: (919) 795-0211 OWNER . . : EVEN PAR DEVELOPMENT LLC PHONE : PARCEL . . : 01-0525- - -0062- -32-APPL NUMBER: 10-50023757 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 02/10/2010 10:47 AM RDCONTE ---126 SAW GRASS / WALNUT GROVE #23 TAKE 210S. GO APROX 9MI, T/L ON LASATER RD. GO APROX 1/4MI, T/L INTO WALNUT GROVE ON SAW GRASS. LOT IS ON THE RIGHT ***SOUTH RIVER*** STRUCTURE: 000 000 42X63 CRAWL 4BD/3BA W/GAR, FIN BN RM FLOOD ZONE . . . : FLOOD ZONE X # BEDROOMS : 4.00 PROPOSED USE SFD SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY : COUNTY PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION COMPLETED RESULT RESULTS/COMMENTS R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001991926

TYP/SQ B101 01 10/08/10 KS 10/08/10 AP T/S: 10/08/2010 09:41 AM NTART -----10/14/10 FB 10/15/10 AP A814 01 ADDRESS CONFIRMATION VRU #: 001993906 T/S: 10/15/2010 04:17 PM FBURGESS ------126 SAW GRASS CT BUNNLEVEL, NC 28323 LOT 23 B103 01 10/14/10 ЈН R*BLDG FOUND & TEMP SVC POLE VRU #: 001993914 10/14/10 AP 10/19/10 DT B105 01 R*OPEN FLOOR TIME: 17:00 VRU #: 001995737 10/19/10 AP T/S: 10/18/2010 11:24 AM RDCONTE -----11/04/10 TI R425 01 FOUR TRADE ROUGH IN VRU #: 002002251 11-4-10 OA TH

PREPARED 11/08/10, 14:16:40 Harnett County INSPECTION TICKET INSPECTOR: IVR

PAGE 1 DATE 11/09/10

ADDRESS . : 126 SAW GRASS CT SUBDIV: WALNUT GROVE 37LOTS CONTRACTOR : PALMETTO BUILDING INC. PHONE : (919) 795-0211

CONTRACTOR : PALMETTO BUILDING INC. PHONE : OWNER . . : EVEN PAR DEVELOPMENT LLC PHONE :

PARCEL . . : 01-0525- - -0062- -32-

APPL NUMBER: 10-50023757 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 02/10/2010 10:47 AM RDCONTE ---

126 SAW GRASS / WALNUT GROVE #23

TAKE 210S. GO APROX 9MI, T/L ON LASATER RD. GO APROX $1/4\mathrm{MI}$, T/L INTO WALNUT GROVE ON SAW GRASS. LOT IS ON THE RIGHT

SOUTH RIVER

STRUCTURE: 000 000 42X63 CRAWL 4BD/3BA W/GAR, FIN BN RM

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 4.00 PROPOSED USE : SFD SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY : COUNTY

PERMIT:	CPSF 00 CP *	SFD INSP	DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B101 01	10/08/10 10/08/10	KS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001991926 T/S: 10/08/2010 09:41 AM NTART
A814 01	10/14/10	FB	ADDRESS CONFIRMATION VRU #: 001993906
	10/15/10	AP	T/S: 10/15/2010 04:17 PM FBURGESS
B103 01	10/14/10	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001993914
	10/14/10	AP	
B105 01	10/19/10	DT	R*OPEN FLOOR TIME: 17:00 VRU #: 001995737
	10/19/10	AP	T/S: 10/18/2010 11:24 AM RDCONTE
R425 01	11/04/10	JH	FOUR TRADE ROUGH IN VRU #: 002002251
	11/04/10	DA	1) Missing nuts & washers on anchor bolts in garage. 2) Replace all notched stdus in garage, notch iis at bottom plate. 3) Need repair on 2 x 10 beam over master bedroom door where holes have been drilled through. 4) Fire caulk refridgerant lines @ top plate & floor in kitchen. 5) Add 2 studs under lvls in kitchen @ bar. 6) Missing double joist inkitchen to left of window on end wall. 7) Missing studs in garage to left of lvls on right side. 8) Frame wall @ front door per 2 story plans note on plans. 9) Need letter for catalever on back if its not in file.
R425 02	11/05/10 11/05/10	DA DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002003010 T/S: 11/04/2010 12:01 PM RDCONTE
I129 01	11/09/10 49/ (0)	A M	R*INSULATION INSPECTION VRU #: 002003911 Thanks for helping me thru the two story foyer framing. I emailed Dean a copy of the engineering letter on how it was to be constructed, but I'm also leaving a copy in the permit box. Thanks againHank
R425 03	11/09/10	₩ <i>)</i> 1	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002004679 T/S: 11/08/2010 02:16 PM NTART

----- COMMENTS AND NOTES -----



t 919 773-1200 • # 919 773-9658 69 Shipwash Drive • Garner • North Carolina • 27529 www.tyndallengineering.com

November 5, 2010

Palmetto Design Build 122 W. Savannah Ridge Road Holly Springs, NC 27540 Email: hankmccullough@aol.com

Reference: Engineering Services

Lot 23, Walnut Grove Harnett County, NC

Project No.: 10GAR-R0444B

To Whom It May Concern:

A representative of Tyndall Engineering & Design (TE&D) was on-site this day to visually observe and analyze the following item:

1) Determine structural adequacy of the existing 2x4 hinged wall framing in-lieu of a two story wall framing as depicted on the approved plan.

The following conclusions and recommendation were noted:

 Based on our visual observation and analysis, TE&D recommends the following framing enhancements shall be constructed in general accordance with the attached diagram.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information please do not hesitate to contact us.

Sincerely,


Tyndall Engineering & Design, PA

Clarence L. Harris

Ol LA

CLH/10GAR-R0444B

Daga 1 afg



PREPARED 1/12/11, 14:02:44 INSPECTION TICKET PAGE 4
Harnett County INSPECTOR: IVR DATE 1/13/11

Harnett County INSPECTOR: IVR DATE 1/13/11

PHONE :

PROPOSED USE SFD

ADDRESS . : 126 SAW GRASS CT SUBDIV: WALNUT GROVE 37LOTS

CONTRACTOR : PALMETTO BUILDING INC. PHONE : (919) 795-0211

4.00

OWNER . . : EVEN PAR DEVELOPMENT LLC
PARCEL . . : 01-0525- - -0062- -32-

APPL NUMBER: 10-50023757 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: T/S: 02/10/2010 10:47 AM RDCONTE ---

126 SAW GRASS / WALNUT GROVE #23

STRUCTURE: 000 000 42X63 CRAWL 4BD/3BA W/GAR, FIN BN RM

TAKE 210S. GO APROX 9MI, T/L ON LASATER RD. GO APROX 1/4MI, T/L INTO WALNUT GROVE ON SAW GRASS. LOT IS ON THE RIGHT

SOUTH RIVER

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS :

	-	INSP	
	COMPLETED		RESULTS/COMMENTS
B101 01	10/08/10	KS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 00199192
	10/08/10	AP	T/S: 10/08/2010 09:41 AM NTART
A814 01	10/14/10	FB	ADDRESS CONFIRMATION VRU #: 001993906
	10/15/10	AP	T/S: 10/15/2010 04:17 PM FBURGESS
			✓ 126 SAW GRASS CT BUNNLEVEL, NC 28323 LOT 23
B103 01	10/14/10	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001993914
	10/14/10	AP	
B105 01	10/19/10	DT	R*OPEN FLOOR TIME: 17:00 VRU #: 001995737
	10/19/10	AP	T/S: 10/18/2010 11:24 AM RDCONTE
R425 01	11/04/10	JH	FOUR TRADE ROUGH IN VRU #: 002002251
	11/04/10	DA	1)Missing nuts & washers on anchor bolts in garage.
	, ,		2)Replace all notched stdus in garage, notch iis at bottom
			plate. 3) Need repair on 2 x 10 beam over master bedroom
			door where holes have been drilled through. 4) Fire caulk
			refridgerant lines @ top plate & floor in kitchen. 5)Add 2
			studs under lvls in kitchen @ bar. 6)Missing double joist
			inkitchen to left of window on end wall. 7) Missing studs in
			garage to left of lvls on right side. 8) Frame wall @ front
			door per 2 story plans note on plans. 9) Need letter for
			catalever on back if its not in file.
R425 02	11/05/10	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002003010
	11/05/10	DA	T/S: 11/04/2010 12:01 PM RDCONTE
			All violations corrected except front wall framing. Need
			verification from designer that front wall is to be balloon
			framed. If so, need corrective action from engineer. Ok to
			insulate. Will require letter before insulation inspection
I129 01	11/09/10	DT	R*INSULATION INSPECTION VRU #: 002003911
	11/09/10	AP	Thanks for helping me thru the two story foyer framing. I
			emailed Dean a copy of the engineering letter on how it was
			to be constructed, but I'm also leaving a copy in the
			permit box. Thanks againHank
R425 03	11/09/10	DT	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002004679
	11/09/10	AP	T/S: 11/08/2010 02:16 PM NTART
H824 01	12/13/10	OT	VENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002018877
	12/13/10	AP	T/S: 12/14/2010 09:32 AM SZIMMER

______CONTINUED ONTO NEXT PAGE --------

PREPARED 1/12/11, 14:02:44 INSPECTION TICKET PAGE 5 Harnett County INSPECTOR: IVR DATE 1/13/11 ADDRESS . : 126 SAW GRASS CT SUBDIV: WALNUT GROVE 37LOTS CONTRACTOR : PALMETTO BUILDING INC. PHONE: (919) 795-0211 OWNER . . : EVEN PAR DEVELOPMENT LLC PHONE : PARCEL . . : 01-0525- - -0062- -32-APPL NUMBER: 10-50023757 CP NEW RESIDENTIAL (SFD) ------REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS ______ T/S: 12/14/2010 09:32 AM SZIMMER ------R429 01 1/10/11 TI FOUR TRADE FINAL VRU #: 002027530

R429 02

1/13/11 _!/|3/\|

