INSPECTION TICKET PREPARED 3/09/10, 13:59:23 PAGE Harnett County INSPECTOR: IVR DATE 3/10/10 ADDRESS . : 326 STRIKE EAGLE DR SUBDIV: PATTONS POINT CONTRACTOR : BILL CLARK HOMES LLC PHONE: (252) 355-5805 OWNER . . : BILL CLARK HOME OF FAY PHONE: (910) 426-2898 PARCEL . : 03-9597- - -0039- -86-APPL NUMBER: 10-50023764 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 02/10/2010 11:27 AM JBROCK ----27 TOWARDS 87 TURN LEFT ON TINGEN RD TURN LEFT INTO S/D ON STRIKE EAGLE DR LOT IS DOWN STRIKE EAGLE DR LOT 92 ----STRUCTURE: 000 000 68X37 3BDR SLAB W/ GARAGE & PATIO FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE : SFD # BEDROOMS : 3000000.00 SEPTIC - EXISTING? . . . : NEW WATER SUPPLY : COUNTY PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

B101 01 3/10/10 TI R*BLDG FOOTING / TEMP SVC POLE VRU #: 001892811

3-10-10 DA-MR

Get eng

PREPARED 3/16/10, 13:58:36 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

50 DATE 3/17/10

SUBDIV: PATTONS POINT PHONE: (252) 355-5805

PHONE: (910) 426-2898

ADDRESS . : 326 STRIKE EAGLE DR CONTRACTOR : BILL CLARK HOMES LLC

OWNER . . : BILL CLARK HOME OF FAY

PARCEL . . : 03-9597- - -0039- -86-

APPL NUMBER: 10-50023764 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 02/10/2010 11:27 AM JBROCK ----

> 27 TOWARDS 87 TURN LEFT ON TINGEN RD TURN LEFT INTO S/D ON STRIKE EAGLE DR LOT IS DOWN STRIKE EAGLE DR LOT 92

STRUCTURE: 000 000 68X37 3BDR SLAB W/ GARAGE & PATIO

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE SFD # BEDROOMS 3000000.00

WATER SUPPLY : COUNTY SEPTIC - EXISTING? . . . : NEW

PERMIT: CPSF 00 CP * SFD DESCRIPTION REQUESTED INSP TYP/SQ COMPLETED RESULT RESULTS/COMMENTS ______ R*BLDG FOOTING / TEMP SVC POLE VRU #: 001892811 B101 01 3/10/10 T/S: 03/10/2010 01:47 PM MREARIC -----have engineer advise on water in footer 3/10/10 R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895002 Eng letter is in the permit box..... B101 02 3/16/10 JB 3/15/10 CA T/S: 03/15/2010 03:02 PM JBROCK -----CA PER CUSTOMER CALL 3/17/10 TI R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895184 B101 03 3-17-10 AE-MR

COMMENTS AND NOTES ------

Have eng. Report Notarized

PREPARED 3/19/10, 13:59:24 Harnett County

INSPECTION TICKET INSPECTOR: IVR _______

PAGE DATE

3/22/10

23

ADDRESS . : 326 STRIKE EAGLE DR CONTRACTOR : BILL CLARK HOMES LLC

SUBDIV: PATTONS POINT PHONE: (252) 355-5805 PHONE: (910) 426-2898

OWNER . . : BILL CLARK HOME OF FAY PARCEL . . : 03-9597- - -0039- -86-

APPL NUMBER: 10-50023764 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 02/10/2010 11:27 AM JBROCK ----

> 27 TOWARDS 87 TURN LEFT ON TINGEN RD TURN LEFT INTO S/D ON STRIKE EAGLE DR LOT IS DOWN STRIKE EAGLE DR LOT 92

_____ STRUCTURE: 000 000 68X37 3BDR SLAB W/ GARAGE & PATIO

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE SFD # BEDROOMS 3000000.00 WATER SUPPLY : COUNTY SEPTIC - EXISTING? . . . : NEW

PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS B101 01 3/10/10 MR 3/10/10 DA 3/16/10 JB B101 02 3/15/10 CA 3/17/10 MR B101 03 3/17/10 AE A814 01 3/22/10 TI B103 01 3/22/10 TI 32210 AP.M

R*BLDG FOOTING / TEMP SVC POLE VRU #: 001892811 T/S: 03/10/2010 01:47 PM MREARIC ----have engineer advise on water in footer R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895002 Eng letter is in the permit box..... T/S: 03/15/2010 03:02 PM JBROCK -----CA PER CUSTOMER CALL R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895184 T/S: 03/17/2010 02:21 PM MREARIC ----get engineers report notarized ADDRESS CONFIRMATION VRU #: 001897933 R*BLDG FOUND & TEMP SVC POLE VRU #: 001897941

----- COMMENTS AND NOTES -----

Nied Report on Plumbing IMP

PREPARED 3/25/10, 14:22:44 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE

3/26/10

40

SUBDIV: PATTONS POINT ADDRESS . : 326 STRIKE EAGLE DR CONTRACTOR : BILL CLARK HOMES LLC

PHONE: (252) 355-5805 PHONE: (910) 426-2898

OWNER . . : BILL CLARK HOME OF FAY PARCEL . . : 03-9597- - -0039- -86-

APPL NUMBER: 10-50023764 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: T/S: 02/10/2010 11:27 AM JBROCK ----

27 TOWARDS 87 TURN LEFT ON TINGEN RD TURN LEFT INTO S/D ON STRIKE EAGLE DR LOT IS DOWN STRIKE EAGLE DR LOT 92


STRUCTURE: 000 000 68X37 3BDR SLAB W/ GARAGE & PATIO

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE : SFD # BEDROOMS 3000000.00 WATER SUPPLY : COUNTY SEPTIC - EXISTING? . . . : NEW

PERMIT: CPSF 00 CP * SFD DESCRIPTION REQUESTED INSP TYP/SQ COMPLETED RESULT RESULTS/COMMENTS R*BLDG FOOTING / TEMP SVC POLE VRU #: 001892811 B101 01 3/10/10 MR T/S: 03/10/2010 01:47 PM MREARIC ------3/10/10 DA have engineer advise on water in footer R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895002 Eng letter is in the permit box.... B101 02 3/16/10 JB CA 3/15/10 T/S: 03/15/2010 03:02 PM JBROCK -----CA PER CUSTOMER CALL R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895184 B101 03 3/17/10 MR T/S: 03/17/2010 02:21 PM MREARIC -----3/17/10 AE get engineers report notarized ADDRESS CONFIRMATION VRU #: 001897933 3/22/10 TI A814 01 R*BLDG FOUND & TEMP SVC POLE VRU #: 001897941 B103 01 3/22/10 MR T/S: 03/22/2010 12:45 PM MREARIC -----3/22/10 AP still need sealed engineers report R*PLUMB UNDER SLAB VRU #: 001900697 TI P309 01 3/26/10 3-26-10 AP-M

------ COMMENTS AND NOTES -----





Engineering Services, P.C.

March 15, 2010

Bill Clark Homes 200 E. Arlington Blvd. Greenville, NC 27858

Attention: Mr. JJ Brenning

RE: Foundation Examination Observations

Lot 92, Patton's Point Fayetteville, North Carolina KAM Project No. 10-056

Gentlemen:

On March 11, 2010, a representative of KAM Engineering Services, P.C. was present to perform an examination of the bearing grade soils for the Northwest corner of foundations of Lot 92. Our examination included visual observation, hand rod probing, and dynamic cone penetrometer testing in general accordance with ASTM STP-399. We understand that the new building foundations have been designed using a soil bearing capacity of 2,000 pounds per square foot (psf). The examination performed on this date included only the North West perimeter corner, extending 35 feet East and 10 feet South, and therefore no comment may be made regarding bearing capacity of areas outside of this range. At the time of our arrival at the site, the footing excavations were complete.

Based upon our visual observation of the bearing soils in the footing excavations, the soils are flat and free of deleterious material. The bearing soils appear to consist of clayey sand (USCS SC) material. The soils located in the foundations at the bearing surface appeared to be wet. The bearing surface was hand-rod probed to determine the soil consistency. Based upon these observations, it appears that the sandy clay soils are loose to depths of approximately 12 inches in most locations. Below this depth, the soils are firm and resistant to penetration of the hand-rod probe.

Additionally, dynamic cone penetrometer (DCP) testing was performed at selected areas in the footing excavations. Our DCP testing was performed at the bottom of the footing elevation, and at 12-inch intervals, to a total depth of 36 inches. As indicated by our hand rod probing, the surface soils are soft to a depth of 12 inches, and significantly denser below this depth. We note the presence of groundwater on the surface of the bearing soils. In order to achieve a bearing capacity of 2,000 psf, we recommended that the wet and loose materials be removed to a depth of 12 inches. The resulting excavation should be backfilled using a washed No. 57 stone wrapped in a filter fabric such as Mirafi 140N, and the bottom excavation graded to drain to a low point in the footing. A french drain should subsequently be installed to drain water from the low-point to a lower elevation away from the building foundation. The recommended repairs were not performed while a KAM Engineering representative was onsite. Based upon our observations at the site, and upon completion of the recommended remedial measures, the bearing grade soils will be suitable to provide a bearing capacity of 2,000 psf.



It is important to note that our testing was performed to a depth of 36 inches below the bottom of footing elevation. As such, we are unable to comment upon the settlement characteristics of deeper soils. If soils are left open, or exposed to inclement weather, the bearing characteristics of the soils are prone to change and could be compromised. If the soils become compromised, another inspection should be performed by our representative to demonstrate that the bearing capacity is still available.

We appreciate the opportunity to be of service to you on this project. Should you need additional information, please contact us.

Respectfully submitted, KAM Engineering Services, P.C.

Digitally

signed by Brad Carlson

Brad Carlson Project Manager Kurt A. Miller, Senior Geotechn PREPARED 3/26/10, 14:00:59
Harnett County Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

3.0

DATE 3/29/10

ADDRESS . : 326 STRIKE EAGLE DR SUBDIV: PATTONS POINT PHONE: (252) 355-5805 CONTRACTOR : BILL CLARK HOMES LLC PHONE : (910) 426-2898 OWNER . . : BILL CLARK HOME OF FAY

PARCEL . . : 03-9597- - -0039- -86-

APPL NUMBER: 10-50023764 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 02/10/2010 11:27 AM JBROCK ----27 TOWARDS 87 TURN LEFT ON TINGEN RD TURN LEFT INTO S/D ON STRIKE EAGLE DR LOT IS DOWN STRIKE EAGLE DR LOT 92

STRUCTURE: 000 000 68X37 3BDR SLAB W/ GARAGE & PATIO

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE : SFD # BEDROOMS 3000000.00 WATER SUPPLY : COUNTY SEPTIC - EXISTING? . . . : NEW

PERMIT: CPSF 00 CP * SFD DESCRIPTION REQUESTED INSP TYP/SQ COMPLETED RESULT RESULTS/COMMENTS R*BLDG FOOTING / TEMP SVC POLE VRU #: 001892811 B101 01 3/10/10 MR T/S: 03/10/2010 01:47 PM MREARIC -----3/10/10 DA have engineer advise on water in footer R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895002 3/16/10 JB B101 02 Eng letter is in the permit box.... 3/15/10 CA T/S: 03/15/2010 03:02 PM JBROCK -----CA PER CUSTOMER CALL R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895184 B101 03 3/17/10 MR T/S: 03/17/2010 02:21 PM MREARIC -----3/17/10 AE get engineers report notarized ADDRESS CONFIRMATION VRU #: 001897933 3/22/10 TI A814 01 R*BLDG FOUND & TEMP SVC POLE VRU #: 001897941 3/22/10 MR B103 01 T/S: 03/22/2010 12:45 PM MREARIC -----AΡ 3/22/10 still need sealed engineers report R*PLUMB UNDER SLAB VRU #: 001900697 MR 3/26/10 P309 01 T/S: 03/26/2010 12:40 PM MREARIC -----3/26/10 AP R*BLDG SLAB INSP TIME: 17:00 VRU #: 001901420 ΤI 3/29/10 B111 01 T/S: 03/26/2010 01:19 PM RDCONTE -----NEEDS DONE AS EARLY AS POSSIBLE, HAS CONC SCHEDULED FOR 11AM

_____COMMENTS AND NOTES -----

PREPARED 4/27/10, 13:59:07 INSPECTION TICKET PAGE 17 DATE 4/28/10 Harnett County INSPECTOR: IVR

ADDRESS . : 326 STRIKE EAGLE DR SUBDIV: PATTONS POINT CONTRACTOR : BILL CLARK HOMES LLC PHONE: (252) 355-5805 PHONE: (910) 426-2898 OWNER . . : BILL CLARK HOME OF FAY

PARCEL . .: 03-9597- - -0039- -86-

APPL NUMBER: 10-50023764 CP NEW RESIDENTIAL (SFD) DIRECTIONS : T/S: 02/10/2010 11:27 AM JBROCK ----27 TOWARDS 87 TURN LEFT ON TINGEN RD TURN LEFT INTO S/D ON STRIKE EAGLE DR

STRUCTURE: 000 000 68X37 3BDR SLAB W/ GARAGE & PATIO

LOT IS DOWN STRIKE EAGLE DR LOT 92

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE SFD # BEDROOMS 3000000.00 WATER SUPPLY : COUNTY SEPTIC - EXISTING? . . . : NEW

TYP/SQ		INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	3/10/10	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001892811
	3/10/10	DA	T/S: 03/10/2010 01:47 PM MREARIC
	-,,		have engineer advise on water in footer
B101 02	3/16/10	JВ	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895002
	3/15/10	CA	Eng letter is in the permit box
	-,,		T/S: 03/15/2010 03:02 PM JBROCK
			CA PER CUSTOMER CALL
B101 03	3/17/10	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895184
	3/17/10	AE	T/S: 03/17/2010 02:21 PM MREARIC
	,		get engineers report notarized
B103 01	3/22/10	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001897941
	3/22/10	AP	T/S: 03/22/2010 12:45 PM MREARIC
	, ,		still need sealed engineers report
A814 01	3/22/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001897933
	3/30/10	AP	326 strike eagle dr lot 92
			broadway 27505
			T/S: 03/30/2010 03:49 PM TWARD
P309 01	3/26/10	MR	R*PLUMB UNDER SLAB VRU #: 001900697
	3/26/10	AP	T/S: 03/26/2010 12:40 PM MREARIC
B111 01	3/29/10	MR	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001901420
	3/29/10	AP	T/S: 03/26/2010 01:19 PM RDCONTE
			NEEDS DONE AS EARLY AS POSSIBLE, HAS CONC SCHEDULED FOR
			11AM
			T/S: 03/29/2010 12:27 PM MREARIC
			this was done on 3.25.10
R425 01	4/28/10	TI	FOUR TRADE ROUGH IN VRU #: 001916709
	41-28-10	DA-MK	
•		 >	
			COMMENTS AND NOTES

HARNETT COUNTY

Building Inspections Dept. 108 E. Front St. Lillington, NC 27546 910-893-7525

DO NOT REMOVE

DATE: 04-28-10

, A .

PERMIT # 10-50023764

ADDRESS: 326 strike eagle.

VIOLATIONS:

1. Strap all truss ends... see d3g

2. Close up all open holes in fireplace cabinet

3. Will check on insulation inspection

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

PREPARED 4/30/10, 14:29:12 INSPECTION TICKET

Harnett County INSPECTOR: IVR

DATE 5/03/10

Harnett County INSPECTOR: IVR DATE 5/03/10

ADDRESS : 326 STRIKE EAGLE DR SUBDIV: PATTONS POINT CONTRACTOR : BILL CLARK HOMES LLC PHONE : (252) 355-5805 OWNER . . : BILL CLARK HOME OF FAY PHONE : (910) 426-2898

PARCEL . . : 03-9597- - -0039- -86-

APPL NUMBER: 10-50023764 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: T/S: 02/10/2010 11:27 AM JBROCK ----27 TOWARDS 87 TURN LEFT ON TINGEN RD

TURN LEFT INTO S/D ON STRIKE EAGLE DR
LOT IS DOWN STRIKE EAGLE DR LOT 92

STRUCTURE: 000 000 68X37 3BDR SLAB W/ GARAGE & PATIO

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 3000000.00 PROPOSED USE : SFD SEPTIC - EXISTING? . . . : NEW WATER SUPPLY : COUNTY

TATAL BOTTAL COUNTY

PERMIT:	CPSF 00 CP *		
	REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED		RESULTS/COMMENTS
B101 01	3/10/10	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001892811
	3/10/10	DA	T/S: 03/10/2010 01:47 PM MREARIC
B101 02	3/16/10	JВ	have engineer advise on water in footer R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895002
	3/15/10	CA	Eng letter is in the permit box
			T/S: 03/15/2010 03:02 PM JBROCK
			CA PER CUSTOMER CALL
B101 03	3/17/10	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895184
	3/17/10	AE	T/S: 03/17/2010 02:21 PM MREARIC
			get engineers report notarized
B103 01	3/22/10	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001897941
	3/22/10	AP	T/S: 03/22/2010 12:45 PM MREARIC
			still need sealed engineers report
A314 01	3/22/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001897933
	3/30/10	AP	326 strike eagle dr lot 92
			broadway 27505
			T/S: 03/30/2010 03:49 PM TWARD
P309 01	3/26/10	MR	R*PLUMB UNDER SLAB VRU #: 001900697
	3/26/10	AP	T/S: 03/26/2010 12:40 PM MREARIC
E:11 01	3/29/10	MR	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001901420
	3/29/10	AP	T/S: 03/26/2010 01:19 PM RDCONTE
-			NEEDS DONE AS EARLY AS POSSIBLE, HAS CONC SCHEDULED FOR
			11AM
			T/S: 03/29/2010 12:27 PM MREARIC
			this was done on 3.25.10
R425 01	4/28/10	MR	FOUR TRADE ROUGH IN VRU #: 001916709
	4/28/10	DA	T/S: 04/28/2010 12:21 PM MREARIC
			1. strap all trusses see D3g
			2. close up all holes in fireplace wall envelope
7100 01	4/20/20		ok to side and insul.
I129 01	4/30/10	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001918606
	4/30/10	CA	T/S: 04/29/2010 12:29 PM JBROCK
B425 02	4/20/10	.m	T/S: 04/30/2010 11:18 AM MREARIC
R425 02	4/30/10	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001918598
	4/30/10	CA	T/S: 04/29/2010 12:29 PM JBROCK
			T/S: 04/30/2010 11:18 AM MREARIC

------ CONTINUED ONTO NEXT PAGE -----

× = 3 4/30/10, 14 29:12 INSPECTION TICKET PAGE t County INSPECTOR: FIVE DATE 5/03/10 RESS . : 326 STRIKE EAGLE DR SUBDIV: PATTONS POINT TRACTOR : BILL CLARK HOMES LLC PHONE: (252) 355-5805 IR . . : BILL CLARK HOME OF FAY PHONE: (910) 426-2898 'EL . . : 03-9597- - -0039- -86-NUMBER: 10-50023764 CP NEW RESIDENTIAL (SFD) REQUESTED INSP DESCRIPTION SQ COMPLETED RESULT RESULTS/COMMENTS 02 5/03/10 TI R*INSULATION INSPECTION VRU #: 001919513 5-3-16 AP-UR FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001919596 T/S: 04/30/2010 02:28 PM DJOHNSON -----COMMENTS AND NOTES -----

PREPARED 6/22/10, 13:59:55 INSPECTION TICKET PAGE 19
Harnett County 5 INSPECTOR: IVR DATE 6/23/10

Harnett County INSPECTOR: IVR DATE 6/23/1

ADDRESS . : 326 STRIKE EAGLE DR SUBDIV: PATTONS POINT CONTRACTOR : BILL CLARK HOMES LLC PHONE : (252) 355-5805 OWNER . . : BILL CLARK HOME OF FAY PHONE : (910) 426-2898

PARCEL . . : 03-9597- - -0039- -86-

APPL NUMBER: 10-50023764 CP NEW RESIDENTIAL (SFD)
DIRECTIONS: T/S: 02/10/2010 11:27 AM JBROCK ---27 TOWARDS 87 TURN LEFT ON TINGEN RD
TURN LEFT INTO S/D ON STRIKE EAGLE DR
LOT IS DOWN STRIKE EAGLE DR LOT 92

STRUCTURE: 000 000 68X37 3BDR SLAB W/ GARAGE & PATIO

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 3000000.00 PROPOSED USE : SFD SEPTIC - EXISTING? . . . : NEW WATER SUPPLY : COUNTY

PERMIT:	CPSF 00 CP *	SFD	
	REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED		RESULTS/COMMENTS
	3/10/10		R*BLDG FOOTING / TEMP SVC POLE VRU #: 001892811
2101 01	3/10/10	DA	T/S: 03/10/2010 01:47 PM MREARIC
	3, 23, 23		have engineer advise on water in footer
B101 02	3/16/10	JB	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895002
	3/15/10	CA	Eng letter is in the permit box
			T/S: 03/15/2010 03:02 PM JBROCK
			CA PER CUSTOMER CALL
B101 03	3/17/10	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895184
	3/17/10	AE	T/S: 03/17/2010 02:21 PM MREARIC
			get engineers report notarized
B103 01	3/22/10	MIR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001897941
	3/22/10	AP	T/S: 03/22/2010 12:45 PM MREARIC
			still need sealed engineers report
A814 01	3/22/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001897933
	3/30/10	AP	$\sqrt{326}$ strike eagle dr lot 92
			broadway 27505
			T/S: 03/30/2010 03:49 PM TWARD
P309 01	3/26/10	MR	R*PLUMB UNDER SLAB
	3/26/10	AP	
B111 01	3/29/10	MR	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001901420 T/S: 03/26/2010 01:19 PM RDCONTE
	3/29/10	AP	NEEDS DONE AS EARLY AS POSSIBLE, HAS CONC SCHEDULED FOR
			11AM
			T/S: 03/29/2010 12:27 PM MREARIC
			this was done on 3.25.10
R425 01	4/28/10	MR	FOUR TRADE ROUGH IN VRU #: 001916709
K425 01	4/28/10	DA	T/S: 04/28/2010 12:21 PM MREARIC
	1,20,10	2	1. strap all trusses see D3g
			2. close up all holes in fireplace wall envelope
			ok to side and insul.
I129 01	4/30/10	MIR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001918606
	4/30/10	CA	T/S: 04/29/2010 12:29 PM JBROCK
	, .		T/S: 04/30/2010 11:18 AM MREARIC
R425 02	4/30/10	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001918598
	4/30/10	CA	T/S: 04/29/2010 12:29 PM JBROCK
			T/S: 04/30/2010 11:18 AM MREARIC
I129 02	5/03/10	MR	R*INSULATION INSPECTION VRU #: 001919513
			•

----- CONTINUED ONTO NEXT PAGE -----

PREPARED 6/22/10, 13:59:55 INSPECTION TICKET PAGE 20
Harnett County INSPECTOR: IVR DATE 6/23/10

ADDRESS . : 326 STRIKE EAGLE DR SUBDIV: PATTONS POINT CONTRACTOR : BILL CLARK HOMES LLC PHONE : (252) 355-5805 OWNER . . : BILL CLARK HOME OF FAY PHONE : (910) 426-2898

PARCEL . .: 03-9597- - -0039- -86-

APPL NUMBER: 10-50023764 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	5/03/10	AP	T/S: 05/03/2010 11:50 AM MREARIC
R425 03	5/03/10	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001919596
	5/03/10	AP	T/S: 04/30/2010 02:28 PM DJOHNSON
			T/S: 05/03/2010 11:51 AM MREARIC
H824 01	5/04/10	OT	VENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001921055
	5/04/10	AP	T/S: 05/05/2010 10:36 AM SSTEWART
			T/S: 05/05/2010 10:37 AM SSTEWART
R429 01	6/23/10	TI _	FOUR TRADE FINAL VRU #: 001945013
	6.23.10	DP-MR	
	·	• •	

------ COMMENTS AND NOTES ------

HARNETT COUNTY

Building Inspections Dept. 108 E. Front St. Lillington, NC 27546 910-893-7525

DO NOT REMOVE

DATE: 06-23-10

PERMIT # 10-50023764

ADDRESS: 326 strike eagle

VIOLATIONS:

Not enough insulation in attic

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

PREPARED 6/25/10, 14:26:49 INSPECTION TICKET PAGE 17 DATE 6/28/10 Harnett County INSPECTOR: IVR

ADDRESS . : 326 STRIKE EAGLE DR SUBDIV: PATTONS POINT CONTRACTOR : BILL CLARK HOMES LLC PHONE: (252) 355-5805 OWNER . . : BILL CLARK HOME OF FAY PHONE: (910) 426-2898

PARCEL . : 03-9597- - -0039- -86-

APPL NUMBER: 40250023764xGP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 02/10/2010 11:27 AM JBROCK ----27 TOWARDS 87 TURN LEFT ON TINGEN RD TURN LEFT INTO S/D ON STRIKE EAGLE DR LOT IS DOWN STRIKE EAGLE DR LOT 92

STRUCTURE: 000 000 68X37 3BDR SLAB W/ GARAGE & PATIO

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS 3000000.00 PROPOSED USE : SFD SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT:	CPSF 00 CP * REQUESTED	INSP	DESCRIPTION
ryp/sq	COMPLETED		RESULTS/COMMENTS
	3/10/10	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001892811
	3/10/10	DA	T/S: 03/10/2010 01:47 PM MREARIC
			have engineer advise on water in footer
3101 02	3/16/10	JB	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895002
	3/15/10	CA	Eng letter is in the permit box
			T/S: 03/15/2010 03:02 PM JBROCK
			CA PER CUSTOMER CALL
101 03	3/17/10	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001895184
	3/17/10	AE	T/S: 03/17/2010 02:21 PM MREARIC
			get engineers report notarized
3103 01	3/22/10	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001897941
	3/22/10	AP	T/S: 03/22/2010 12:45 PM MREARIC
			still need sealed engineers report
814 01	3/22/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001897933
	3/30/10	AP	326 strike eagle dr lot 92
			broadway 27505
	- 11		T/S: 03/30/2010 03:49 PM TWARD
309 01	3/26/10	MIR 	R*PLUMB UNDER SLAB VRU #: 001900697
	3/26/10	AP	T/S: 03/26/2010 12:40 PM MREARIC
111 01	3/29/10	MR	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001901420
	3/29/10	AP	T/S: 03/26/2010 01:19 PM RDCONTE
			NEEDS DONE AS EARLY AS POSSIBLE, HAS CONC SCHEDULED FOR
			11AM T/S: 03/29/2010 12:27 PM MREARIC
			this was done on 3.25.10
42E 01	4/28/10	MR	FOUR TRADE ROUGH IN VRU #: 001916709
425 UI	4/28/10	DA	T/S: 04/28/2010 12:21 PM MREARIC
	4/20/10	DA	1. strap all trusses see D3g
			2. close up all holes in fireplace wall envelope
			ok to side and insul.
129 01	4/30/10	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001918606
	4/30/10	CA	T/S: 04/29/2010 12:29 PM JBROCK
	1,00,10		T/S: 04/30/2010 11:18 AM MREARIC
425 02	4/30/10	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001918598
v	4/30/10	CA	T/S: 04/29/2010 12:29 PM JBROCK
	2, 22, 23		T/S: 04/30/2010 11:18 AM MREARIC
129 02	5/03/10	MR	R*INSULATION INSPECTION VRU #: 001919513

PREPARED 6/25/10, 14:26:49
Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE

6/28/10

ADDRESS : : 326 STRIKE EAGLE DR
CONTRACTOR : BILL CLARK HOMES LLC
OWNER : : BILL CLARK HOME OF FAY

SUBDIV: PATTONS POINT
PHONE : (252) 355-5805
PHONE : (910) 426-2898

PARCEL . . : 03-9597- - -0039- -86-

APPL NUMBER: 10-50023764 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R425 03	5/03/10 5/03/10	AP MR	T/S: 05/03/2010 11:50 AM MREARIC
R425 05	5/03/10	AP	T/S: 04/30/2010 02:28 PM DJOHNSON
H824 01	5/04/10	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001921055
	5/04/10	AP	T/S: 05/05/2010 10:36 AM SSTEWART
R429 01	6/23/10 6/24/10	MR DP	FOUR TRADE FINAL VRU #: 001945013 T/S: 06/24/2010 12:54 PM MREARIC
R429 02	6/25/10	MR	not enough insulation in attic FOUR TRADE FINAL TIME: 17:00 VRU #: 001946128
	6/25/10	CA	T/S: 06/24/2010 01:09 PM VBROWN
R429=03====61/281/10=========			door locked FOUR TRADE FINAL TIME: 17:00 VRU #: 001946631
	6-280	AP-NE	T/S: 06/25/2010 12:00 PM RDCONTE

County of Harnett Building Inspections Department Planning Services

Certificate of Compliance: X Occupancy: X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: R3		Permit Numbers
Name: Bill Clark Home	es LLC	Building: 10-50023764
	an .	Electrical:
Address:		Insulation: U
326 Strike Eagle		Plumbing:
		Mechanical:
		MFG Home:
Date: 6.2 Os. 10 Bui	ilding Official	of mar. Opai