
ADDRESS . . : 278 GOLD CT SUBDIV: TINGEN POINTE PH 3B
 CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
 OWNER . . . : THE HARNETT LAND GROUP II LLC PHONE :
 PARCEL . . . : 03-9576-01- -0088- -02-
 APPL NUMBER: 10-50024596 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 06/14/2010 12:11 PM VBROWN -----
 278 GOLD COURT TINGEN POINT #98. 27W
 GO PAST WHHS 3MI ON LEFT.

STRUCTURE: 000 000 60X60 3BDR 2BATH SFD WITH GAR SLAB
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED	INSP	DESCRIPTION
	COMPLETED	RESULT	RESULTS/COMMENTS
P309 01	7/15/10	TI	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001954528
	<u>7-15-10</u>	<u>AP-MR</u>	T/S: 07/14/2010 01:07 PM VBROWN -----

----- COMMENTS AND NOTES -----

25358440

ADDRESS : 278 GOLD CT
CONTRACTOR : WYNN CONSTRUCTION, INC.
OWNER : THE HARNETT LAND GROUP II LLC
PARCEL : 03-9576-01- -0088- -02-
APPL NUMBER: 10-50024596 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 06/14/2010 12:11 PM VBROWN ----
278 GOLD COURT TINGEN POINT #98. 27W
GO PAST WHHS 3MI ON LEFT.

SUBDIV: TINGEN POINTE PH 3B
PHONE : (919) 528-1347
PHONE :

STRUCTURE: 000 000 60X60 3BDR 2BATH SFD WITH GAR SLAB

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW TANK
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	7/15/10	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001954528
	7/15/10	AP	T/S: 07/14/2010 01:07 PM VBROWN ----- T/S: 07/15/2010 12:23 PM MREARIC -----
B111 01	7/16/10	TI	R*BLDG SLAB INSP VRU #: 001955432

7-16-10 ~~CA MR~~
AP-MR

COMMENTS AND NOTES

~~Not Ready~~

ADDRESS : 278 GOLD CT SUBDIV: TINGEN POINTE PH 3B
CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
OWNER : THE HARNETT LAND GROUP II LLC PHONE :
PARCEL : 03-9576-01- -0088- -02-
APPL NUMBER: 10-50024596 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 06/14/2010 12:11 PM VBROWN ----
278 GOLD COURT TINGEN POINT #98. 27W
GO PAST WHHS 3MI ON LEFT.

STRUCTURE: 000 000 60X60 3BDR 2BATH SFD WITH GAR SLAB

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	7/15/10	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001954528
	7/15/10	DA	T/S: 07/14/2010 01:07 PM VBROWN ----- T/S: 07/15/2010 12:23 PM MREARIC ----- T/S: 07/16/2010 02:00 PM MREARIC ----- steel needed in footer
B111 01	7/16/10	MR	R*BLDG SLAB INSP VRU #: 001955432
	7/16/10	DA	T/S: 07/16/2010 01:47 PM NTART -----
B111 02	7/19/10	TI	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001956143
	<u>7-19-10</u>	<u>AP-MR</u>	T/S: 07/16/2010 01:48 PM NTART -----

COMMENTS AND NOTES

Rebar installed

Harnett County

INSPECTOR: IVR

DATE 8/06/10

ADDRESS . . : 278 GOLD CT SUBDIV: TINGEN POINTE PH 3B
 CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
 OWNER . . : THE HARNETT LAND GROUP II LLC PHONE :
 PARCEL . . : 03-9576-01- -0088- -02-
 APPL NUMBER: 10-50024596 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 06/14/2010 12:11 PM VBROWN ----
 278 GOLD COURT TINGEN POINT #98. 27W
 GO PAST WHHS 3MI ON LEFT.

STRUCTURE: 000 000 60X60 3BDR 2BATH SFD WITH GAR SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	7/15/10	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001954528
	7/15/10	DA	T/S: 07/14/2010 01:07 PM VBROWN ----- T/S: 07/15/2010 12:23 PM MREARIC ----- T/S: 07/16/2010 02:00 PM MREARIC ----- steel needed in footer
B111 01	7/16/10	MR	R*BLDG SLAB INSP VRU #: 001955432
	7/16/10	DA	T/S: 07/16/2010 01:47 PM NTART -----
B111 02	7/19/10	MR	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001956143
	7/19/10	AP	T/S: 07/16/2010 01:48 PM NTART ----- T/S: 07/19/2010 11:22 AM MREARIC -----
A814 01	8/06/10	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001965029
			T/S: 08/05/2010 09:45 AM RDCONTE -----
R425 01	8/06/10	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001965037
	<u>8-6-10</u>	<u>DA-MR</u>	T/S: 08/05/2010 09:45 AM RDCONTE -----

----- COMMENTS AND NOTES -----

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DO NOT REMOVE

DATE: 08-06-10

PERMIT # 10-50024596

ADDRESS: 278 gold

1. Double girder beams must be nailed on edge per Table 602.3(1)
2. Seal openings in slab under tubs
3. No fireplace or gas line
4. Bolt or screw side loaded Garage lam beam per specs.
5. Ok to side and insulate

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

ADDRESS : 278 GOLD CT SUBDIV: TINGEN POINTE PH 3B
 CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
 OWNER : THE HARNETT LAND GROUP II LLC PHONE :
 PARCEL : 03-9576-01- -0088- -02-
 APPL NUMBER: 10-50024596 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 06/14/2010 12:11 PM VBROWN ----
 278 GOLD COURT TINGEN POINT #98. 27W
 GO PAST WHHS 3MI ON LEFT.

STRUCTURE: 000 000 60X60 3BDR 2BATH SFD WITH GAR SLAB
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	7/15/10 7/15/10	MR DA	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001954528 T/S: 07/14/2010 01:07 PM VBROWN ---- T/S: 07/15/2010 12:23 PM MREARIC ---- T/S: 07/16/2010 02:00 PM MREARIC ---- steel needed in footer
B111 01	7/16/10 7/16/10	MR DA	R*BLDG SLAB INSP VRU #: 001955432 T/S: 07/16/2010 01:47 PM NTART ----
B111 02	7/19/10 7/19/10	MR AP	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001956143 T/S: 07/16/2010 01:48 PM NTART ---- T/S: 07/19/2010 11:22 AM MREARIC ----
A814 01	8/06/10 8/06/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001965029 T/S: 08/05/2010 09:45 AM RDCONTE ---- 278 gold ct lot 98 broadway 27505 T/S: 08/06/2010 01:43 PM TWARD ----
R425 01	8/06/10 8/06/10	MR DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001965037 T/S: 08/05/2010 09:45 AM RDCONTE ---- T/S: 08/06/2010 01:05 PM MREARIC ---- double girder box beams must be nailed on edge at 16" 602.3(2) seal openings through slab bolt or screw lam beams per specs ok to side and insulate
R425 02	8/09/10 <i>8-9-10</i>	TI <i>APJD</i>	FOUR TRADE ROUGH IN VRU #: 001966217

COMMENTS AND NOTES

ADDRESS : 278 GOLD CT SUBDIV: TINGEN POINTE PH 3B
 CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
 OWNER : THE HARNETT LAND GROUP II LLC PHONE :
 PARCEL : 03-9576-01- -0088- -02-
 APPL NUMBER: 10-50024596 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 06/14/2010 12:11 PM VBROWN ----
 278 GOLD COURT TINGEN POINT #98. 27W
 GO PAST WHHS 3MI ON LEFT.

STRUCTURE: 000 000 60X60 3BDR 2BATH SFD WITH GAR SLAB
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	7/15/10	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001954528
	7/15/10	DA	T/S: 07/14/2010 01:07 PM VBROWN ----- T/S: 07/15/2010 12:23 PM MREARIC ----- T/S: 07/16/2010 02:00 PM MREARIC ----- steel needed in footer
B111 01	7/16/10	MR	R*BLDG SLAB INSP VRU #: 001955432
	7/16/10	DA	T/S: 07/16/2010 01:47 PM NTART -----
B111 02	7/19/10	MR	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001956143
	7/19/10	AP	T/S: 07/16/2010 01:48 PM NTART ----- T/S: 07/19/2010 11:22 AM MREARIC -----
A814 01	8/06/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001965029
	8/06/10	AP	T/S: 08/05/2010 09:45 AM RDCONTE ----- 278 gold ct lot 98 roadway 27505 T/S: 08/06/2010 01:43 PM TWARD -----
R425 01	8/06/10	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001965037
	8/06/10	DA	T/S: 08/05/2010 09:45 AM RDCONTE ----- T/S: 08/06/2010 01:05 PM MREARIC ----- double girder box beams must be nailed on edge at 16" seal openings through slab bolt or screw lam beams per specs ok to side and insulate
R425 02	8/09/10	JH	FOUR TRADE ROUGH IN VRU #: 001966217
	8/09/10	AP	-----
I129 01	8/10/10	TI	R*INSULATION INSPECTION VRU #: 001967241
	<u>8/10/10</u>	<u>AP DT</u>	

COMMENTS AND NOTES

ADDRESS : 278 GOLD CT SUBDIV: TINGEN POINTE PH 3B
CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
OWNER : THE HARNETT LAND GROUP II LLC PHONE :
PARCEL : 03-9576-01- -0088- -02- 25358440
APPL NUMBER: 10-50024596 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 06/14/2010 12:11 PM VBROWN ----
278 GOLD COURT TINGEN POINT #98. 27W
GO PAST WHHS 3MI ON LEFT.

STRUCTURE: 000 000 60X60 3BDR 2BATH SFD WITH GAR SLAB

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	7/15/10 7/15/10	MR DA	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001954528 T/S: 07/14/2010 01:07 PM VBROWN T/S: 07/15/2010 12:23 PM MREARIC T/S: 07/16/2010 02:00 PM MREARIC steel needed in footer
B111 01	7/16/10 7/16/10	MR DA	R*BLDG SLAB INSP VRU #: 001955432 T/S: 07/16/2010 01:47 PM NTART
B111 02	7/19/10 7/19/10	MR AP	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001956143 T/S: 07/16/2010 01:48 PM NTART T/S: 07/19/2010 11:22 AM MREARIC
A814 01	8/06/10 8/06/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001965029 T/S: 08/05/2010 09:45 AM RDCONTE 278 gold ct lot 98 broadway 27505 T/S: 08/06/2010 01:43 PM TWARD
R425 01	8/06/10 8/06/10	MR DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001965037 T/S: 08/05/2010 09:45 AM RDCONTE T/S: 08/06/2010 01:05 PM MREARIC double girder box beams must be nailed on edge at 16" seal openings through slab bolt or screw lam beams per specs ok to side and insulate
R425 02	8/09/10 8/09/10	JH AP	FOUR TRADE ROUGH IN VRU #: 001966217
I129 01	8/10/10 8/10/10	DT AP	R*INSULATION INSPECTION VRU #: 001967241
H824 01	9/23/10 9/23/10	OT DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001986397 PUMP AND ALARM STILL TO BE CHECKED. T/S: 09/23/2010 09:47 AM SZIMMER T/S: 09/23/2010 09:48 AM SZIMMER T/S: 09/23/2010 11:35 AM SSTEWARD
H824 02	9/28/10 9/28/10	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001988039 T/S: 09/29/2010 09:19 AM SZIMMER T/S: 09/29/2010 09:19 AM SZIMMER
R429 01	10/18/10 10/18/10	MR CA	FOUR TRADE FINAL VRU #: 001995331 T/S: 10/18/2010 11:25 AM MREARIC rafter fit ac access

PREPARED 10/21/10, 13:57:43
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 8
DATE 10/22/10

ADDRESS : 278 GOLD CT
CONTRACTOR : WYNN CONSTRUCTION, INC.
OWNER : THE HARNETT LAND GROUP II LLC
PARCEL : 03-9576-01- -0088- -02-
APPL NUMBER: 10-50024596 CP NEW RESIDENTIAL (SFD)

SUBDIV: TINGEN POINTE PH 3B
PHONE : (919) 528-1347
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R429 02	10/22/10 <u>10/22/10</u>	TI <u>APDF</u>	handrail attic door FOUR TRADE FINAL VRU #: 001997345

COMMENTS AND NOTES

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: ___ Occupancy: X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Permit Numbers

Name: Wynn Construction Inc

Building: _____

Electrical: _____

Address: 278 Gold Ct

Insulation: _____

Broadway, NC 27505

Plumbing: _____

Mechanical: 10-50024546

MFG Home: _____

Date: 10/22/10

Building Official: [Signature]