

ADDRESS : 138 GOLD CT
CONTRACTOR : WYNN CONSTRUCTION, INC.
OWNER : THE HARNETT LAND GROUP II LLC
PARCEL : 03-9576- - -0088- -96-
APPL NUMBER: 10-50024774 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 07/07/2010 02:59 PM RDCONTE ---
138 GOLD COURT / TINGEN POINTE #92
TAKE 27W APPROX 11MI. T/L INTO TINGEN
POINTE ON OMAHA DRIVE. T/R ON GOLD
COURT.
PREMISE # WAITING ON CUS

SUBDIV: TINGEN POINTE PH 3B
PHONE : (919) 528-1347
PHONE :

3158 4373

STRUCTURE: 000 000 60X50 SLAB 3BD/2BA W/GAR

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	11/08/10 <u>11-8-10</u>	TI <u>AP-MR</u>	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002003598 T/S: 11/05/2010 12:00 PM VBROWN -----

COMMENTS AND NOTES

ADDRESS . . : 138 GOLD CT
 SUBDIV: TINGEN POINTE PH 3B

CONTRACTOR : WYNN CONSTRUCTION, INC.
 PHONE : (919) 528-1347

OWNER . . : THE HARNETT LAND GROUP II LLC
 PHONE :

PARCEL . . : 03-9576- - -0088- -96-

APPL NUMBER: 10-50024774 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 07/07/2010 02:59 PM RDCONTE ---
 138 GOLD COURT / TINGEN POINTE #92
 TAKE 27W APPROX 11MI. T/L INTO TINGEN
 POINTE ON OMAHA DRIVE. T/R ON GOLD
 COURT.
 PREMISE # WAITING ON CUS

STRUCTURE: 000 000 60X50 SLAB 3BD/2BA W/GAR

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00 PROPOSED USE : SFD

SEPTIC - EXISTING? : SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	11/08/10	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002003598
	11/08/10	AP	T/S: 11/05/2010 12:00 PM VBROWN ----- T/S: 11/08/2010 09:45 AM MREARIC ----- #31584373
B114 01	11/12/10	TI	R*BLDG MONOLITHIC SLAB VRU #: 002005494

11-12-10 AP MR

----- COMMENTS AND NOTES -----

ADDRESS : 138 GOLD CT SUBDIV: TINGEN POINTE PH 3B
CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
OWNER : THE HARNETT LAND GROUP II LLC PHONE :
PARCEL : 03-9576- - -0088- -96-
APPL NUMBER: 10-50024774 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 07/07/2010 02:59 PM RDCONTE ---
138 GOLD COURT / TINGEN POINTE #92
TAKE 27W APPROX 11MI. T/L INTO TINGEN
POINTE ON OMAHA DRIVE. T/R ON GOLD
COURT.
PREMISE # WAITING ON CUS

STRUCTURE: 000 000 60X50 SLAB 3BD/2BA W/GAR
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	11/08/10 11/08/10	MR AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002003598 T/S: 11/05/2010 12:00 PM VBROWN ----- T/S: 11/08/2010 09:45 AM MREARIC ----- #31584373
B114 01	11/12/10 11/12/10	MR AP	R*BLDG MONOLITHIC SLAB VRU #: 002005494 T/S: 11/12/2010 01:14 PM MREARIC -----
A814 01	11/24/10 11/24/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002011161 138 gold ct lot 92 roadway 27505----- T/S: 11/24/2010 10:41 AM TWARD -----
R425 01	11/30/10 11/29/10	TI CA	FOUR TRADE ROUGH IN VRU #: 002011179
R425 02	12/01/10	TI	FOUR TRADE ROUGH IN VRU #: 002012532

12-1-10 DA-MR

COMMENTS AND NOTES

*Leak under tub
Seal under both tubs
OK to side + ins.
Raise Stand Pipe box*

ADDRESS . . : 138 GOLD CT
CONTRACTOR : WYNN CONSTRUCTION, INC.
OWNER . . . : THE HARNETT LAND GROUP II LLC
PARCEL . . . : 03-9576- - -0088- -96-
APPL NUMBER: 10-50024774 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 07/07/2010 02:59 PM RDCONTE ---
138 GOLD COURT / TINGEN POINTE #92
TAKE 27W APPROX 11MI. T/L INTO TINGEN
POINTE ON OMAHA DRIVE. T/R ON GOLD
COURT.
PREMISE # WAITING ON CUS

SUBDIV: TINGEN POINTE PH 3B
PHONE : (919) 528-1347
PHONE :

STRUCTURE: 000 000 60X50 SLAB 3BD/2BA W/GAR

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	11/08/10 11/08/10	MR AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002003598 T/S: 11/05/2010 12:00 PM VBROWN ----- T/S: 11/08/2010 09:45 AM MREARIC ----- #31584373
B114 01	11/12/10 11/12/10	MR AP	R*BLDG MONOLITHIC SLAB VRU #: 002005494 T/S: 11/12/2010 01:14 PM MREARIC -----
A814 01	11/24/10 11/24/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002011161 138 gold ct lot 92 roadway 27505----- T/S: 11/24/2010 10:41 AM TWARD -----
R425 01	11/30/10 11/29/10	TI CA	FOUR TRADE ROUGH IN VRU #: 002011179
R425 02	12/01/10 12/01/10	MR DA	FOUR TRADE ROUGH IN VRU #: 002012532 T/S: 12/01/2010 11:40 AM MREARIC ----- leak under tub seal slab under tub raise washer box ok to side and insulate
I129 01	12/03/10	TI	R*INSULATION INSPECTION VRU #: 002014173
R425 03	<u>12-3-10</u> 12/03/10	DA-MR TI AP-MR DA-MR AP-MR	FOUR TRADE ROUGH IN VRU #: 002014165

COMMENTS AND NOTES

~~to~~
You must have 18"
above wiper on
stand pipe

OK NOW

ADDRESS : 138 GOLD CT SUBDIV: TINGEN POINTE PH 3B
CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
OWNER : THE HARNETT LAND GROUP II LLC PHONE :
PARCEL : 03-9576- - -0088- -96-
APPL NUMBER: 10-50024774 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 07/07/2010 02:59 PM RDCONTE ---
138 GOLD COURT / TINGEN POINTE #92
TAKE 27W APPROX 11MI. T/L INTO TINGEN
POINTE ON OMAHA DRIVE. T/R ON GOLD
COURT.
PREMISE # WAITING ON CUS

STRUCTURE: 000 000 60X50 SLAB 3BD/2BA W/GAR

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	11/08/10 11/08/10	MR AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002003598 T/S: 11/05/2010 12:00 PM VBROWN ----- T/S: 11/08/2010 09:45 AM MREARIC ----- #31584373
B114 01	11/12/10 11/12/10	MR AP	R*BLDG MONOLITHIC SLAB VRU #: 002005494 T/S: 11/12/2010 01:14 PM MREARIC -----
A814 01	11/24/10 11/24/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002011161 ✓ 138 gold ct lot 92 roadway 27505----- T/S: 11/24/2010 10:41 AM TWARD -----
R425 01	11/30/10 11/29/10	TI CA	FOUR TRADE ROUGH IN VRU #: 002011179
R425 02	12/01/10 12/01/10	MR DA	FOUR TRADE ROUGH IN VRU #: 002012532 T/S: 12/01/2010 11:40 AM MREARIC ----- leak under tub seal slab under tub raise washer box ok to side and insulate
I129 01	12/03/10 <u>12-3-10</u>	TI <u>AP-MR</u>	R*INSULATION INSPECTION VRU #: 002014173
R425 03	12/03/10 <u>12-3-10</u>	TI <u>AP-MR</u>	FOUR TRADE ROUGH IN VRU #: 002014165
H824 01	1/05/11 1/05/11	OT AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002026755 T/S: 01/06/2011 10:29 AM SZIMMER ----- T/S: 01/06/2011 10:30 AM SZIMMER -----
R429 01	1/14/11 <u>1-14-11</u>	TI <u>CA-MR</u>	FOUR TRADE FINAL VRU #: 002029023

COMMENTS AND NOTES

OK-except grading not Right

ADDRESS : 138 GOLD CT SUBDIV: TINGEN POINTE PH 3B
 CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
 OWNER : THE HARNETT LAND GROUP II LLC PHONE :
 PARCEL : 03-9576- - -0088- -96-
 APPL NUMBER: 10-50024774 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 07/07/2010 02:59 PM RDCONTE ---
 138 GOLD COURT / TINGEN POINTE #92
 TAKE 27W APPROX 11MI. T/L INTO TINGEN
 POINTE ON OMAHA DRIVE. T/R ON GOLD
 COURT.
 PREMISE # WAITING ON CUS

STRUCTURE: 000 000 60X50 SLAB 3BD/2BA W/GAR

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	11/08/10	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002003598
	11/08/10	AP	T/S: 11/05/2010 12:00 PM VBROWN ----- T/S: 11/08/2010 09:45 AM MREARIC ----- #31584373
B114 01	11/12/10	MR	R*BLDG MONOLITHIC SLAB VRU #: 002005494
	11/12/10	AP	T/S: 11/12/2010 01:14 PM MREARIC -----
A814 01	11/24/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002011161
	11/24/10	AP	✓ 138 gold ct lot 92 roadway 27505----- T/S: 11/24/2010 10:41 AM TWARD -----
R425 01	11/30/10	TI	FOUR TRADE ROUGH IN VRU #: 002011179
	11/29/10	CA	
R425 02	12/01/10	MR	FOUR TRADE ROUGH IN VRU #: 002012532
	12/01/10	DA	T/S: 12/01/2010 11:40 AM MREARIC ----- leak under tub seal slab under tub raise washer box ok to side and insulate
I129 01	12/03/10	TI	R*INSULATION INSPECTION VRU #: 002014173
	<u>12-3-10</u>	<u>AP-MR</u>	
R425 03	12/03/10	TI	FOUR TRADE ROUGH IN VRU #: 002014165
	<u>12-3-10</u>	<u>AP-MR</u>	
H824 01	1/05/11	OT	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002026755
	1/05/11	AP	T/S: 01/06/2011 10:29 AM SZIMMER ----- T/S: 01/06/2011 10:30 AM SZIMMER -----
R429 01	1/14/11	MR	FOUR TRADE FINAL VRU #: 002029023
	1/14/11	DA	T/S: 01/14/2011 10:07 AM MREARIC ----- all ok except grading on right side
R429 02	1/18/11	TI	FOUR TRADE FINAL VRU #: 002029460
	<u>1-18-11</u>	<u>AP-MR</u>	

COMMENTS AND NOTES

31584373

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: X Occupancy: X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: R-3

Permit Numbers

Name: Wynn Construction

Building: 10-56024774

Electrical: 11

Address: 138 Gold Ct.

Insulation: 11

Plumbing: 11

Mechanical: 1

MFG Home: _____

Date: 1-18-11

Building Official: T. Michael Ream