

ADDRESS : 349 CAROLINA OAKS CIR
 CONTRACTOR : BILL CLARK HOMES LLC
 OWNER : BILL CLARK HOMES LLC
 PARCEL : 01-0544- -0012- -54-
 APPL NUMBER: 11-50025967 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : CAROLINA OAKS # 54

SUBDIV: CAROLINA OAKS 64 LOTS
 PHONE : (252) 355-5805
 PHONE :

STRUCTURE: 000 000 59X34 3 BDR, 2 BTHS ATT GARAGE SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : SEPTIC

PROPOSED USE : RESIDENTIAL
 WATER SUPPLY : COUNTY

PERMIT: CPSF 01 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/04/11 3/04/11	JH DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002049245 1)Remove all stumps & roots from bottom of footing. 2)Missing step down boards.3)Footing is to be 12" from gradeto bottom of footing.
B101 02	3/08/11 3/08/11	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002050649 no T-pole
B103 01	3/10/11 3/10/11	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002052249 T-pole passed
A814 01	3/10/11 3/15/11	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002052231 349 carolina oaks cir lot 54 linden 28356 T/S: 03/15/2011 04:42 PM TWARD
P309 01	3/16/11 3/16/11	JH AP	R*PLUMB UNDER SLAB VRU #: 002054332
B111 01	3/18/11 3/18/11	DT AP	R*BLDG SLAB INSP/TEMP SVC POLE VRU #: 002055885
R425 01	4/12/11 4/12/11	JH DA	FOUR TRADE ROUGH IN VRU #: 002066114 1)100 psi on water line test. 2)Need receptacle within 6' from closet door in bed 2. 3)Strap pvc pipe in attic every 4'. 4)Need repair letter for D2G 2ply truss @ sidding doors.5)Nail all 2ply truss per drawings. 6)10 psi on gas lines.
R425 02	4/14/11 4/14/11	JH AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002066702 T/S: 04/12/2011 11:31 AM NTART T/S: 04/13/2011 09:36 AM NTART No permit card in box4 PM JHALL
I129 01	4/15/11 4/15/11	JH AP	R*INSULATION INSPECTION VRU #: 002067872 T/S: 04/15/2011 10:04 AM NTART
H824 01	5/06/11 5/06/11	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002077949 T/S: 05/09/2011 10:30 AM SZIMMER T/S: 05/09/2011 10:31 AM SZIMMER
R429 01	6/13/11 6/13/11	JH DA	FOUR TRADE FINAL VRU #: 002093219 HOUSE LOCKED CAN NOT DO FINAL INS
R429 02	6/15/11 6/15/11	JH DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 002094696 T/S: 06/14/2011 12:42 PM VBROWN 1)Need a carbon monoxide detector outside of master bedroom.2)Label AHU in attic.
R429 03	6/17/11 6/17/11	JH CA	FOUR TRADE FINAL TIME: 17:00 VRU #: 002096147 T/S: 06/16/2011 12:38 PM VBROWN PAUL FROM BILL CLARK HOMES REQUEST A PM INSP AFTER LUNCH.

PREPARED 6/20/11, 14:02:17
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 1
DATE 6/21/11

ADDRESS : 349 CAROLINA OAKS CIR
CONTRACTOR : BILL CLARK HOMES LLC
OWNER : BILL CLARK HOMES LLC
PARCEL : 01-0544- - -0012- -54-
APPL NUMBER: 11-50025967 CP NEW RESIDENTIAL (SFD)

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (252) 355-5805
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R429 04	6/21/11 <i>6/21/11</i>	TI <i>APD</i>	per Paul FOUR TRADE FINAL TIME: 17:00 VRU #: 002097574 T/S: 06/20/2011 12:52 PM JBROCK

COMMENTS AND NOTES

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: ___ Occupancy: X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Bill Clark Homes LLC

Address: 349 Carolina Oaks Cir
Linden, NC 28356

Date: 6/21/11

Building Official: [Signature]

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

11-500259167