



ADDRESS : 46 STONEHURST DR SUBDIV: STONE CROSS SECT 2 PH2A&B  
 CONTRACTOR : D.R. HORTON INC PHONE : (919) 460-2969  
 OWNER : DR HORTON INC PHONE : (919) 460-2933  
 PARCEL : 01-0535-14- -0100- -38-  
 APPL NUMBER: 11-50026927 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 06/16/2011 09:52 AM VBROWN ----  
 STONEHURST DRIVE, STONE CROSS #108.  
 210S, RIGHT ON OVERHILLS RD GO 4MI,  
 RIGHT ON COBBLESTONE DR, LEFT ON  
 STONEHURST DRIVE

STRUCTURE: 000 000 43X38 3BDR MONO W/ GARAGE  
 FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	2/19/13	MR	R*PLUMB UNDER SLAB VRU #: 002340065
	2/19/13	AP	T/S: 02/19/2013 11:49 AM MREARIC -----
A814 01	2/25/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002342913
	2/25/13	AP	46 STONEHURST DR LOT 108 SPRING LAKE 28390 T/S: 02/25/2013 12:47 PM TWARD -----
B114 01	2/25/13	MR	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 002342921
	2/25/13	AP	T/S: 02/25/2013 12:49 PM MREARIC -----
R425 01	3/28/13	DT	FOUR TRADE ROUGH IN VRU #: 002358174
	3/28/13	DA	T/S: 03/28/2013 10:19 AM DETAYLOR ----- BO3L truss not properly strapped for uplift on one side Front porch outlet wire not caulked at top plate in dining room Finish blocking/air barrier under master bedroom windows Okay to side do not insulate
R425 02	4/03/13	JH	FOUR TRADE ROUGH IN VRU #: 002359982
	4/03/13	DP	BLOCKING UNDER WINDOW IN MASTER BEDROOM NOT COMPLETE---- PAY \$50 RE FEE
R425 03	4/09/13	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002363307
	4/09/13	AP	-----
I129 01	4/10/13	JH	R*INSULATION INSPECTION VRU #: 002364040
	4/10/13	AP	-----
R125 01	4/17/13	JH	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002368306
	4/17/13	AP	STONE WIRE INSPECTION
			-----
H824 01	4/24/13	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002373330
	4/24/13	AP	T/S: 04/25/2013 11:21 AM SSTEWARD ----- T/S: 04/25/2013 11:22 AM SSTEWARD -----
R429 01	6/04/13	JH	FOUR TRADE FINAL TIME: 17:00 VRU #: 002391142
	6/04/13	DA	Support door threshold on door in garage. Repair hole in sheetrock to right of door in garage. Label dryer duct length per code.4)protect foundation insulation per code.
R429 02	6/07/13	TI	FOUR TRADE FINAL VRU #: 002393056

6-7-13 AP-MR

COMMENTS AND NOTES