

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: ___ Occupancy: X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Permit Numbers

Name: Jeffrey and Linda Jones

Building: 11-50027202

Electrical: 11-50027202

Address: 120 Wood Lake Drive

Insulation: 11-50027202

Fuquay Varina NC 27526

Plumbing: 11-50027202

Mechanical: 11-50027202

MFG Home: NANANANANANA

Date: 06-20-2012

Building Official: BSutton

ADDRESS : 90773 *UNASSIGNED SUBDIV:
 CONTRACTOR : STANTON HOMES INC. PHONE : (919) 278-8070
 OWNER : JONES JEFFERY & LINDA PHONE :
 PARCEL : 08-0645- - -0041- -08-
 APPL NUMBER: 11-50027202 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 07/21/2011 02:56 PM DJOHNSON --
 WOODLAKE LOT 4
 401 N TO RAWLS CH RD 2.5 RIGHT ON
 CHRISTIAN LIGHT RD 1.5 MILES RIGHT ON
 WOODLAKE DR LOT 4

STRUCTURE: 000 000 71X49 4BR CRAWL
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : WELL

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/14/11 9/14/11	BS AE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002136059 Approved pending engineers letter stating rebar in perimeter footing is not required. Engineering for soil problems is attached.
B103 01	10/25/11 10/25/11	BS AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 002152312 Install a sleeve drain through foundation at front (lowest) portion of foundation to allow water out of inside of foundation. Will check at open floor inspection
B105 01	11/18/11 11/18/11	KS DP	R*OPEN FLOOR VRU #: 002162519 Open floor inspection S: 11/18/2011 10:47 AM KSLATTUM ----- No plans in box. could not do inspection. \$50 re-inspection fee
A814 01	11/22/11 12/05/11	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002163558 120 WOOD LAKE DR FUQUAY VARINA 27526----- T/S: 12/05/2011 02:00 PM TWARD -----
B105 02	11/22/11 11/22/11	MR AP	R*OPEN FLOOR TIME: 17:00 VRU #: 002163566 T/S: 11/22/2011 12:19 PM MREARIC -----
R327 01	2/15/12 2/15/12	BS DP	THREE TRADE ROUGH IN >2500 VRU #: 002192754 This house has been completely bricked without any exterior inspections. All trades (framing, electrical, plumbing, and HVAC) must be roughed in, fire/draftstop done, baffles if needed, and no siding installed. 50.00 Reinspection fee. Find some other code approved method of wall bracing, and supply engineering that the windows are installed properly, flashed properly, and a complete membrane is covering structure, and the foundation/veneer line is properly flashed.
R327 02	2/17/12 2/17/12	BS DA	THREE TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002194165 1. Nail LVL hanger connection abovefront hall. 2. No water on DWV test. 3. Rodentproof all tubs/shower drains at first floor level. 4. Must have air barrier between tub and wall and at all kneewalls facing attic space. 5. All electrical feeders from main service must be 4 wire if feeding a panelboard. OK to insulate. See notes engineering and pictures in laserfische about this job

ADDRESS : 90773 *UNASSIGNED SUBDIV:
 CONTRACTOR : STANTON HOMES INC. PHONE : (919) 278-8070
 OWNER : JONES JEFFERY & LINDA PHONE :
 PARCEL : 08-0645- - -0041- -08-
 APPL NUMBER: 11-50027202 CP NEW RESIDENTIAL (SPD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E207 01	3/02/12 3/02/12	DT CA	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002198836 T/S: 03/01/2012 09:25 AM VBROWN ----- T/S: 03/02/2012 09:36 AM DETAYLOR -----
R427 01	3/02/12 3/02/12	DT DA	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002198828 T/S: 03/01/2012 09:24 AM VBROWN ----- T/S: 03/02/2012 09:38 AM DETAYLOR ----- PREVIOUS ITEM NUMBER 3 NOT CORRECTED. MUST SCHEDULE INSULATION INSPECTIONS ON HOUSE AND GARAGE
E207 02	3/06/12 3/06/12	DT AP	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002199974 T/S: 03/05/2012 10:06 AM VBROWN ----- T/S: 03/05/2012 10:06 AM VBROWN ----- PREMIS NUMMBER *****52764243***** T/S: 03/06/2012 10:16 AM DETAYLOR -----
I129 01	3/06/12 3/06/12	DT AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002199966 T/S: 03/05/2012 10:04 AM VBROWN ----- T/S: 03/06/2012 10:16 AM DETAYLOR -----
R427 02	3/06/12 3/06/12	DT AP	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002199958 T/S: 03/05/2012 10:04 AM VBROWN ----- T/S: 03/06/2012 10:16 AM DETAYLOR -----
P307 01	3/27/12 3/27/12	BS AP	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002207488 T/S: March 27, 2012 09:22 AM BSUTTON -----
HB24 01	5/01/12 5/01/12	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002222826 T/S: 05/02/2012 10:27 AM SZIMMER ----- T/S: 05/02/2012 10:28 AM SZIMMER -----
M305 01	5/08/12 5/08/12	BS AP	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 002224582 T/S: May 08, 2012 08:50 AM BSUTTON -----
R431 01	5/21/12 5/21/12	BS DA	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 002229086 1. Need receptacle at wallspace adjacent to master bedroom hallway. 2. Clean crawlspace and complete install of vapor barrier and seal all joints.
R431 02	6/20/12 <u>6-20-12</u>	TI <u>APB</u>	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 002241438 T/S: 06/18/2012 02:00 PM VBROWN ----- T/S: 06/18/2012 03:46 PM VBROWN -----

COMMENTS AND NOTES

Larkin Mephan
910-990-3725 Grace Ansel

Mike Hill
9

Chris Stevens

919-795-5042

John Strong