



ADDRESS : 265 CAROLINA OAKS CIR SUBDIV: CAROLINA OAKS 64 LOTS  
 CONTRACTOR : BILL CLARK HOMES LLC PHONE : (252) 355-5805  
 OWNER : BILL CLARK HOMES LLC PHONE :  
 PARCEL : 01-0544- - -0012- -53-  
 APPL NUMBER: 12-50028196 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 01/18/2012 09:41 AM JBROCK ----  
 TAKE 401 S OUT OF LILLINGTON TO ELLIOTT  
 BRIDGE RD GO R ELLIOTT BRIDGE RD TO  
 WILL LUCAS RD GO RIGHT INTO S/D  
 CAROLINA OAKS ON RIGHT TAKE CAROLINA  
 OAKS CIR TOWARD BACK LOT ION LEFT LOT  
 53

**STRUCTURE: 000 000 47X53 3BDR SLAB W/ GARAGE**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/14/12	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002192250
	2/14/12	AP	T/S: 02/13/2012 11:46 AM DJOHNSON FOOTING AND TSP INSPECTION AM INSPECTION BECAUSE CONCRETE ON FOR NOON
A814 01	2/21/12	TW	T/S: 02/14/2012 09:56 AM DETAYLOR ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002195055
	2/23/12	AP	265 CAROLINA OAKS CIR LOT 53 LINDEN 28356 T/S: 02/23/2012 05:07 PM TWARD
B103 01	2/21/12	JH	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002195048
	2/21/12	AP	
P309 01	2/24/12	JH	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002196541
	2/24/12	AP	
B111 01	3/01/12	JH	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002198213
	3/01/12	CA	T/S: 02/29/2012 01:29 PM DJOHNSON PER PAUL
P309 02	3/01/12	JH	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002198638
	3/01/12	CA	T/S: 02/29/2012 01:28 PM DJOHNSON PER PAUL
R427 01	3/26/12	DT	FOUR TRADE ROUGH IN >2500 VRU #: 002207141
	3/26/12	CA	T/S: 03/26/2012 11:05 AM DETAYLOR Per Paul
R425 01	3/28/12	DT	FOUR TRADE ROUGH IN VRU #: 002207971
	3/28/12	CA	T/S: 03/28/2012 01:07 PM DETAYLOR House not ready
R425 02	4/02/12	JH	FOUR TRADE ROUGH IN VRU #: 002209862
	4/02/12	DA	1)Missing anchor bolts in garage @ house door & water heater & right of window in living room omn back wall.2)Replace notched stud in garage @ bottom of stairs.3)Support trunk line in living room per code every 64".4)Need studs under top plate @ each end of master bath tub.5)Missing nail guards on wires @ top plate to left of master bath door.6)Fire caulk wires @ top plate in laundry room above light switch.7)Replace all short nails in roof truss hangers in bed2, hall & laundry room that are nailed

ADDRESS : 265 CAROLINA OAKS CIR SUBDIV: CAROLINA OAKS 64 LOTS  
CONTRACTOR : BILL CLARK HOMES LLC PHONE : (252) 355-5805  
OWNER : BILL CLARK HOMES LLC PHONE :  
PARCEL : 01-0544- - -0012- -53-  
APPL NUMBER: 12-50028196 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			into 2 ply truss.8)Missing hurricane straps on trusses A1, A2, A8, A9, A10 & A11 on garage wall & back wall.9)Need receptacle on front of house accessible from grade.
R425 03	4/04/12	JH	FOUR TRADE ROUGH IN VRU #: 002211403
	4/04/12	DP	Items # 5,6 & 9 were not corrected from previous violations
H824 01	4/09/12	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002213767
	4/09/12	AP	T/S: 04/10/2012 09:50 AM SZIMMER ----- T/S: 04/10/2012 09:51 AM SZIMMER -----
R425 04	4/10/12	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002213197
	4/10/12	AP	T/S: 04/09/2012 08:38 AM DJOHNSON -----
I129 01	4/13/12	JH	R*INSULATION INSPECTION VRU #: 002214810
	4/13/12	AP	-----
R429 01	6/12/12	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002238285
	<u>6-12-12</u>	<u>AP</u>	T/S: 06/11/2012 12:00 PM VBROWN -----

----- COMMENTS AND NOTES -----