

ADDRESS : 595 JUNO DR
CONTRACTOR : WYNN CONSTRUCTION, INC.
OWNER : THE HARNETT LAND GROUP II LLC
PARCEL : 03-9576-01- -0088- -32-
APPL NUMBER: 12-50029200 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 06/19/2012 01:12 PM JBROCK ----
HWY 27 W LEFT OMAHA DR LEFT ON JUNO LOT
128

SUBDIV: TINGEN POINTE PH 5 33LOTS
PHONE : (919) 528-1347
PHONE :

STRUCTURE: 000 000 50X55 3BDR MONO W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3000000.00
SEPTIC - EXISTING? : NEW TANK
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	1/29/13	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002331965
P309 01	1/29/13 <u>1-29-13</u>	TI <u>AP-MR</u>	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002331981

COMMENTS AND NOTES

#03152632

DAVID MILLER, PE
6300 Creedmoor Rd, STE 170#363
Raleigh, NC 27612
(919) 422-8932 (Office) ; DAVE@DMA-PA.COM

January 23, 2013

WYNN CONSTRUCTION
2550 CAPITAL DRIVE
SUITE 105
CREEDMOOR, NC 27522
E mailed to: jason@wynnconstruct.com ; Laurie@wynnconstruct.com

RE: Engineering – Field Observation
Lot 128 Tingen Point Subdivision
Fayetteville, NC
Job No.: 13DDM-0123B

To whom it may concern/ Inspections Dept.:

The undersigned arrived on-site 1-23-13 to observe and test the in-place fill conditions for the above referenced site. Based on the testing (Per ASTM Special publication 399) the fill materials (Tan silty sands (Unified Soil Classification System – SM)) were adequately compacted (95% Standard Proctor) and adequate to support the planned structure. Based on the observations and testing the bearing soils for the footings will provide adequate support.

Sincerely,

David Miller, PE

DEM/13DDM-0123B

