

**County of Harnett
Building Inspections Department
Planning Services**

Certificate of Compliance: _____ Occupancy: X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: Stancil Builders Inc

Address: 130 Alvis Ct
Fuquay Varina NC 27526

Date: 12-19-2012

Building Official: BSutton

Permit Numbers

Building: 12-50029455

Electrical: 12-50029455

Insulation: 12-50029455

Plumbing: 12-50029455

Mechanical: 12-50029455

MFG Home: NANANANANA

ADDRESS : 130 ALVIS CT
 CONTRACTOR : STANCIL BUILDERS INC.
 OWNER : ATKINS PLACE LLC
 PARCEL : 08-0653- - -0030- -45-
 APPL NUMBER: 12-50029455 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 07/25/2012 04:06 PM JBROCK ----
 401 S TOWARDS FUQUAY LEFT OB
 CHALYEBEATE RD DEXTERFIELD IS ON THE
 LEFT LOT 45

SUBDIV: DEXTERFIELD
 PHONE : (919) 639-2073
 PHONE :

STRUCTURE: 000 000 48X42 3BDR CRAWL W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00
 SEPTIC - EXISTING? : NEW
 PROPOSED USE : DWMH
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/11/12 9/11/12	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002276922 T/S: September 11, 2012 10:08 AM BSUTTON ----- Using a simple spring calibration pocket penetrometer. both lots checked at all locations at 2000# (code min) or better. Most checked higher. No water was observed, but some areas were over excavated.
B103 01	9/24/12 9/24/12	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002281925 T/S: September 24, 2012 12:34 PM BSUTTON -----
B105 01	10/04/12 10/04/12	BS AP	R*OPEN FLOOR VRU #: 002286760 T/S: October 04, 2012 09:39 AM BSUTTON -----
A814 01	10/18/12 10/24/12	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002292167 T/S: 10/17/2012 08:45 AM VBROWN ----- 130 alvis ct lot 45 fuquay varina 27526----- T/S: 10/24/2012 03:50 PM TWARD -----
R425 01	10/19/12 10/19/12	BS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002292795 T/S: 10/18/2012 10:18 AM VBROWN ----- T/S: October 19, 2012 09:55 AM BSUTTON ----- 1. Roof boots missing on plumbing. 2. Install kitchen window. 3. repair holes in housewrap 4. Gas test leaked down 5. Smoke detector needed outside master bedroom 6. Repair floor joist overnotched for master toilet. DO NOT SIDE/INSULATE.
R425 02	10/22/12 10/22/12	BS CA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002293629 T/S: 10/19/2012 12:32 PM VBROWN ----- ca - julie
R425 03	10/30/12 10/30/12	BS AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002296929 T/S: October 30, 2012 08:49 AM BSUTTON -----
I129 01	11/01/12 11/02/12	DT AP	R*INSULATION INSPECTION VRU #: 002298040 T/S: 11/02/2012 02:19 PM DETAYLOR -----
H824 01	11/06/12 11/06/12	BM AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002300499 T/S: 11/07/2012 10:52 AM SSTEWARD ----- T/S: 11/07/2012 10:52 AM SSTEWARD -----
R429 01	12/14/12 12/14/12	KS DA	FOUR TRADE FINAL VRU #: 002315992 i would like to meet you out there, call/text me 919-868-2515 with an approx time, thank! T/S: 12/14/2012 02:37 PM KSLATTUM ----- 1. No attic insulation. 2. No insulation card in attic.

ADDRESS : 130 ALVIS CT
CONTRACTOR : STANCIL BUILDERS INC.
OWNER : ATKINS PLACE LLC
PARCEL : 08-0653- - -0030- -45-
APPL NUMBER: 12-50029455 CP NEW RESIDENTIAL (SFD)

SUBDIV: DEXTERFIELD
PHONE : (919) 639-2073
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R429 02	12/19/12 <i>12-19-12</i>	TI <i>APK</i>	3. Need dead bolts on doors and bathroom doors. 4. decks shall be crossed braced. FOUR TRADE FINAL VRU #: 002317758 i want to meet you there on Wed, text me or call me with a time that i can get over to meet you please, 919-868-2515 thanks! Julie

COMMENTS AND NOTES

ADDRESS : 130 ALVIS CT
 CONTRACTOR : STANCIL BUILDERS INC.
 OWNER : ATKINS PLACE LLC
 PARCEL : 08-0653- - -0030- -45-
 APPL NUMBER: 12-50029455 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 07/25/2012 04:06 PM JBROCK -----
 401 S TOWARDS FUQUAY LEFT OB
 CHALYEBEATE RD DEXTERFIELD IS ON THE
 LEFT LOT 45

SUBDIV: DEXTERFIELD
 PHONE : (919) 639-2073
 PHONE :

73111

STRUCTURE: 000 000 48X42 3BDR CRAWL W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00
 SEPTIC - EXISTING? : NEW
 PROPOSED USE : DWMH
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/11/12 9/11/12	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002276922 T/S: September 11, 2012 10:08 AM BSUTTON ----- Using a simple spring calibration pocket penetrometer. both lots checked at all locations at 2000# (code min) or better. Most checked higher. No water was observed, but some areas were over excavated.
B103 01	9/24/12 9/24/12	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002281925 T/S: September 24, 2012 12:34 PM BSUTTON -----
B105 01	10/04/12 10/04/12	BS AP	R*OPEN FLOOR VRU #: 002286760 T/S: October 04, 2012 09:39 AM BSUTTON -----
A814 01	10/18/12 10/24/12	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002292167 T/S: 10/17/2012 08:45 AM VBROWN ----- 130 alvis ct lot 45 fuquay varina 27526----- T/S: 10/24/2012 03:50 PM TWARD -----
R425 01	10/19/12 10/19/12	BS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002292795 T/S: 10/18/2012 10:18 AM VBROWN ----- T/S: October 19, 2012 09:55 AM BSUTTON ----- 1. Roof boots missing on plumbing. 2. Install kitchen window. 3. repair holes in housewrap 4. Gas test leaked down 5. Smoke detector needed outside master bedroom 6. Repair floor joist overnotched for master toilet. DO NOT SIDE/INSULATE.
R425 02	10/22/12 10/22/12	BS CA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002293629 T/S: 10/19/2012 12:32 PM VBROWN ----- ca - julie
R425 03	10/30/12 10/30/12	BS AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002296929 T/S: October 30, 2012 08:49 AM BSUTTON -----
I129 01	11/01/12 11/02/12	DT AP	R*INSULATION INSPECTION VRU #: 002298040 T/S: 11/02/2012 02:19 PM DETAYLOR -----
H824 01	11/06/12 11/06/12	BM AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002300499 T/S: 11/07/2012 10:52 AM SSTEWARD ----- T/S: 11/07/2012 10:52 AM SSTEWARD -----
R429 01	12/14/12 <u>12-14</u>	TI <u>DA</u>	FOUR TRADE FINAL VRU #: 002315992 i would like to meet you out there, call/text me 919-868-2515 with an approx time, thank!

----- COMMENTS AND NOTES -----

ADDRESS . . : 130 ALVIS CT SUBDIV: DEXTERFIELD
CONTRACTOR : STANCIL BUILDERS INC. PHONE : (919) 639-2073
OWNER . . : ATKINS PLACE LLC PHONE :
PARCEL . . : 08-0653- - -0030- -45-
APPL NUMBER: 12-50029455 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 07/25/2012 04:06 PM JBROCK ----
401 S TOWARDS FUQUAY LEFT OB
CHALYEBEATE RD DEXTERFIELD IS ON THE
LEFT LOT 45

STRUCTURE: 000 000 48X42 3BDR CRAWL W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3000000.00 PROPOSED USE : DWMH
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/11/12 9/11/12	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002276922 T/S: September 11, 2012 10:08 AM BSUTTON ----- Using a simple spring calibration pocket penetrometer. both lots checked at all locations at 2000# (code min) or better. Most checked higher. No water was observed, but some areas were over excavated.
B103 01	9/24/12 9/24/12	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002281925 T/S: September 24, 2012 12:34 PM BSUTTON -----
B105 01	10/04/12 10/04/12	BS AP	R*OPEN FLOOR VRU #: 002286760 T/S: October 04, 2012 09:39 AM BSUTTON -----
A814 01	10/18/12 10/24/12	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002292167 T/S: 10/17/2012 08:45 AM VBROWN ----- 130 alvis ct lot 45 fuquay varina 27526----- T/S: 10/24/2012 03:50 PM TWARD -----
R425 01	10/19/12 10/19/12	BS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002292795 T/S: 10/18/2012 10:18 AM VBROWN ----- T/S: October 19, 2012 09:55 AM BSUTTON ----- 1. Roof boots missing on plumbing. 2. Install kitchen window. 3. repair holes in housewrap 4. Gas test leaked down 5. Smoke detector needed outside master bedroom 6. Repair floor joist overnotched for master toilet. DO NOT SIDE/INSULATE.
R425 02	10/22/12 10/22/12	BS CA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002293629 T/S: 10/19/2012 12:32 PM VBROWN ----- ca - julie
R425 03	10/30/12 10/30/12	BS AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002296929 T/S: October 30, 2012 08:49 AM BSUTTON -----
I129 01	11/01/12 <u>11/1/12</u>	TI <u>APDT</u>	R*INSULATION INSPECTION VRU #: 002298040

----- COMMENTS AND NOTES -----