

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: X Occupancy: X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: R-3

Name: H+H Constructors, INC

Address: 279 Executive Dr.

Permit Numbers

Building: 12-50029567

Electrical: 11

Insulation: 11

Plumbing: 11

Mechanical: 11

MFG Home:

Date: 4-18-13

Building Official: T. McLeod Reavis

ADDRESS : 279 EXECUTIVE DR SUBDIV: OAKMONT PHASE 1 SECT1
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTORS INC #18 PHONE : (910) 486-4804
 PARCEL : 03-0507- - -0046- -18-
 APPL NUMBER: 12-50029567 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 08/16/2012 03:39 PM DJOHNSON --
 27W TO DOCS RD LEFT GO ABOUT 1.5 MILES
 THEN LEFT INTO OAKMONT
 OAKMONT PHS 1 #18

STRUCTURE: 000 000 36X61 4BR ATT GARAGE PATIO PORCH SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/21/12	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002281459
	9/21/12	AP	T/S: 09/21/2012 12:39 PM MREARIC -----
A814 01	9/24/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002282119
	9/28/12	AP	279 EXECUTIVE DR LOT 18 LILLINGTON 27546----
			T/S: 09/28/2012 08:45 AM TWARD -----
B103 01	9/24/12	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002282101
	9/24/12	DA	T/S: 09/24/2012 01:43 PM MREARIC -----
			not ready
B103 02	9/26/12	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002283406
	9/26/12	AP	T/S: 09/26/2012 01:23 PM MREARIC -----
P309 01	10/11/12	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002289700
	10/11/12	AP	T/S: 10/11/2012 01:14 PM MREARIC -----
B111 01	10/16/12	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002291565
	10/16/12	DA	T/S: 10/15/2012 01:34 PM DJOHNSON -----
			T/S: 10/16/2012 10:15 AM MREARIC -----
			res-check is based on slab on grade... you have a stem-wall which must be insulated inside, R-10 , down to footer
B111 02	10/22/12	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002293744
	10/22/12	AP	T/S: 10/22/2012 01:50 PM MREARIC -----
			res check provided
P307 01	10/31/12	MR	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002297646
	10/31/12	AP	T/S: 10/31/2012 12:23 PM MREARIC -----
R425 01	12/14/12	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002316487
	12/14/12	DA	T/S: 12/14/2012 01:31 PM MREARIC -----
			leak under tub / need stud in 2nd fl. bath when over 24"
I129 01	12/18/12	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002317725
	12/18/12	CA	
R425 02	12/18/12	DT	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002317733
	12/18/12	CA	T/S: 12/18/2012 11:40 AM DETAYLOR -----
I129 02	12/20/12	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002319085
	12/20/12	AP	T/S: 12/20/2012 01:25 PM MREARIC -----
R425 03	12/20/12	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002319093
	12/20/12	AP	T/S: 12/20/2012 01:25 PM MREARIC -----
H824 01	1/22/13	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002330421
	1/22/13	AP	T/S: 01/23/2013 11:43 AM SSTEWARD -----
			T/S: 01/23/2013 11:43 AM SSTEWARD -----
E209 01	2/20/13	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002340891

ADDRESS : 279 EXECUTIVE DR SUBDIV: OAKMONT PHASE 1 SECT1
CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
OWNER : H & H CONSTRUCTORS INC #18 PHONE : (910) 486-4804
PARCEL : 03-0507- - -0046- -18-
APPL NUMBER: 12-50029567 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	2/20/13	AP	T/S: 02/20/2013 01:26 PM MREARIC -----
R429 01	4/04/13	MR	FOUR TRADE FINAL TIME: 17:00 VRU #: 002361111
	4/04/13	DP	T/S: 04/04/2013 03:12 PM MREARIC ----- 1. glazing over tub to be tempered 2. front window over garage needs fall protection device 3. energy cert. must have contractor name and be signed
R429 02	4/18/13 <u>4-18-13</u>	TI <u>AP-MR</u>	FOUR TRADE FINAL TIME: 17:00 VRU #: 002368678

----- COMMENTS AND NOTES -----

ADDRESS : 279 EXECUTIVE DR SUBDIV: OAKMONT PHASE 1 SECT1
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTORS INC #18 PHONE : (910) 486-4804
 PARCEL : 03-0507- - -0046- -18-
 APPL NUMBER: 12-50029567 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 08/16/2012 03:39 PM DJOHNSON --
 27W TO DOCS RD LEFT GO ABOUT 1.5 MILES
 THEN LEFT INTO OAKMONT
 OAKMONT PHS 1 #18

STRUCTURE: 000 000 36X61 4BR ATT GARAGE PATIO PORCH SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/21/12	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002281459
	9/21/12	AP	T/S: 09/21/2012 12:39 PM MREARIC -----
A814 01	9/24/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002282119
	9/28/12	AP	279 EXECUTIVE DR LOT 18 LILLINGTON 27546----
			T/S: 09/28/2012 08:45 AM TWARD -----
B103 01	9/24/12	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002282101
	9/24/12	DA	T/S: 09/24/2012 01:43 PM MREARIC -----
			not ready
B103 02	9/26/12	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002283406
	9/26/12	AP	T/S: 09/26/2012 01:23 PM MREARIC -----
P309 01	10/11/12	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002289700
	10/11/12	AP	T/S: 10/11/2012 01:14 PM MREARIC -----
B111 01	10/16/12	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002291565
	10/16/12	DA	T/S: 10/15/2012 01:34 PM DJOHNSON -----
			T/S: 10/16/2012 10:15 AM MREARIC -----
			res-check is based on slab on grade... you have a stem-wall which must be insulated inside, R-10 , down to footer
B111 02	10/22/12	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002293744
	10/22/12	AP	T/S: 10/22/2012 01:50 PM MREARIC -----
			res check provided
P307 01	10/31/12	MR	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002297646
	10/31/12	AP	T/S: 10/31/2012 12:23 PM MREARIC -----
R425 01	12/14/12	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002316487

12-14-12 DA-MR

COMMENTS AND NOTES

- 1) Leak under tub
- 2) Stud over 24" in bath 2nd Fl.

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DATE: 12/14/2012

PERMIT # 12-50029567

ADDRESS: 279 Executive

1. There appears to be a small leak from the tub on the 2nd fl.
..repair it and re-fill it and I will check it on the insulation
2. There is a stud missing (max 24")in the 2nd fl. Bathroom /
bedroom wall

Mike Rearic cell# (910) 984- 4772

ADDRESS : 279 EXECUTIVE DR SUBDIV: OAKMONT PHASE 1 SECT1
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE : (910) 486-4864
 OWNER : H & H CONSTRUCTORS INC #18 PHONE : (910) 486-4804
 PARCEL : 03-0507- - -0046- -18-
 APPL NUMBER: 12-50029567 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 08/16/2012 03:39 PM DJOHNSON --
 27W TO DOCS RD LEFT GO ABOUT 1.5 MILES
 THEN LEFT INTO OAKMONT
 OAKMONT PHS 1 #18

STRUCTURE: 000 000 36X61 4BR ATT GARAGE PATIO PORCH SLAB

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/21/12	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002281459
	9/21/12	AP	T/S: 09/21/2012 12:39 PM MREARIC -----
A814 01	9/24/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002282119
	9/28/12	AP	279 EXECUTIVE DR LOT 18 LILLINGTON 27546----
			T/S: 09/28/2012 08:45 AM TWARD -----
B103 01	9/24/12	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002282101
	9/24/12	DA	T/S: 09/24/2012 01:43 PM MREARIC ----- not ready
B103 02	9/26/12	MR	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002283406
	9/26/12	AP	T/S: 09/26/2012 01:23 PM MREARIC -----
P309 01	10/11/12	MR	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002289700
	10/11/12	AP	T/S: 10/11/2012 01:14 PM MREARIC -----
B111 01	10/16/12	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002291565
	10/16/12	DA	T/S: 10/15/2012 01:34 PM DJOHNSON ----- T/S: 10/16/2012 10:15 AM MREARIC ----- res-check is based on slab on grade... you have a stem-wall which must be insulated inside, R-10 , down to footer
B111 02	10/22/12	MR	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002293744
	10/22/12	AP	T/S: 10/22/2012 01:50 PM MREARIC ----- res check provided
P307 01	10/31/12	MR	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002297646
	10/31/12	AP	T/S: 10/31/2012 12:23 PM MREARIC -----
R425 01	12/14/12	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002316487
	12/14/12	DA	T/S: 12/14/2012 01:31 PM MREARIC ----- leak under tub / need stud in 2nd fl. bath when over 24"
I129 01	12/18/12	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002317725
	12/18/12	CA	
R425 02	12/18/12	DT	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002317733
	12/18/12	CA	T/S: 12/18/2012 11:40 AM DETAYLOR -----
I129 02	12/20/12	TI	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002319085
	<u>12.20.12</u>	<u>AP-MR</u>	
R425 03	12/20/12	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002319093
	<u>12.20.12</u>	<u>AP-MR</u>	

COMMENTS AND NOTES