

ADDRESS : 70 SHEPARD DR SUBDIV: KENLAN FARMS PH1SECT2
 CONTRACTOR : SAVVY HOMES, LLC PHONE : (919) 781-8104
 OWNER : ABJ INVESTMENTS LLC PHONE : (910) 485-5790
 PARCEL : 12-0555- - -0216- -67-
 APPL NUMBER: 12-50029778 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 09/20/2012 09:58 AM JBROCK ----
 210 TOWARDS FAYETTEVILLE TAKE LEFT AT
 MCNEILL HOBBS RD FOLLOW FOR ABOUT 4.5
 MILES TO R AT WIRE RD KENLAN S/D IS
 LOCATED APPROX 3.5 MILES ON THE R LOT
 63

STRUCTURE: 000 000 60X65 4BDR SLAB W/ GARAGE

FLOOD_ZONE : FLOOD_ZONE X
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/04/13	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002346443
	3/04/13	CA	PER DAVE
B101 02	3/05/13	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002346963
	3/05/13	AP	
B103 01	3/12/13	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 002350486
	3/12/13	AP	T_POLE PASSED
P309 01	3/22/13	JH	R*PLUMB UNDER SLAB VRU #: 002355584
	3/22/13	CA	PER DAVE
B111 01	3/26/13	DT	R*BLDG SLAB INSP/TEMP SVC POLE VRU #: 002356871
	3/26/13	CA	T/S: 03/26/2013 12:31 PM DETAYLOR Needed plumbing under slab insp
P309 02	3/26/13	TI	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002357879
A814 01	4/25/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002372498
	4/26/13	AP	70 shepard dr lot 63 linden 28356 T/S: 04/26/2013 09:38 AM TWARD
R425 01	4/25/13	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002372506
	4/25/13	DA	<ul style="list-style-type: none"> 1) Missing hanger on double I joist in garage. 2) Receptacle missing to left of pantry door. 3) Missing nails in I joist hangers @ bottom of stairs @ coat closet @ garage door. 4) Missing blocking on load point in pantry. 5) Missing air barrier on outside wall @ end of tub. 6) Nail osb on end wall in bed 2. 7) Replace damaged stud to right of back door. 8) Missing Nail guard on 2" pipe @ top plate above dryer. 9) Strap trusses A01GR & A01AGR in master bed & bed 4 per truss drawings. 10) Need correct set of rtuss drawings. 11) 10psi on gas line. DO NOT INSULATE
R425 02	4/30/13	TI	FOUR TRADE ROUGH IN VRU #: 002374569

4-30-13 *ACTH*

COMMENTS AND NOTES

ADDRESS : 70 SHEPARD DR SUBDIV: KENLAN FARMS PH1SECT2
 CONTRACTOR : SAVVY HOMES, LLC PHONE : (919) 781-8104
 OWNER : ABJ INVESTMENTS LLC PHONE : (910) 485-5790
 PARCEL : 12-0555- - -0216- -67-
 APPL NUMBER: 12-50029778 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 09/20/2012 09:58 AM JBROCK ----
 210 TOWARDS FAYETTEVILLE TAKE LEFT AT
 MCNEILL HOBBS RD FOLLOW FOR ABOUT 4.5
 MILES TO R AT WIRE RD KENLAN S/D IS
 LOCATED APPROX 3.5 MILES ON THE R LOT
 63

STRUCTURE: 000 000 60X65 4BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/04/13	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002346443
	3/04/13	CA	PER DAVE
B101 02	3/05/13	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002346963
	3/05/13	AP	
B103 01	3/12/13	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 002350486
	3/12/13	AP	T_POLE PASSED
P309 01	3/22/13	JH	R*PLUMB UNDER SLAB VRU #: 002355584
	3/22/13	CA	PER DAVE
B111 01	3/26/13	DT	R*BLDG SLAB INSP/TEMP SVC POLE VRU #: 002356871
	3/26/13	CA	T/S: 03/26/2013 12:31 PM DETAYLOR Needed plumbing under slab insp
P309 02	3/26/13	TI	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002357879
	<u>3-26-13</u>	<u>DT</u>	
A814 01	4/25/13	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002372498
	4/26/13	AP	70 shepard dr lot 63 linden 28356 T/S: 04/26/2013 09:38 AM TWARD
R425 01	4/25/13	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002372506
	4/25/13	DA	1)Missing hanger on double I joist in garage.2)Receptacle missing to left of pantry door.3)Missing nails in I joist hangers @ bottom of stairs @ coat closet @ garage door.4)Missing blocking on load point in pantry.5)Missing air barrier on outside wall @ end of tub.6)Nail osb on end wall in bed 2.Replace damaged stud to right of back door.8)Missing Nail guard on 2" pipe @ top plate above dryer.9)Strap trusses A01GR & A01AGR in master bed & bed 4 per truss drawings.10)Need correct set of rtuss drawings.11)10psi on gas line. DO NOT INSULATE
R425 02	4/30/13	JH	FOUR TRADE ROUGH IN VRU #: 002374569
	4/30/13	AP	
I129 01	5/03/13	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002376549
	5/03/13	CA	PER DAVE
I129 02	5/06/13	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002377281
	5/06/13	CA	T/S: 05/03/2013 03:17 PM VBROWN PER DAVE WIRES STOLEN ON SECOND FLOOR NEED TO REINSPECT

PREPARED 5/07/13, 14:04:02
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 18
DATE 5/08/13

ADDRESS : 70 SHEPARD DR
CONTRACTOR : SAVVY HOMES, LLC
OWNER : ABJ INVESTMENTS LLC
PARCEL : 12-0555- - -0216- -67-
APPL NUMBER: 12-50029778 CP NEW RESIDENTIAL (SFD)

SUBDIV: KENLAN FARMS PH1SECT2
PHONE : (919) 781-8104
PHONE : (910) 485-5790

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
--------	------------------------	----------------	---------------------------------

R125 01	5/08/13 <u>5-8-13</u>	TR <i>AA JV</i>	ELECTRIC ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002377703 ELE NEEDS TO BE FIX WERE IT WAS STOLEN
---------	--------------------------	--------------------	---

per [signature]
COMMENTS AND NOTES