

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: X **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: R-3

Name: Stancil Builders Inc.

Address: _____

 114 Humvee Ct.

Permit Numbers

Building: 13-50030743

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

Date: 9-17-15

Building Official: J. Michael Reovic

ADDRESS : 114 HUMVEE CT SUBDIV: PATTONS POINT PH 2 73LOTS
 CONTRACTOR : STANCIL BUILDERS INC. PHONE : (919) 639-2073
 OWNER : STANCIL BUILDERS INC PHONE :
 PARCEL : 03-9597- - -0225- -19-
 APPL NUMBER: 13-50030743 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 02/28/2013 09:34 AM JBROCK ----
 PATTONS POINTE S/D LOT 138

STRUCTURE: 000 000 57X29 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/07/15	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002614521
	1/07/15	AP	T/S: 01/07/2015 01:48 PM MREARIC -----
B103 01	1/27/15	TSG	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002621308
	1/27/15	AP	T/S: 01/26/2015 03:05 PM VBROWN -----
A814 01	1/28/15	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002621316
	1/27/15	AP	T/S: 01/26/2015 03:05 PM VBROWN ----- T/S: 01/27/2015 10:50 AM SBENNETT ----- 114 HUMVEE CT BROADWAY 27505 POST # ON HOME T/S: 01/27/2015 10:51 AM SBENNETT -----
B105 01	3/13/15	MR	R*OPEN FLOOR TIME: 17:00 VRU #: 002634244
	3/13/15	AP	T/S: 03/13/2015 01:29 PM MREARIC -----
R425 01	4/01/15	TSG	FOUR TRADE ROUGH IN VRU #: 002640887
	4/01/15	DA	1- NAIL OR STRAP PORCH BEAM COLOUM IN FRONT BEDROOM WALL 2- FIRE CAULK HOLE TOP PLATE OF WALL BETWEEN FRONT BEDROOM AND MIDDLE BATH. 3-LEFT SIDE BATH MISSING NAILER ON LEFT SIDE OF TUB/SHOWER UNIT 4- LEFT SIDE BATH HAS GAP IN FIRE CAULK LEFT SIDE TOP OF AIR BARRIER AT TOP PLATE. 5- LABEL DRYER DUCT LENGTH OK TO INSULATE OK TO SIDE
I129 01	4/07/15	MR	R*INSULATION INSPECTION VRU #: 002643125
	4/07/15	AP	T/S: 04/07/2015 01:18 PM MREARIC -----
H824 01	5/29/15	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002666691
	5/29/15	AP	T/S: 06/01/2015 11:09 AM SSTEWARD ----- T/S: 06/01/2015 11:09 AM SSTEWARD -----
R429 01	9/15/15	JH	FOUR TRADE FINAL VRU #: 002717796
	9/15/15	DA	1)Label dryer duct length per code.2)Remove temp water faucet at meter.
R429 02	9/17/15	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002719649

15 *AP-MR*

COMMENTS AND NOTES