

**COUNTY OF HARNETT**  
**Building Inspections Department**  
**Planning Services**

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: Cumberland Homes Inc

Address: 167 Gwendolyn Way

Fugary Virginia N.C. 27526

Date: 9-1-15

Building Official: [Signature]

**Permit Numbers**

Building: 14-50034665

Electrical: " "

Insulation: " "

Plumbing: " "

Mechanical: " "

~~MFG Home:~~ \_\_\_\_\_



ADDRESS : 167 GWENDOLYN WAY SUBDIV: BALLARD WOODS 4-B 21LOTS  
 CONTRACTOR : CUMBERLAND HOMES INC PHONE : (910) 892-4345  
 OWNER : NELSON THOMAS W & LORRAINE B PHONE :  
 PARCEL : 08-0652- - -0089- -31-  
 APPL NUMBER: 14-50034665 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 09/29/2014 09:54 AM VBROWN ----  
 167 GWENDOLYN WAY BALLARD WOODS SUB DIV  
 #145

**STRUCTURE: 000 000 62X64 3BDR 2BATH SFD W GAR PATIO**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/24/15	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002638104
	3/24/15	AP	T/S: March 24, 2015 09:21 AM BSUTTON -----
B103 01	4/07/15	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 002642938
	4/07/15	AP	T/S: April 07, 2015 08:51 AM BSUTTON ----- Insulation is incomplete at left rear and right rear. T/S: April 07, 2015 01:59 PM BSUTTON ----- Came back same day
P309 01	4/15/15	BS	R*PLUMB UNDER SLAB VRU #: 002646514
	4/15/15	AP	T/S: April 15, 2015 10:33 AM BSUTTON -----
B111 01	4/21/15	BS	R*BLDG SLAB INSP/TEMP SVC POLE VRU #: 002648843
	4/21/15	AP	T/S: April 21, 2015 03:32 PM BSUTTON -----
R425 01	5/26/15	BS	FOUR TRADE ROUGH IN VRU #: 002663068
	5/26/15	DA	T/S: May 26, 2015 11:32 AM BSUTTON ----- 1. Midstory guides missing on plumbing. 2. Nail strap to bottom plate/stud at left rear corner of master. 3. Repair air barriers at stairway. ok to side/insulate
I129 01	6/01/15	BS	R*INSULATION INSPECTION VRU #: 002665985
	6/01/15	AP	T/S: June 01, 2015 09:35 AM BSUTTON -----
R425 02	6/01/15	BS	FOUR TRADE ROUGH IN VRU #: 002665976
	6/01/15	AP	T/S: June 01, 2015 09:35 AM BSUTTON -----
A814 01	6/01/15	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002666162
	6/03/15	AP	167 GWENDOLYN WAY FUQUAY VARINA 27526 T/S: 06/03/2015 09:09 AM SBENNETT -----
R125 01	6/01/15	BS	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002666170
	6/01/15	AP	T/S: 05/29/2015 01:32 PM DJOHNSON ----- WIRE FOR STONE T/S: June 01, 2015 09:35 AM BSUTTON -----
H824 01	6/29/15	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002681641
	6/29/15	AP	T/S: 06/30/2015 12:29 PM SSTEWARD ----- T/S: 06/30/2015 12:29 PM SSTEWARD -----
E209 01	8/27/15	BS	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002709301
	8/27/15	AP	T/S: August 27, 2015 09:42 AM BSUTTON -----
R429 01	9/01/15	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002712115

9-1-15 APBS

COMMENTS AND NOTES