PREPARED 8/26/15, 14:13:12 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 8/27/15 ADDRESS : 121 STARLIGHT DR SUBDIV: NEW HORIZONS CONTRACTOR : PHONE : OWNER . . : BUCHANAN ROOFING INC PHONE : PARCEL . .: 13-0610- - -0107- -24-APPL NUMBER: 15-50036199 CP NEW RESIDENTIAL (SFD) DIRECTIONS : T/S: 05/20/2015 01:37 PM LBENNETT --HEAD NORTH ON HWY 421 TO TO COOL SPRINGS RD - TAKE RIGHT AND NEW HORIZONS WILL BE ON RIGHT LAND NOTES : LXMN 9/14/04 SPLIT FROM THE 10 PARCEL ______ STRUCTURE: 000 000 45X66 3BDR W/GARAGE CRAWL FLOOD ZONE . . . : FLOOD ZONE X # BEDROOMS : 3.00 PROPOSED USE SFD SEPTIC - EXISTING? . . . : NEW SEPTIC WATER SUPPLY : COUNTY ______ PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION TYP/SQ RESULT

----- COMMENTS AND NOTES -----

R*BLDG FOOTING / TEMP SVC POLE VRU #: 002709377

RESULTS/COMMENTS

COMPLETED

B101 01

Weston Lyall, PE, PLS, PLLC
214 Highway 17 N. Suite 1
Holly Ridge, NC 28445
910-329-9961 Office 910-329-9963 Fax
Firm License Number P-0937
www.WestonLyall.com

August 26, 2015

To: Buchanan Roofing Attn: Kevin Buchanan

121 Starlight Drive Lillington, NC

Subject: Concrete Footing Modification

The following deviations from the plan set issued by this office for the above referenced residence dated June 25, 2015 are considered acceptable:

- The grade beams and crawl space footings are noted as 10" thick on S-1 and S-2. The footing thickness can be reduced to 8". This will be acceptable at all footing locations.
- Per North Carolina State Building Code, in non-high wind zone areas, reinforcement is not required in any concrete footings. Since this site is not located in a high-wind zone it will be acceptable to not have reinforcing in the grade beam or interior crawl space footings.

A site visit has not been performed by this office to verify field conditions and all information was provided per the contractor.

Sincerely,

Weston Lyall, PE

All Your Engineering and Surveying Needs Licensed Engineer in NC, SC, VA, AL, MS Licensed Land Surveyor in NC