

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: Stancil Builders Inc

Address: 51 Hadleigh Way

 Fuquay Varina NC 27526

Date: 02/02/2016

Permit Numbers

Building: 15-50036330

Electrical: XXXXXXXXXXXXXXXXXXXXXXXX

Insulation: XXXXXXXXXXXXXXXXXXXXXXXX

Plumbing: XXXXXXXXXXXXXXXXXXXXXXXX

Mechanical: XXXXXXXXXXXXXXXXXXXXXXXX

 XXXXXXXX

Building Official: Brad Sutton

THE UNIVERSITY OF CHICAGO
DEPARTMENT OF CHEMISTRY
5800 S. UNIVERSITY AVENUE
CHICAGO, ILLINOIS 60637
TEL: 773-936-3700
FAX: 773-936-3701
WWW: WWW.CHEM.UCHICAGO.EDU

ADDRESS : 51 HADLEIGH WAY SUBDIV: HADDEN POINTE 40LOTS
 CONTRACTOR : STANCIL BUILDERS INC. PHONE : (919) 639-2073
 OWNER : STANCIL BUILDERS INC PHONE :
 PARCEL : 08-0652- - -0024- -19-
 APPL NUMBER: 15-50036330 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 06/04/2015 10:29 AM JBROCK ----
 HADDEN POINT #32

STRUCTURE: 000 000 39X42 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/15/15	BS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002688026
	7/15/15	AP	T/S: July 15, 2015 03:07 PM BSUTTON -----
B103 01	7/24/15	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 002693464
	7/24/15	AP	T/S: July 24, 2015 10:00 AM BSUTTON ----- Still no Tpole at site.
B105 01	8/10/15	KS	R*OPEN FLOOR VRU #: 002700483
	8/10/15	AP	T/S: 08/10/2015 01:10 PM KSLATTUM -----
A814 01	9/25/15	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002723153
	9/25/15	AP	51 HADLEIGH WAY FUQUAY VARINA 27526 T/S: 09/25/2015 10:11 AM SBENNETT -----
R425 01	9/25/15	KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002723195
	9/25/15	DA	T/S: 09/25/2015 01:54 PM KSLATTUM ----- 1. Need air barrier under stairs at fron wall. 2. Repair loose air barriers upstairs. 3. No air barrier behind upstairs tub. If installing vinyl on fron porch header, install house wrap. Ok to insulate
I129 01	10/01/15	BS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002725661
	10/01/15	AP	T/S: 09/30/2015 01:32 PM LBENNETT ----- T/S: October 01, 2015 01:58 PM BSUTTON -----
R425 02	10/01/15	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002725703
	10/01/15	AP	T/S: 09/30/2015 01:46 PM LBENNETT ----- T/S: October 01, 2015 01:58 PM BSUTTON -----
H824 01	11/18/15	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002743953
	11/18/15	AP	T/S: 11/19/2015 12:01 PM SSTEWARD ----- T/S: 11/19/2015 12:02 PM SSTEWARD -----
E209 01	1/12/16	BS	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002764165
	1/12/16	AP	T/S: 01/11/2016 12:53 PM DJOHNSON ----- T/S: January 12, 2016 12:43 PM BSUTTON -----
R429 01	2/02/16	TI	FOUR TRADE FINAL VRU #: 002772173

----- COMMENTS AND NOTES -----