

March 8, 2016

South Scan, Inc.  
3128 Gold Dust Lane  
Willow Spring, NC 27592

**RE: Existing Septic System Inspection HTE# 16-5-38077 – Woodshire Ph 4 Lt. 119**

To Whom It May Concern,

An attempt was made to evaluate your property for the purpose of issuing an Existing Tank Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Uncover outlet lid on septic tank and break seal (*\$25.00 fee incurred*)
- 2. Have system pumped out
- 3. Replace sanitary T
- 4. Other – Replace lid on septic tank. (Current lid has no handle)**

Your application will be put on hold until the selected items above have been addressed. When completed **call 893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Bryan McSwain, R.E.H.S.  
Environmental Health OSWW Program Specialist  
Harnett County Department of Public Health  
Environmental Health

BM/sgs  
Copy - Central Permitting