

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Weaver Development

Address: 14 Ringneck CT

Date: 10/31/16

Building Official: _____

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

500 39039

ADDRESS : 14 RINGNECK CT SUBDIV: THOMAS MANOR 36LOTS
 CONTRACTOR : WEAVER DEVELOPMENT CO INC PHONE : (910) 433-0888
 OWNER : WEAVER DEVELOPMENT COMPANY INC PHONE :
 PARCEL : 13-0630- - -0096- -24-
 APPL NUMBER: 16-50039039 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 06/27/2016 08:48 AM LBENNETT --
 HWY 421 N - LEFT ON NEILL THOMAS RD -
 RIGHT ON OLD 421 LEFT INTO THOMAS MANOR

STRUCTURE: 000 000 58X75 4BDR W/GARAGE W/DECK CRAWL

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	8/18/16	TSG	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002858975
	8/18/16	DA	not ready
B101 02	8/19/16	TSG	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002859890
	8/19/16	AP	
B103 01	8/29/16	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 002862852
	8/29/16	AP	T/S: 08/29/2016 03:13 PM MREARIC -----
A814 01	8/29/16	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002862878
	8/29/16	AP	14 RINGNECK CT LILLINGTON 27546 T/S: 08/29/2016 04:00 PM SBENNETT -----
B105 01	9/02/16	DT	R*OPEN FLOOR VRU #: 002865897
	9/02/16	AP	T/S: 09/02/2016 12:21 PM DETAYLOR -----
R425 01	9/20/16	TSG	FOUR TRADE ROUGH IN VRU #: 002873651
	9/20/16	DA	1-SEAL HOLE AND OPEN EDGE IN FIRE BLOCKING ABOVE FIREPLACE 2-NEED FIRE BLOCKING IN TOP OF CHASES SECOND FLOOR BATH AREA BESIDE TUB AND VANITY.3-SEAL AIR BARRIER AROUND SECOND FLOOR. 4-NEED HOUSE WRAP REPAIR LEFT AND RIGHT SIDE. OK TO INSULATE
I129 01	9/21/16	TSG	R*INSULATION INSPECTION VRU #: 002873990
	9/21/16	AP	
R425 02	9/21/16	TSG	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002874493
	9/21/16	AP	T/S: 09/20/2016 02:17 PM JFORBES -----
H824 01	10/04/16	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002881829
	10/04/16	AP	T/S: 10/05/2016 03:57 PM SSTEWARD ----- T/S: 10/05/2016 03:58 PM SSTEWARD ----- T/S: 10/05/2016 03:59 PM SSTEWARD ----- T/S: 10/05/2016 03:59 PM SSTEWARD -----
R429 01	10/28/16	MR	FOUR TRADE FINAL VRU #: 002890887
	10/28/16	DA	T/S: 10/28/2016 01:50 PM MREARIC ----- power approved booster pump needs separate breaker caulk around toilets support pump provide correct handrail on back porch
R329 01	10/31/16	TI	THREE TRADE FINAL VRU #: 002891554

----- COMMENTS AND NOTES -----