narnett	PREPARED 10/25/16, 14:16:17 Harnett County		TNORTH		PAGE 16 DATE 10/26/16
ADDRESS CONTRACT OWNER PARCEL APPL NUM DIRECTION	.: 226 MAF FOR: LYON BU .: KENNETH .: 13-0630 IBER: 16-5003 INS: T/S: 07 226 MAR LOT# 46	RVIN FERGUS UILDERS INC H CUMMINGS, 0002 39279 CP NE 7/21/2016 RVIN FERGUS	SON DR LLC 947- W RESIDENTIAL (SFI 03:49 PM LBENNET SON - MAMIE BELL R	רידיי _	74
FLOOD ZON # BEDROOM SEPTIC -	MS	52X55 3BDR V FLOOD ZONE	W/GARAGE W/DECK C E X 3.00 EW	PROPOSED USE	. : SFD . : COUNTY
	CPSF 00 CP * REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS	**************************************	
B101 01	10/24/16 10/24/16	MR	no plans	TEMP SVC POLE VRU #: 002 01:59 PM MREARIC	 2888063
B101 02	10/26/16	DP-(UV	T/5: 10/24/2016	on footer compaction TEMP SVC POLE TIME: 17:0 01:47 PM JBROCK	
		· 		ND NOTES	

NR

PREPARED 16/26/16, 14:59:30 Harnett County			INSPECTION TICKET INSPECTOR: IVR	PAGE DATE	1 10/27/16
OWNER PARCEL	E . : 226 MARVIN PTOR : LYON BUILDER : KENNETH CUMN : 13-0630 MBER: 16-50039279	RS INC MINGS, LLC -002947-	SUBDIV: PHONE : (919) 498-2074 PHONE : (910) 893-5826 FIAL (SFD)		10/2//16
DIRECTI	ONS : T/S: 07/21/2 226 MARVIN LOT# 46	016 03:49 PM FERGUSON - MAM	LBENNETT IE BELL RIDGE		
# BEDROO	RE: 000 000 62X55 DNE : FLOO. DMS	D ZONE X	PROPOSED USE	: SFD	
TYP/SQ	CPSF 00 CP * SFD REQUESTED INS COMPLETED RESU	ULT RESULTS/	TON	~	
	70/04/50	R*BLDG F T/S: 10/ no plans	OOTING / TEMP SVC POLE	3063 	
B101 02	10/26/16 MR 10/26/16 DP	R*BLDG F(T/S: 10/2 T/S: 10/2 T/S: 10/2	ineering on footer compaction DOTING / TEMP SVC POLE TIME: 17:00 24/2016 01:47 PM JBROCK 25/2016 12:55 PM LBENNETT 26/2016 08:58 AM MREARIC 1 not ready		
B101 03	10/27/16 TI 	R*BLDG FO T/S: 10/2	DOTING / TEMP SVC POLE TIME: 17:00 26/2016 02:59 PM DJOHNSON KE TSP LOOKED AT ALSO	VRU #: 002	890457

COMMENTS AND NOTES -----



¥ 919 773-1200 4 F 919 773-9454 69 Ship-rash Drive - Ga nor - North Carolina - 27529 ww=.tyndallengineering.com

October 24, 2016

C&C Services

Ph: (910) 850-2877 Fax: (910) 564-6633

Reference:

Engineering Services 226 Marvin Ferguson Dr. Lillington, North Carolina TE&D Project No. 1601-020466

To Whom It May Concern:

A representative of Tyndall Engineering & Design was onsite to visually observe and analyze foundation items for the above referenced project. Specifically, the following items listed were analyzed:

1) The conditions of the existing subgrade soils within the initial footing excavations.

The following conclusions and recommendations were presented for the abovementioned items:

1) Based on our observations and analyses, an area of soft and saturated soil conditions were encountered with the footing excavations along the left rear corner (facing house from front) of the proposed dwelling. The soft and saturated soils are to be over excavated to expose the underlying firm bearing soils. The depths of over excavation are estimated at approximately 12" to 18" in the majority of the repaired footing area. The over excavated area should be lined with a woven geo-textile and backfilled with washed stone to the proposed footing bearing elevation. The modified/repaired footing excavations will be adequate to support the anticipated loading conditions (i.e. 2000 psf design bearing pressure). The reader is referred to the attached diagram for supplemental information.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information please do not hesitate to contact us.

Sincerely,

Tyndall Engineering & Design, PA

Prentice A. Tyndall, Jr.

1601-020466

r 919 773 1300 = # 919 773 9456 69 Shipwach Drive = Garner = North Carolina = 27529 www.tyndellengmeering.com

	
JOB_ 1601-02046	6
LOCATION 226 Maria	erguson Dr
CALCULATED BY P. 7-1.	DATE 6/24 16
SHEET NO	OF Z
SCALE NIA	