

ECS Southeast, LLP 6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

## LETTER OF TRANSMITTAL

January 21, 2018

Canyon Stone 409 Northbrook Drive Youngsville, NC 27596

ATTN: Mr. Daniel Price

RE: Gatewest Drive (Lot 47)

ECS Job # 33:4272-A

Permits:

Location: Gatewest Drive

Bunnlevel, NC

We are enclosing:

X Field Reports

X For your use

X As requested

ENCL:

Field Report #1

01/17/2018

Stone Inspection

Dennis D Lowery, P.E.

Project Engineer

Ryan H. Parrish

Construction Materials Project Manager

- H. Parist





ECS Southeast, LLP

6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

Project

Gatewest Drive (Lot 47)

Location

Bunnlevel, NC

Client

Canyon Stone - Daniel Price

FIELD REPORT

Project No.

33:4272-A

Report No.

1

Day & Date

Wednesday 01/17/2018

Weather

34°/ Sunny

On-Site Time

Re Obs. Time

Lab Time 0.25

Travel Time\* 1.00

2.00

Total

0.00

0.75

Remarks

**Stone Inspection** 

Trip Charges\*

Tolls/Parking\*

Mileage\*

Time of

Arrival Departure

09:15A 08:30A

Chargeable Items

\* Travel time and mileage will be billed in accordance with the contract.

Summary of Services Performed (field test data, locations, elevations & depths are estimates) & Individuals Contacted.

ECS arrived onsite, as requested, to evaluate the installation of the previously installed manufactered stone veneer for the residential home located off Rugar Ct.

Based on today's observations, the installation of weather resistive barrier, metal lath, mortar scratch coat, and appropriate drainage systems were observed to be installed per the Canyon Stone installation guide and the 2012 North Carolina building code manual.

While onsite ECS also reached out to the general contractor to confirm mortar S was used during construction.

ECS will return upon request.

