PREPARED 12/01/17, 13:53:39 INSPECTION TICKET PAGE 42 INSPECTOR: IVR Harnett County DATE 12/04/17 ADDRESS . : 366 COTTLE LAKE DR SUBDIV: J L STONE CONTRACTOR : WJH LLC PHONE : (336) 282-3606 OWNER . . : MASTIN BAKER INVESTMENTS LLC PHONE : PARCEL . . : 07-0589- - -0102- -45-APPL NUMBER: 17-50042301 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 09/19/2017 09:02 AM JBROCK ----COTTLESTONE #41 210 S TAKE L ONTO S MAIN ST THEN R ONTO E FRONT ST \_\_\_\_\_ STRUCTURE: 000 000 40X49 4BDR 2.5BA MONO W/ GARAGE FLOOD ZONE . . . : FLOOD ZONE X # BEDROOMS . . . . . : 4000000.00 PROPOSED USE . . . . . : SFD SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY . . . . . . : COUNTY

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	11/27/17	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003057528
	11/27/17	AP	366 COTTLE LAKE DR COATS 27521
			T/S: 11/27/2017 11:26 AM SBENNETT
P309 01	11/28/17	DT	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 003057536
	11/28/17	AP	T/S: 11/27/2017 09:06 AM JBROCK
			T/S: 11/28/2017 12:08 PM DETAYLOR
B114 01	11/30/17	DT	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 003059250
	11/30/17	DA	T/S: 11/29/2017 09:51 AM JBROCK
			T/S: 11/30/2017 12:11 PM DETAYLOR
			Slab prep incomplete
B114 02	12/04/17	TI_ \	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 003060369
	12/4/17	AP DT	T/S: 11/30/2017 02:05 PM BPETRICH



PO Box 80755 Raleigh, NC 27623 (P) (919) 480-1075 (F) (866) 792-5107

Soil Suitability for Foundation Install Sealed Rep Client: Wack Jovey Date: 11.27.17 Project Number: BCH171682 Location: 41 Codd 1951006	ation - Field Report - port Forthcoming towes (Coats NC)	
Observations:		
JDS performed DCP and probe rod testing to verify	soil bearing conditions	s for the areas indicated below:
Basement	Front Porch	Other:
Crawl Space	Rear Porch / Patio	Omer.
Stem Wall	Deck	
Monolithic Slab	Garage	
	Carage	
Results:		
Test results indicate the soils are suitable for the mir	nimum required bearing	g pressure of:
1/		
2000 PSF	2500 PSF	3000 PSF
Over-excavation:  1 Ft to 2  Back Filled with: #57 #67	<b>-</b> Ft #78	DCP Min: 7 1955 MPRP: 2"  Solid Concrete
General Notes:		Right Side
*Bearing capacity test results are voided if significant precipitati initial testing.	ion or water intrusion has oc	curred within 48 hours of the
•IDS is not responsible for site conditions that divert water toware foundation that can lead to soft soils and future settlement.	ards the foundation or that pr	revent drainage away from the
•This report is assessment of vertical bearing capacity only. Unl slope stability analysis has been evaluated. JDS shall not be held related issues.		

•It is the contractors responsibility to ensure that all foundation areas are free of loose material, standing water, and any

1

•Concrete shall not be placed on to frozen ground or in to excavations containing ice or snow

other deleterious materials prior to placement of stone or concrete.