PAGE DATE

3/27/18

ADDRESS . : 1251 GRIFFIN RD SUBDIV:

CONTRACTOR : LYON BUILDERS INC

PHONE: (919) 498-2074

PHONE :

OWNER : LYON BUILDERS INC

APPL NUMBER: 17-50042656 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 10/30/2017 03:32 PM BPETRICH --

1251 GRIFFEN ROAD - NEST TO BOONE TRAIL

ELEMENTARY

APPL NOTES: BPMN 12/21/17 T/S: 12/21/2017 11:22 AM BPETRICH --HOUSE IS PERMITTED AS A 3 BD 2.5BA WITH AN UNFINISHED 2ND FLOOR. CUSTOMER WILL BE FINISHING UPSTAIRS EVENTUALLY MAKING A 5BD 3.5BA AND WILL PULL ALL PERMITS NEEDED AT THAT TIME. ORIGINAL IPAC WAS ISSUED FOR 5BD HOME AND WILL NOT NEED TO GO BACK THROUGH ENVIRONMENTAL.

STRUCTURE: 000 000 71X56 3BD 2.5BA MONO W/GAR UNFIN 2ND FLR

FLOOD ZONE . . . : FLOOD ZONE X

# BATHS . . . . . . . . . . . 2.5 PROPOSED USE . . . . . . . SFD

# BEDROOMS . . . . . . : SEPTIC - EXISTING? . . . : NEW TANK

WATER SUPPLY . . . . . : COUNTY

PERMIT: CPSF 00 CP * SFD			
	REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
A814 01	12/22/17	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003070117
	12/22/17	AP	1251 GRIFFIN RD LILLINGTON 27546
			T/S: 12/22/2017 09:54 AM SBENNETT
E205 01	1/11/18	TSG	R*ELEC UNDER SLAB TIME: 17:00 VRU #: 003075066
	1/11/18	AP	T/S: 01/10/2018 01:44 PM LLUCAS
P309 01	1/11/18	TSG	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 003075058
	1/11/18	AP	T/S: 01/10/2018 01:44 PM LLUCAS
B114 01	1/24/18	TSG	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 003079217
	1/24/18	AP	T/S: 01/23/2018 11:54 AM LLUCAS
E207 01	2/14/18	TSG	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 003088689
	2/14/18	AP	T/S: 02/13/2018 08:13 AM LLUCAS
R425 01	3/20/18	TSG	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003103090
	3/20/18	DA	天文S: 03/19/2018 09:56 AM LLUCAS
			1-air barrier required at stair /garage wall 2-caulk all
			hole in house/garage wall at joist area 3-a/b at exit doors
	•		each side 12" Afgryer vent max length 35' \$\mathcal{B}\$-complete all
			hvac duct and fire block and stop d-install midstory

straping on vent pipes. 7-need all 1vl cut sheets. 4-attach all interior load bearing walls. 9-strap all stud colums of 4 or more. A attach toilet flanges. The install all plumbing rest drain and supply.12-install rafter ties in main room.

ok to side

R425 02

FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003106515 T/S: 03/26/2018 01:47 PM BPETRICH -----

----- COMMENTS AND NOTES ------

## Mark E. Jones, PE Structural Engineering and Design

March 26, 2018

Chris Chambers 1251 Griffin Rd. Lillington, NC

Ref: Plan Item Clarification Personal Residence Plan DK2801

Plan DK2801

Project No. 17-220

To Whom it may concern;

The above referenced plan was reviewed on March 26, 2018 to address the following concerns:

1. Engineer to address need for collar ties at Family room ceiling/roof.

Based on observations and analysis, the conclusions regarding the structure are:

1. The cathedral ceiling in the family room is designed with a structural ridge beam (2-18" LVLs). No collar ties are required.

Thank you for this opportunity to assist you. If you have any questions or need any further assistance, please do not hesitate to the control of the control

Respectfully,

Mark E. Jones, PE