

ADDRESS : 2220 MATTHEWS RD
 CONTRACTOR :
 OWNER : SOUTHERN TOUCH HOMES LLC
 PARCEL : 11-0661- - -0029- -02-
 APPL NUMBER: 17-50042712 CP NEW RESIDENTIAL (SFD)

SUBDIV:
 PHONE :
 PHONE : (919) 524-3354

DIRECTIONS : T/S: 11/08/2017 11:25 AM DJOHNSON --
 210 TOWARDS ANGIER. TAKE LEFT ON
 MATTHEWS RD AND PROPERTY IS ON THE
 LEFT.

APPL NOTES : BPMN 1/16/18 T/S: 01/16/2018 01:35 PM BPETRICH --
 PREMISE 48088802 CALLED IN TEMP SVC
 1/16 BP

STRUCTURE: 000 000 57X47 4 BR 2.5 BATHS DECK GARAGE CRAWL

FLOOD ZONE : FLOOD ZONE X
 # BATHS : 2.5 # BEDROOMS : 4.00
 PROPOSED USE : SFD SEPTIC - EXISTING? : NEW
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

| TYP/SQ | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS |
|---------|------------------------|----------------|---|
| A814 01 | 12/12/17 | TW | ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003064607 |
| | 12/12/17 | AP | 2220 Matthews Rd Lillington 27546 |
| | | | T/S: 12/12/2017 09:24 AM TWARD ----- |
| B101 01 | 12/12/17 | KS | R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003064599 |
| | 12/12/17 | AP | T/S: 12/11/2017 08:28 AM BPETRICH ----- |
| | | | T/S: 12/12/2017 12:03 PM KSLATTUM ----- |
| B103 01 | 12/20/17 | DT | R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 003068822 |
| | 12/20/17 | AP | T/S: 12/19/2017 09:33 AM BPETRICH ----- |
| | | | TPOLE ALSO |
| | | | T/S: 12/20/2017 04:30 PM DETAYLOR ----- |
| B111 01 | 1/17/18 | DT | R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 003077005 |
| | 1/19/18 | DA | T/S: 01/16/2018 01:35 PM BPETRICH ----- |
| | | | T/S: 01/19/2018 03:56 PM DETAYLOR ----- |
| | | | Slab prep incomplete |
| P309 01 | 1/24/18 | MC | R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 003078862 |
| | 1/24/18 | AP | T/S: 01/22/2018 02:22 PM JBROCK ----- |
| | | | T/S: 01/24/2018 02:05 PM MCOOK ----- |
| B111 02 | 1/30/18 | DT | R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 003081833 |
| | 1/30/18 | AP | T/S: 01/26/2018 12:28 PM DJOHNSON ----- |
| | | | WOULD LIKE INSPECTION AFTER LUNCH IF POSSIBLE |
| | | | T/S: 01/30/2018 03:31 PM DETAYLOR ----- |
| R425 01 | 3/09/18 | MC | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003098852 |
| | 3/09/18 | DA | T/S: 03/07/2018 11:08 AM BPETRICH ----- |
| | | | AM INSPECTION REQUESTED |
| | | | T/S: 03/09/2018 12:10 PM MCOOK ----- |
| | | | 1.patch hole under window front porch 2. missing install window left side 3. missing fie/draft stop all electrical 4. missing 3sc at middle dormers both sides 5. install gaurds rails at stairs 6. missing air barrier at stairs at wall wher return installed 7. missing 5sc each side garage door 8. ? 3-2x10 at porch beam header each end porch 9. install fireplace and hook-up |

 ADDRESS . : 2220 MATTHEWS RD SUBDIV:
 CONTRACTOR : PHONE :
 OWNER . . : SOUTHERN TOUCH HOMES LLC PHONE : (919) 524-3354
 PARCEL . . : 11-0661- - -0029- -02-
 APPL NUMBER: 17-50042712 CP NEW RESIDENTIAL (SFD)

| TYP/SQ | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS |
|---------|---------------------|-------------|--|
| R425 02 | 3/13/18 | MC | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003100708 |
| | 3/13/18 | DA | T/S: 03/12/2018 11:29 AM JBROCK ----- T/S: 03/13/2018 01:47 PM MCOOK ----- 1. still missing 3sc at middle dormer ok to insulate and side |
| I129 01 | 3/16/18 | MC | R*INSULATION INSPECTION TIME: 17:00 VRU #: 003102266 |
| | 3/16/18 | DA | T/S: 03/15/2018 12:21 PM DJOHNSON ----- T/S: 03/16/2018 03:52 PM MCOOK ----- 1. install ok but rough-ins not signed off |
| R425 03 | 3/16/18 | MC | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003102258 |
| | 3/16/18 | DA | T/S: 03/15/2018 12:21 PM DJOHNSON ----- T/S: 03/16/2018 03:55 PM MCOOK ----- insulation install ok , missing front door |
| I129 02 | 3/28/18 | MC | R*INSULATION INSPECTION TIME: 17:00 VRU #: 003107398 |
| | 3/28/18 | DA | T/S: 03/27/2018 01:54 PM JBROCK ----- T/S: 03/28/2018 01:37 PM MCOOK ----- 1. previous not corrected |
| R425 04 | 3/28/18 | MC | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003107406 |
| | 3/28/18 | DA | T/S: 03/27/2018 01:54 PM JBROCK ----- T/S: 03/28/2018 01:38 PM MCOOK ----- 1. front door covered up with siding not able to properly inspect |
| H824 01 | 4/19/18 | AC | ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 003117033 |
| | 4/19/18 | AP | T/S: 04/20/2018 11:09 AM KHINSON ----- T/S: 04/20/2018 11:09 AM KHINSON ----- |
| E209 01 | 5/17/18 | DT | R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 003128600 |
| | 5/17/18 | AP | T/S: 05/16/2018 10:03 AM BPETRICH ----- T/S: 05/17/2018 03:59 PM BPETRICH ----- |
| I129 03 | 5/17/18 | MC | R*INSULATION INSPECTION TIME: 17:00 VRU #: 003128584 |
| | 5/17/18 | AP | T/S: 05/16/2018 10:03 AM BPETRICH ----- T/S: 05/17/2018 08:18 AM MCOOK ----- |
| R425 05 | 5/17/18 | MC | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003128592 |
| | 5/17/18 | AP | T/S: 05/16/2018 10:03 AM BPETRICH ----- T/S: 05/17/2018 08:18 AM MCOOK ----- |
| R429 01 | 6/01/18 | TI | FOUR TRADE FINAL TIME: 17:00 VRU #: 003134640 |
| | | | T/S: 06/01/2018 09:51 AM LLUCAS ----- |

----- COMMENTS AND NOTES -----