

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: Wynn Construction Inc

Address: 38 Education Dr

Spring Lake NC 28390

Date: 5.25.18

Building Official: B. [Signature]

Permit Numbers

Building: 17-5-42786

Electrical: " "

Insulation: " "

Plumbing: " "

Mechanical: " "

MEG Home: _____

ADDRESS . : 38 EDUCATION DR SUBDIV: ACADEMY@ACC PH 7 50LOTS
 CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
 OWNER . . : WYNN CONSTRUCTION INC PHONE :
 PARCEL . . : 01-0535-25- -0100- -27-
 APPL NUMBER: 17-50042786 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 11/20/2017 11:02 AM JBROCK ----
 ANDERSON CREEK ACADEMY #1084

STRUCTURE: 000 000 51.2X46.9 4BDR 3.5BA SLAB W/ GARAGE
 FLOOD ZONE : FLOOD ZONE X
 # BATHS : 3.5 # BEDROOMS : 4000000.00
 PROPOSED USE : SFD SEPTIC - EXISTING? : SEWER
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	12/12/17 12/12/17	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003064672 38 EDUCATION DR SPRING LAKE 28390 LOT 1084 T/S: 12/12/2017 10:00 AM TWARD ----- T/S: 12/12/2017 10:01 AM TWARD -----
B101 01	12/12/17 12/12/17	JH CA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003064664 T/S: 12/11/2017 09:13 AM BPETRICH ----- T/S: 12/11/2017 09:13 AM BPETRICH ----- PER CRAIG -----
B101 02	12/14/17 12/14/17	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003066537 T/S: 12/13/2017 11:57 AM BPETRICH ----- NO T-POLE -----
B103 01	1/03/18 1/03/18	TSG AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 003072279 T/S: 12/29/2017 03:43 PM LLUCAS ----- T/S: 01/03/2018 02:14 PM SGUY -----
E207 01	1/12/18 1/12/18	JH AP	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 003075082 T/S: 01/10/2018 01:51 PM LLUCAS ----- CRAIG WITH WYNN SAID T-POLE WAS UP AT FOUNDATION BUT NOT CHECKED -----
M305 01	1/23/18 1/23/18	JH AP	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 003079043 T/S: 01/23/2018 10:20 AM JBROCK -----
P307 01	1/23/18 1/23/18	JH AP	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 003079068
P309 01	1/23/18 1/23/18	JH AP	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 003079076
B111 01	1/25/18 1/25/18	JH DA	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 003079605 T/S: 01/23/2018 04:03 PM BPETRICH ----- NEED COMPACTION TEST FOR SLAB -----
B111 02	2/01/18 2/01/18	JH AP	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 003083599 T/S: 01/31/2018 10:52 AM LLUCAS -----
B104 01	2/09/18 2/09/18	JB AP	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 003087798 T/S: 02/09/2018 09:59 AM JBROCK -----
R425 01	3/09/18 3/09/18	JH CA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003099546 T/S: 03/08/2018 10:04 AM BPETRICH ----- PER CRAIG -----
R425 02	3/12/18 3/12/18	JH CA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003100286 T/S: 03/09/2018 11:35 AM BPETRICH -----

 ADDRESS . : 38 EDUCATION DR SUBDIV: ACADEMY@ACC PH 7 50LOTS
 CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
 OWNER . . : WYNN CONSTRUCTION INC PHONE :
 PARCEL . . : 01-0535-25- -0100- -27-
 APPL NUMBER: 17-50042786 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			PER CRAIG
R425 03	3/14/18	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003100807
	3/14/18	DP	T/S: 03/12/2018 12:42 PM JBROCK ----- 1)Missing nuts & washers on garage wing walls.2)Insulate traps in garage ceiling.3)Missing air barriers in chase in back right corner of garage.4)3-2x10 header over back door per plans.5)Ballon frame back wall in living room 12" oc per plans.6)Missing 3 studs in master bedroom behind fire box under lvl per plans.7)Nail osb on end wall in master bedroom.8)Anchor all interior load bearing walls per code.9)2x10 header corner to corner per plans for opening at dining room with 2 jack studs each end per plans.10)Add studs at front door for dining room header 3 studs per plans.11)Support loose wires under stairs per code.12)Missing house wrap over garage door.
			NO INSULATION
R425 04	3/16/18	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003102217
	3/16/18	AP	T/S: 03/15/2018 11:46 AM BPETRICH -----
I129 01	3/20/18	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 003103140
	3/20/18	AP	T/S: 03/19/2018 10:26 AM BPETRICH -----
R125 01	4/11/18	JH	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 003113123
	4/11/18	AP	T/S: 04/10/2018 01:38 PM BPETRICH ----- STONE PREP
E209 01	5/03/18	JH	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 003122124
	5/03/18	AP	T/S: 05/01/2018 02:45 PM LLUCAS -----
R429 01	5/23/18	MC	FOUR TRADE FINAL TIME: 17:00 VRU #: 003130838
	5/23/18	DA	T/S: 05/22/2018 01:06 PM BPETRICH ----- T/S: 05/23/2018 03:25 PM MCOOK ----- 1. install anti-tip device on stove
R429 02	5/25/18	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 003131653
			T/S: 05/23/2018 02:08 PM BPETRICH -----

 COMMENTS AND NOTES
