

ADDRESS : 127 EDUCATION DR SUBDIV: ACADEMY@ACC PH 7 50LOTS
 CONTRACTOR : WYNN CONSTRUCTION, INC. PHONE : (919) 528-1347
 OWNER : WYNN CONSTRUCTION INC PHONE :
 PARCEL : 01-0535-25- -0100- -42-
 APPL NUMBER: 18-50043488 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 03/07/2018 10:45 AM JBROCK ----
 ANDERSON CREEK CROSSING #1098

STRUCTURE: 000 000 51.2X46.8 4BDR 2BA W/GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BATHS : 3 # BEDROOMS : 4000000.00
 PROPOSED USE : SFD SEPTIC - EXISTING? : SEWER
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	5/10/18 5/10/18	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003125739 127 EDUCATION DR SPRING LAKE 28390 T/S: 05/10/2018 04:11 PM SBENNETT -----
B101 01	5/10/18 5/10/18	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003125747 T/S: 05/09/2018 12:12 PM LLUCAS ----- no t-pole
B103 01	5/29/18 5/29/18	JH AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 003132560 T/S: 05/25/2018 10:48 AM DJOHNSON ----- TSP ALSO T-POLE PASSED
B105 01	6/05/18 6/05/18	JH AP	R*OPEN FLOOR TIME: 17:00 VRU #: 003135126 T/S: 06/04/2018 09:29 AM JBROCK -----
B104 01	7/03/18 7/03/18	BP AP	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 003147782 T/S: 07/03/2018 01:11 PM BPETRICH ----- T/S: 07/03/2018 01:11 PM BPETRICH -----
R425 01	7/05/18 7/05/18	JH DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003147790 T/S: 07/03/2018 01:11 PM BPETRICH ----- 1) Missing chase for duct in back left corner of garage. 2) Fire caulk wires in top plate on right side of garage, dryer wire 3) Missing nail guards at top plate on wires in half bath, bottom plate in master bath closet to right of window & top plate front right bath to right of door 4) 3-2x10 header over back door per plans. 5) Plans claa for 3-2x6 headers for ballon frame walls in living room. 6) Missing air barriers in chases at dining room archway & front wall in foyer archway. 7) 3-2x8 headers over front door per plans. 8) Need compaction letter for fill on front porch. OK TO SIDE DO NOT INSULATE
R425 02	7/10/18 <u>7-10-18</u>	TI <u>AP JV</u>	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 003149580 T/S: 07/09/2018 11:50 AM DJOHNSON -----

COMMENTS AND NOTES

** Jimmy **

DAVID MILLER, PE

6300 Creedmoor Rd, STE 170#363
Raleigh, NC 27612
(919) 422-8932 (Office); DAVE@DMA-PA.COM

July 5, 2018

WYNN CONSTRUCTION
2550 CAPITAL DRIVE
SUITE 105
CREEDMOOR, NC 27522

E-mailed to: jason@wynnhomes.com ; keith@wynnconstruct.com ;
cdunham@wynnhomes.com
Craig Dunham 910-988-5691

RE: Engineering - Foundation
Lot 1098 Anderson Creek Crossing Subdivision
Lillington, NC
Project No.: 18DDM-0705C

To whom it may concern/ Inspections Dept.:

The undersigned has analyzed the plans and observed the washed stone filled porch conditions. Based on the analysis of the washed stone fill and the loading conditions for the porch the washed stone fill is adequately placed to provide adequate support for the loading conditions.

Sincerely,

David Miller, PE

DEM/18DDM-0705C

DocuSigned by:



AED026D4715F40



7/5/2018 9:34:50 AM PDT