

т 919 773-1200 = F 919 773-9658

250 Shipwash Drive, Suite 104 - Garner - North Carolina - 27529 www.tyndallengineering.com

October 15, 2018

Matthew Brown 139 Fulton Lane Lillington, NC 27546

Ph: 919-795-1630

Email: m s brown1988@yahoo.com

Reference: Brown Residence

Project No.: 1801-010150

This letter is to address framing changes to the above referenced plans. The roof and ceiling will now be framed with roof trusses bearing on the exterior walls only. Ceiling joists and beams previously shown on the plans are no longer required. All exterior header sizes remain unchanged. Since there will no longer be any interior load bearing walls, a thickened slab footing is no longer required under any interior walls.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely,

Tyndall Engineering & Design

Prentice A. Tyndall Jr., P.E.

PAT/1801-010150

SE, 02489.