

Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner:
Address:
Proposed Facility:
Location of Site:
Water Supply: ☐ Public ☐ Individual ☐ Well
Evaluation Method: ☐ Auger Boring ☐ Pit
Type of Wastewater: ☐ Sewage ☐ Industrial Process

Applicant:
Date Evaluated:
Property Size:
Property Recorded: ☐ Spring ☐ Other
☐ Cut ☐ Mixed

	1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY 1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			1941 Structure/ Texture	1941 Consistence Mineralogy	1942 Soil Wetness/ Color	1943 Soil Depth (IN.)	1956 Sapro Class	1944 Restr Horiz	
1	L 4%	0-24	SC CLAY	SL FINE SBR SS-P	16" 7.5yR 6.2				
2	L 3%	0-30	SL	FL GR NBP					4
		31-48	SL	FL GR NBP					
				SL FINE MSA SS-P	40" 7.5yR 6.2				
3	L 3%	0-16	SL	FL GR NBP					3
		16-42	SL	SL FINE SBR SS-P	30 7.5yR 6.2				
4	L 3%	0-12	SL	FL GR NBP					3
		12-36	SL	SL FINE SBR SS-P	30 7.5yR 6.2				

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	✓	✓
Site LTAR	-3	-3

Other Factors (.1946): _____
Site Classification (.1948): _____
Evaluated By: _____
Others Present: _____

COMMENTS:

LANDSCAPE POSITIONS

R-RIDGE
S-SHOULDER SLOPE
L-LINEAR SLOPE
FS-FOOT SLOPE
N-NOSE SLOPE
H-HEAD SLOPE
CC-CONCLAVE SLOPE
CV-CONVEX SLOPE
T-TERRACE
FP-FLOOD PLAN

GROUP

I

TEXTURES

S-SAND
LS-LOAMY SAND

.1955 LTAR

1.2 - 0.8

CONSISTENCE MOIST

VFR-VERY FRIABLE
FR-FRIABLE
FI-FIRM
VFI-VERY FIRM
EFI-EXTREMELY FIRM

WET

NS-NON-STICKY
SS-SLIGHTLY STICKY
S-STICKY
VS-VERY STICKY
NP-NON-PLASTIC
SP-SLIGHTLY STICKY
P-PLASTIC
VP-VERY PLASTIC

II

SL-SANDY LOAM
L-LOAM

0.8 - 0.6

III

SI-SILT-
SIL-SILT LOAM
CL-CLAY LOAM
SCL-SANDY CLAY LOAM
SICL-SILTY CLAY LOAM

0.6 - 0.3

IV

SIC-SILTY CLAY
C-CLAY
SC-SANDY CLAY

0.4 - 0.1

STRUCTURE


SG-SINGLE GRAIN
M-MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY
PR-PRISMATIC

MINERALOGY

SLIGHTLY EXPANSIVE

EXPANSIVE


Show profile locations and other site features (dimensions, reference or benchmark, and North).



ZONING ADMINISTRATOR

Mark Blalock

Personal
Workshop / storage



- possible driveway

How many people
2000.00?

February 17, 2005