

February 16, 2017

Keith Stewart  
40 Bill Avery Road  
Coats, NC 27521

**RE: Existing Septic System Inspection HTE# 17-5-40652**

Dear Mr. Stewart,

An attempt was made to evaluate your property for the purpose of issuing an Existing Tank Permit. The evaluation could not be completed for one or more of the following reasons.

**1. Uncover outlet lid on septic tank and break seal (\$25.00 fee incurred)**

2. Have system pumped out

3. Replace sanitary T

**4. Other - Concrete was exposed but the lid had not been lifted up breaking the seal, keep lid closed after breaking seal.**

Your application will be put on hold until the selected items above have been addressed. When completed **call 893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



James E. Manhart, III, R.E.H.S.  
Environmental Health OSWW Program Specialist  
Harnett County Department of Public Health  
Environmental Health

/sgs

Copy - Central Permitting