

DEPARTMENT OF PUBLIC HEALTH-

TELEPHONE: 910-893-7550 FAX: 910-893-9429 A. WAYNE RAYNOR, MPH DIRECTOR

July 15, 2002

To Whom It May Concern:

The septic system at lot 77 Starwood appears to be in a condition to function as designed. The settling of soils around the septic tank/pump chamber should have no affect on the performance of the septic system. Settling of soil around a septic tank is normal and should not be considered a defect. The problem has been corrected by adding soil and packing the soil around the tank.

Sincerely,

Joe West, R.S.

Environmental Health Specialist