

April 10th, 2019

Stacy Avery
4810 NC 55 E
Erwin, NC 28339

RE: Repair Application # EH1903-0011

Mr. Avery,

An attempt was made to evaluate your property for the purpose of issuing a repair permit. The evaluation could not be completed for one or more of the following reasons.

___ 1. Uncover Outlet lid on septic tank and break seal (\$25.00 fee incurred).

___ 2. Have system pumped out

___ 3. Replace Sanitary T

___ 4. **Other – Pending lot recombination shall be performed by surveyor prior to repair of vacant home. Applicant stated intended to re-combine and split land in pending future with surveyor Andy Joyner. Applicant still desired to repair system. Informed to get in touch with surveyor and determine future land allocation prior to repairing vacant home. Repair of system prior to recombination may prevent ability to split lot. Reconfirm with EH when lot has been divided/recombined and applicable repair areas assigned.**

Your application will be put on hold until the selected items above have been addressed. When completed **call 893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Andrew Currin R.E.H.S
Environmental Health Specialist
Harnett County Department of Public Health

AC/kh
Copy - Central Permitting