

www.harnett.org

April 14, 2021

Harnett County Government Complex 307 W. Cornelius Harnett Boulevard Lillington, NC 27546

> ph: 910-893-7547 fax: 910-893-9371

John Miller 182 Adrian Street Holly Springs, NC 27540

Re: Status of Repair Permit for: 182 Adrian Street Holly Springs, NC 27540

Mr. Miller:

An attempt was made to evaluate your property for the purpose of issuing a Repair Permit. The evaluation could not be completed for one or more of the following reasons.

repair	7. Other-Right side property irons and lines shall be clearly visible and marked onsite. Any must meet 10ft side setbacks. Existing septic area marked onsite with white flags. If septic area be installed down the hill, a soil scientist proposal shall be required due to initial soil scientist
	6. Backhoe pits required
	5. Driveway not shown on site plan
	4. Property needs only brush or vegetation removed
	3. Directions not clear to property (\$25.00 fee incurred)
	2. Use orange flags to mark house corners (\$25.00 fee incurred)
<u>X</u>	_ 1. Use pink flags to mark property lines and irons that are set by surveyor need to be visible.

Your application will be put on hold until the selected items above have been addressed. When completed **please call 910-893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,

Andrew Currin, R.E.H.S.

proposed drip repair.

Environmental Health Specialist

Harnett County Department of Public Health

AC/slc

Copy: Central Permitting

Enclosures