

July 27, 2021

Harnett County Government Complex
307 W. Cornelius Harnett Boulevard
Lillington, NC 27546

Tanglewood Properties LLC
PO Box 1436
Apex NC 27502

ph: 910-893-7547
fax: 910-893-9371

Re: Status of Repair Permit for: 106 Tobacco Road Willow Springs, NC

Mr. Ingraham:

An attempt was made to evaluate your property for the purpose of issuing a Repair Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Use pink flags to mark property lines and irons that are set by surveyor need to be visible.
- 2. Use orange flags to mark house corners (*\$25.00 fee incurred*)
- 3. Directions not clear to property (*\$25.00 fee incurred*)
- 4. Property needs only brush or vegetation removed
- 5. Driveway not shown on site plan
- 6. Backhoe pits required
- 7. Other- General Maintenance Advised – Inlet access full to inside riser. Appears to occasionally overflow with heavy use. Blockage or crush likely. Site appears to show no general maintenance or evaluations have been complete. Advised to have contractor and/or pumper review entire condition of system including but not limited to inlet review, outlet review, and distribution method review. Septic inspection Report shall be provided or coordination with Harnett County environmental Health performed.**

Your application will be put on hold until the selected items above have been addressed. When completed **please call 910-893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Andrew Currin, R.E.H.S.
Environmental Health Specialist
Harnett County Department of Public Health

AC/slc

Copy: Central Permitting

strong roots • new growth