

August 10, 2021

509 E Wake Street Dunn NC 28334

www.harnett.org

Harnett County Government Complex 307 W. Cornelius Harnett Boulevard Lillington, NC 27546

ph: 910-893-7547

fax: 910-893-9371

Re: Status of Repair Permit for: 139 Lane Road Dunn, NC 28334

Mrs. Williams:

_X7.	Other- Onsite evaluation shows tank not uncovered and no pooling of septic fluid in yard.
6.	. Backhoe pits required
5.	Driveway not shown on site plan
4.	Property needs only brush or vegetation removed
3.	Directions not clear to property (\$25.00 fee incurred)
2.	. Use orange flags to mark house corners (\$25.00 fee incurred)
1.	Use pink flags to mark property lines and irons that are set by surveyor need to be visible.
An attempt was made to evaluate your property for the purpose of issuing a Repair Permit. The evaluation could not be completed for one or more of the following reasons.	

Homeowner advised to do full maintenance of system in advance of looking into septic repair. Recommended to evaluate both ends of tank and distribution method for blockages or damage. Repair as needed. To receive a repair permit (new lines, tank) the applicant would be required to provide soil scientist proposal on property. Repair would likely require unconventional repair.

Coordinate with certified septic contractor and reconfirm if traditional maintenance is unsuccessful.

Soil evaluation shows soil is generally unsuitable to repair in vicinity of home.

Your application will be put on hold until the selected items above have been addressed. When completed please call 910-893-7547 to confirm that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,

Andrew Currin, R.E.H.S. Environmental Health Specialist Harnett County Department of Public Health

AC/slc