

May 25, 2022

www.harnett.org

Harnett County Government Complex 307 W. Cornelius Harnett Boulevard Lillington, NC 27546

ph: 910-893-7547 fax: 910-893-9371

Carolyn S. Dorman CSJD LTD LLC 205 Pineview Drive Erwin, NC 28339

Re: Status of Repair Permit for: 8287 NC 27 E Coats, NC 27521

Ms. Carolyn Dorman:
An attempt was made to evaluate your property for the purpose of issuing a Repair Permit. The evaluation could not be completed for one or more of the following reasons.
1. Use pink flags to mark property lines and irons that are set by surveyor need to be visible.
2. Use orange flags to mark house corners (\$25.00 fee incurred)
3. Directions not clear to property (\$25.00 fee incurred)
4. Property needs <u>only</u> brush or vegetation removed
5. Driveway not shown on site plan
6. Backhoe pits required
X 7. Other-Only inlet end of tank uncovered and exposed. Tank is old large slab lid tank. Drain field area shows no surfacing nor any signs of failure. Sufficient repair exist on property but would require left property line to be surveyed, new septic tank, new pump tank, and new drain field. Ownership advised to coordinate with a licensed septic contractor to do a full and extensive review of existing septic tank for functionality and safety prior to proceeding to full repair. Entire septic tank and drain field could likely not have been evaluated with only inlet lid exposed.

Your application will be put on hold until the selected items above have been addressed. When completed **please call 910-893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,

Andrew Currin, R.E.H.S.

Environmental Health Specialist

Harnett County Department of Public Health

AC/slc