

November 13th, 2025

Harnett County Government Complex
307 W. Cornelius Harnett Boulevard
Lillington, NC 27546

ph: 910-893-7550
fax: 910-893-9429

Lloyd Burch
316 Kinnis Creek Dr
Angier, NC 27501

Re: Status of Permit Application-EH2510-0016

To whom it may concern,

An attempt was made to evaluate your property for issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Survey Corner Irons need to be uncovered and clearly demonstrated. Have surveyor flag/mark every 50' between property survey corner irons. (25.00 Fee Incurred)
- 2. House Box needs to be marked/demonstrated clearly. (25.00 Fee Incurred)
- 3. Directions not clear to property (*\$25.00 fee incurred*)
- 4. Needs more clearing. Do not disturb the soil. Need access points to do evaluations.
- 5. Driveway not shown on site plan
- 6. Backhoe Pits Required

X 7. Other- Will need a septic inspection report turned into Environmental Health stating that the current septic system is still functional and that each septic line is cleared from blockages. Will need a septic contractor to locate and demonstrate both existing 2 – 100' lines (marked/flagged). Will need a surveyor to uncover/demonstrate property survey corner irons and mark the property lines every 50' between irons.

Your application will be put on hold until the selected items above have been addressed.
Please call 910-893-7525 to schedule your property for evaluation.

Sincerely,



Reynold Levocz, REHS
Environmental Health Specialist
RL/kh
Copy: Central Permitting