

Application # \_\_\_\_\_

**Harnett County Central Permitting**

PO Box 65 Lillington, NC 27546 - Ph: 910-893-7525 - Fx: 910-893-2793 - www.harnett.org/permits

**Certification of Work Performed By Owner/Contractor  
(Individual Trade Application)**

Owner (s) of Structure: WILLIAM HANRATTY Phone: 608 384-5651

Owner (s) Mailing Address: 1266 COACHMAN WAY SANFORD NC 27332

Land Owner Name (s): WILLIAM HANRATTY Phone: 608-384-5651

Construction or Site Address: 1266 COACHMAN WAY SANFORD NC 27332

PIN # 9585-74-2700.000 Parcel # 03958520 0195

Job Cost: 9798.00 Description of Work to be done REPLACING WHOLE HOUSE SPLIT HEAT PUMP  
MOVING ODU AND ADDING NEW ELECTRICAL CIRCUIT

Mechanical: New Unit With Ductwork  New Unit Without Ductwork  Gas Piping  Other

Electrical\*: 200 Amp  <200 Amp  Service Change  Service Reconnect  Other   
\* For Progress Energy customers we need the premise number

Plumbing: Water/Sewer Tap  Number of Baths  Water Heater

Specific Directions to Job from Lillington:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subdivision: BLK T CLAKES Lot #: 195

I ARS will provide the MECHHANICAL/ELECTRICAL labor on this structure.  
(Contractors Name) (Trade)

I am the building owner or my NC state license number is 29147/28807, which entitles me to perform such work on the above structure legally. All work shall comply with the State Building Code and all other applicable State and local laws, ordinances and regulations.

AMERICAN RESIDENTIAL SERVICES LLC  
Contractor's Company Name  
517 PYLON DRIVE RALEIGH NC 27606  
Address  
MECH29147/ELEC28807  
License #

919-861-0883  
Telephone  
8876INSPECTIONS@ARS.COM  
Email Address

Structure Owner / Contractor Signature:  Date: 1/28/2022

By signing this application you affirm that you have obtained permission from the above listed license holder to purchase permits on their behalf. If doing the work as owner you understand that you cannot rent, lease or sell the listed property for 12 months after completion of the listed work.

**\*Company name, address, & phone must match information on license**