

Harnett County Central Permitting

PO Box 65 Lillington, NC 27546 - Ph: 910-893-7525 - Fx: 910-893-2793 - www.harnett.org/permits

**Certification of Work Performed By Owner/Contractor
(Individual Trade Application)**

Owner (s) of Structure: Shelley & James Linder Phone: 910-751-2160

Owner (s) Mailing Address: 433 Robeson St. Spring Lake, NC 28390

Land Owner Name (s): Shelley & James Linder Phone: 910-751-2160

Construction or Site Address: 433 Robeson St. Spring Lake, NC 28390

PIN # _____ Parcel # _____

Job Cost: \$10,973 Description of Work to be done Changeout and Reconnect 2.0 Ton Heat Pump & Air Handler located in the attic unit service for Upstairs Closet in Master Bedroom - Like for Like.

Mechanical: New Unit With Ductwork New Unit Without Ductwork Gas Piping Other

Electrical*: 200 Amp <200 Amp Service Change Service Reconnect Other

* For Progress Energy customers we need the premise number

Plumbing: Water/Sewer Tap Number of Baths Water Heater

Specific Directions to Job from Lillington:

Subdivision: _____ Lot #: _____

I Jimmy Pierce/Joel Worsham will provide the mechanical/electrical labor on this structure.
(Contractors Name) (Trade)

I am the building owner or my NC state license number is 18855/21474, which entitles me to perform such work on the above structure legally. All work shall comply with the State Building Code and all other applicable State and local laws, ordinances and regulations.

Comfort First Heating and Cooling
Contractor's Company Name
7001 Lark Lane, Sanford NC 27332
Address
18855/21474
License # _____

919-569-5161
Telephone
installadmin@yourcomfortfirst.com
Email Address

Structure Owner / Contractor Signature: Jimmy Pierce & Joel Worsham Date: 1/2/2025

By signing this application you affirm that you have obtained permission from the above listed license holder to purchase permits on their behalf. If doing the work as owner you understand that you cannot rent, lease or sell the listed property for 12 months after completion of the listed work.

***Company name, address, & phone must match information on license**