

Harnett County Central Permitting

PO Box 65 Lillington, NC 27546 - Ph: 910-893-7525 - Fx: 910-893-2793 - www.harnett.org/permits

**Certification of Work Performed By Owner/Contractor
(Individual Trade Application)**Owner (s) of Structure: Mhaelyn Nanquil Phone: 858-414-7704Owner (s) Mailing Address: 56 Education Dr. Spring Lake, NC 28390Land Owner Name (s): Mhaelyn Nanquil Phone: 858-414-7704Construction or Site Address: 56 Education Dr. Spring Lake, NC 28390

PIN # _____ Parcel # _____

Job Cost: \$4,670 Description of Work to be done Changeout and Reconnect 2.5 Ton Heat Pump & Air Handler located in the attic unit service for downstairs - Like for Like.Mechanical: New Unit With Ductwork _____ New Unit Without Ductwork ☒ Gas Piping _____ Other _____

Electrical*: 200 Amp _____ <200 Amp _____ Service Change _____ Service Reconnect _____ Other _____

* For Progress Energy customers we need the premise number

Plumbing: Water/Sewer Tap _____ Number of Baths _____ Water Heater _____

Specific Directions to Job from Lillington:

Subdivision: _____ Lot #: _____

I Jimmy Pierce/Joel Worsham will provide the mechanical/electrical labor on this structure.
(Contractors Name) (Trade)I am the building owner or my NC state license number is 18855/21474, which entitles me to perform such work on the above structure legally. All work shall comply with the State Building Code and all other applicable State and local laws, ordinances and regulations.Comfort First Heating and CoolingContractor's Company Name7001 Lark Lane, Sanford NC 27332Address18855/21474License #919-569-5161Telephoneinstalladmin@yourcomfortfirst.comEmail AddressStructure Owner / Contractor Signature: Jimmy Pierce & Joel Worsham Date: 5/2/2025

By signing this application you affirm that you have obtained permission from the above listed license holder to purchase permits on their behalf. If doing the work as owner you understand that you cannot rent, lease or sell the listed property for 12 months after completion of the listed work.

***Company name, address, & phone must match information on license**