


Highland Hills Lot #40 5-10-93

Reverse grade with high spot



D-box not level

- 1-3 inches of gravel under pipe
- not enough gravel in general