

COMMENTS:

Top of Tent is Damaged - Appears to be
Driven over by large Truck etc. Tent
& D Box need Replacing

ONSITE WASTEWATER REPAIR DATA CHECKLIST

1. Physical location of system. (911 address)

58 Stone Cliff

2. Type of landuse being served by system. SFR

3. Age of system. (approximate is cannot confirm) 12 yrs

4. Type of system. Gravel

5. Type of replacement system. - Replacing Damaged Tank

6. Contributing factors to failure. Tank Damaged ~~due~~ Due To Traffic

7. Onsite or offsite solution. Onsite

8. Type of soil in initial system area. No holes dug

9. Type of soil in replacement system area. No holes dug