

Brian Samuels

59 Bark Way , Angier, NC 27501

07/29/2024

Project Information

Project Name	Brian Samuels	Customer Phone Number	(929) 422-9685
Customer Address	59 Bark Way , Angier, NC 27501	Installation Date	07/29/2024

Job Check In

Was the customer home for install?	Yes	MSP Check - Red Flags Present?	No
Did the Customer agree to the equipment location?	Yes	Does Structure Match Plans?	Yes
Roof Check - Red Flags Present?	No	Structural Check - Red Flags Present?	No
MSP Check - Does MSP Match Plans?	Yes	Miscellaneous - Red Flags Present?	No

Project Completion Photos

Site and Safety

Rooftop Installation

Roof Type	Comp Shingle	Does this project have a attic run?	Yes
Comp Shingle Mounting Method	Rail-less	Conduit Transition	Attic Run Only
Railless - Flashed or Flashless	Flashless	Does this project include a Trench?	No
Does the Job Require Unirac Tilt Legs?	No	J-Box Type	Deck Mounted J-Box

Electrical Installation

Were Consumption CT's installed on this project? No

Was there any Electrical Equipment/Conduit Installed Inside The Garage/Home? No

Why were Consumption CT's not installed on this project?

none available

Does This Project Include a Battery? No

Commissioning

Was the Inverter/Combiner Commissioned? Yes

Were there any errors during the commissioning process? No

Does this project include a battery? No

Was PCS utilized or required on the SLD for this project? No

Crew Lead Review + Quality Assurance

Was there a need to change the layout? No, was able to install layout as designed.

Design Change Approved By: None

Was there a need to change the point of interconnection method? No, was able to install POI as designed.

Are There Any Remaining Punchlist Items? No

Was there a need to change the BOS Location? No, was able to install as designed.

Was permit left onsite? No

Customer Installation Review

Is the customer home? Yes

Was the Monitoring set up reviewed with the customer? Yes

Was the Installation reviewed with the customer? Yes

Any customer requests outside of punchlist items?

Was the final layout reviewed with the customer? Yes

No

Miscellaneous - Trenching, Critter Guard, Rafter Upgrades

Removal/Reinstall? No

Are The Gas & Electrical Meter On The Same Wall?

Job Check In / Picture of Front of the House



RGH03
Loc: 35.463, -78.8031

Job Check In / Picture of Front of the House



RGH03
Loc: 35.463, -78.8031

Project Completion Photos / Complete Array Photos (all modules MUST be visible in each array)



RGH03
Loc: 35.4629, -78.8029

Project Completion Photos / Complete Array Photos (all modules MUST be visible in each array)




RGH03
Loc: 35.4629, -78.8029

Project Completion Photos / Pullback Photos of All BOS Mounted in Completed State



RGH03
Loc: 35.463, -78.803

Project Completion Photos / Equipment Labels Complete



RGH03
Loc: 35.463, -78.803

Project Completion Photos / Equipment Labels Complete



RGH03
Loc: 35.463, -78.803

Project Completion Photos / Equipment Labels Complete



RGH03
Loc: 35.463, -78.803

Project Completion Photos / Equipment Labels Complete



RGH03
Loc: 35.463, -78.803

Project Completion Photos / Equipment Labels Complete



RGH03
Loc: 35.463, -78.803

Project Completion Photos / Equipment Labels Complete



RGH03
Loc: 35.463, -78.803

Project Completion Photos / Equipment Labels Complete



RGH03
Loc: 35.463, -78.803

Rooftop Installation / Completed Roof Attachment



RGH03
Loc: 35.4629, -78.8028

Rooftop Installation / Completed Roof Attachment



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / Close Up of Railless Coupling Installed



RGH03
Loc: 35.4629, -78.8028

Rooftop Installation / Close Up of Skirt Splice + Skirt Roof Attachment Complete



RGH03
Loc: 35.4629, -78.8028

Rooftop Installation / Close Up of Skirt Splice + Skirt Roof Attachment Complete



RGH03
Loc: 35.4629, -78.8028

Rooftop Installation / Optimizer/ Micro Inverter Installed



RGH03

Rooftop Installation / Module Ready Photos



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / Module Ready Photos



RGH03
Loc: 35.4629, -78.8028

Rooftop Installation / Module Ready Photos



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / Module Ready Photos



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / Module Ready Photos




RGH03
Loc: 35.4629, -78.8028

Rooftop Installation / Module Label




RGH03
Loc: 35.4628, -78.8028

Rooftop Installation / Module Gapping: Tape Measure showing 3/8" - 1" Gap



RGH03
Loc: 35.4629, -78.8028

Rooftop Installation / Module Gapping: Tape Measure showing 3/8" - 1" Gap




RGH03
Loc: 35.4629, -78.8028

Rooftop Installation / Module Gapping: Tape Measure showing 3/8" - 1" Gap



RGH03
Loc: 35.4629, -78.8028

Rooftop Installation / Array Bonding/Grounding



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / Array Bonding/Grounding



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03
Loc: 35.463, -78.8029

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / Entire Attic Run



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / Entire Attic Run



RGH03
Loc: 35.463, -78.8029

Rooftop Installation / Entire Attic Run



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / Entire Attic Run



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / Entire Attic Run



RGH03
Loc: 35.4631, -78.803

Rooftop Installation / Entire Attic Run



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / Entire Attic Run




RGH03
Loc: 35.463, -78.8029

Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)




RGH03
Loc: 35.4628, -78.8029

Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)



RGH03
Loc: 35.4629, -78.8029

Rooftop Installation / J-Box Completed W/ Lid Installed



RGH03
Loc: 35.4629, -78.8029

Electrical Installation / Close Up Photo of Panel Label + Main Breaker Rating on The Breaker




RGH03
Loc: 35.463, -78.803

Electrical Installation / The Main Service Panel's GEC



RGH03
Loc: 35.463, -78.803

Electrical Installation / Point of Interconnection




RGH03
Loc: 35.463, -78.803

Electrical Installation / Close Up Photo of the OCPD Rating for PV




RGH03
Loc: 35.463, -78.803

Electrical Installation / Inverter/Combiner Installed & Wired




RGH03
Loc: 35.463, -78.803

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component




RGH03
Loc: 35.463, -78.803

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component




RGH03
Loc: 35.463, -78.803

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component




RGH03
Loc: 35.463, -78.803

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component



RGH03
Loc: 35.463, -78.803

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component



RGH03
Loc: 35.463, -78.803



RGH03
Loc: 35.463, -78.8029



RGH03




RGH03




RGH03



RGH03



RGH03



RGH03



RGH03



RGH03



RGH03



RGH03



RGH03

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03
Loc: 35.4631, -78.8033

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03
Loc: 35.4627, -78.803

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03
Loc: 35.4629, -78.8031

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03
Loc: 35.4629, -78.8029

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03
Loc: 35.4629, -78.8029

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03
Loc: 35.4629, -78.8029



RGH03
Loc: 35.4629, -78.8029



RGH03
Loc: 35.4631, -78.8029