

## Spencer Richard

44 Jack Harris Ln , Spring Lake, NC 28390

12/10/2024

### Project Information

Project Name	Spencer Richard	Customer Phone Number	(910) 587-4736
Customer Address	44 Jack Harris Ln , Spring Lake, NC 28390	Installation Date	12/10/2024

### Job Check In

#### PHOTO REQUIREMENT NOTICE

FAILURE TO FULLY COMPLETE THIS SITE CAPTURE FORM WITH ALL PHOTOS AND INFORMATION PER FINANCE COMPANY REQUIREMENTS WILL RESULT IN A FORFEIT OF CREW PAY BONUS

PHOTO REQUIREMENT ACKNOWLEDGMENT Acknowledged

What is the financing company for this job? Mosaic

Was the customer home for install? Yes

Did the Customer agree to the equipment location? Yes

Roof Check - Red Flags Present? No

MSP Check - Does MSP Match Plans? Yes

MSP Check - Red Flags Present? No

Does Structure Match Plans? Yes

Structural Check - Red Flags Present? No

Miscellaneous - Red Flags Present? No

### Project Completion Photos

How many arrays were installed on this project? 3 Arrays

Person responsible for Optimizer/ Micro documentation Elvis+ Luis + Sergio

### Site and Safety

Was attic work performed on this project? Yes

### Rooftop Installation

Roof Type	Comp Shingle
Comp Shingle Mounting Method	Rail-less
Railless - Flashed or Flashless	Flashless
Does the Job Require Unirac Tilt Legs?	No

Does this project have a attic run?	Yes
Conduit Transition	Internal Conduit Entry Point
Does this project include a Trench?	No
J-Box Type	Deck Mounted J-Box

### Electrical Installation

Does this project require an MPU?	No
Were Consumption CT's installed on this project?	No
Why were Consumption CT's not installed on this project?	Not required by Finance

Was there any Electrical Equipment/Conduit Installed Inside The Garage/Home?	No
Does This Project Include a Battery?	No

### Commissioning

Was the Inverter/Combiner Commissioned?	Yes
Is this a Everbright Financed project?	No
Were CT's installed on this project?	No

Does this project include a battery?	No
Were there any errors during the commissioning process?	No
Was PCS utilized or required on the SLD for this project?	No

### Crew Lead Review + Quality Assurance

Was there a need to change the layout?	No, was able to install layout as designed.
Was there a need to change the piont of interconnection method?	No, was able to install POI as designed.
Was there a need to change the BOS Location?	No, was able to install as designed.

Design Change Approved By:	None
Are There Any Remaining Punchlist Items?	No
Was permit left onsite?	No

### Customer Installation Review

Is the customer home?	Yes
Was the Installation reviewed with the customer?	Yes

Was the Monitoring set up reviewed with the customer?	Yes
Any customer requests outside of punchlist items?	

---

Was the final layout reviewed  
with the customer?      Yes

No

---

**Miscellaneous - Trenching, Critter Guard, Rafter Upgrades**

---

Removal/Reinstall?      No


Are The Gas & Electrical Meter  
On The Same Wall?

Job Check In / Picture of Front of the House with Address Visible



RGH03  
Loc: 35.2553, -78.9511

Project Completion Photos / Photo of array 1



RGH03  
Loc: 35.2554, -78.9509

Project Completion Photos / Photo of array 1



RGH03  
Loc: 35.2553, -78.9509

Project Completion Photos / Photo of array 1



RGH03  
Loc: 35.2554, -78.9509



Project Completion Photos / Photo of array 2



RGH03  
Loc: 35.2554, -78.9509

Project Completion Photos / Photo of array 2



RGH03  
Loc: 35.2554, -78.9509

Project Completion Photos / Photo of array 3



RGH03  
Loc: 35.2554, -78.9509

Project Completion Photos / Pullback Photos of All BOS Mounted in Completed State



RGH03  
Loc: 35.5724, -78.5197



Project Completion Photos / Equipment Labels Complete



RGH03  
Loc: 35.5725, -78.5196

Project Completion Photos / Equipment Labels Complete



RGH03  
Loc: 35.5725, -78.5196

Project Completion Photos / Equipment Labels Complete



RGH03  
Loc: 35.5725, -78.5196

Project Completion Photos / Equipment Labels Complete



RGH03  
Loc: 35.5725, -78.5196

Project Completion Photos / Equipment Labels Complete



RGH03  
Loc: 35.5725, -78.5196

Project Completion Photos / Equipment Labels Complete



RGH03  
Loc: 35.5725, -78.5196

Project Completion Photos / Equipment Labels Complete



RGH03  
Loc: 35.5725, -78.5196

Rooftop Installation / Completed Roof Attachment



RGH03  
Loc: 35.2552, -78.951



Rooftop Installation / Completed Roof Attachment



RGH03  
Loc: 35.2553, -78.9515

Rooftop Installation / Close Up of Railless Coupling Installed



RGH03  
Loc: 35.2553, -78.9516

Rooftop Installation / Close Up of Skirt Splice + Skirt Roof Attachment Complete



RGH03  
Loc: 35.2553, -78.9508

Rooftop Installation / Close Up of Skirt Splice + Skirt Roof Attachment Complete



RGH03  
Loc: 35.2553, -78.9508



Rooftop Installation / 2 Optimizer's/ Micro Inverter's/ Tesla MCI's Installed



RGH03  
Loc: 35.2554, -78.9516

Rooftop Installation / 2 Optimizer's/ Micro Inverter's/ Tesla MCI's Installed



RGH03  
Loc: 35.2555, -78.9511

Rooftop Installation / 2 Optimizer's/ Micro Inverter's/ Tesla MCI's Installed



RGH03  
Loc: 35.2555, -78.9508

Rooftop Installation / 2 Optimizer's/ Micro Inverter's Model Number



RGH03  
Loc: 35.2551, -78.9515



Rooftop Installation / 2 Optimizer's/ Micro Inverter's Model Number




RGH03  
Loc: 35.2554, -78.951

Rooftop Installation / 2 Optimizer's/ Micro Inverter's Model Number



RGH03  
Loc: 35.2554, -78.951

Rooftop Installation / Module Ready Photos



RGH03  
Loc: 35.2554, -78.951

Rooftop Installation / Module Ready Photos



RGH03  
Loc: 35.2554, -78.9509




Rooftop Installation / Module Ready Photos



RGH03  
Loc: 35.2554, -78.9508

Rooftop Installation / Module Ready Photos



RGH03  
Loc: 35.2555, -78.9509

Rooftop Installation / Module Ready Photos



RGH03  
Loc: 35.2553, -78.9513


Rooftop Installation / Module Ready Photos



RGH03  
Loc: 35.2554, -78.9508



Rooftop Installation / Module Ready Photos



RGH03  
 Loc: 35.2554, -78.9508

Rooftop Installation / Module Ready Photos



RGH03  
 Loc: 35.2553, -78.9509

Rooftop Installation / Module Ready Photos



RGH03  
 Loc: 35.2554, -78.9509

Rooftop Installation / Module Label



RGH03  
 Loc: 35.2552, -78.9516




Rooftop Installation / Module Gapping: Tape Measure showing 3/8" - 1" Gap



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Module Gapping: Tape Measure showing 3/8" - 1" Gap




RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Module Gapping: Tape Measure showing 3/8" - 1" Gap



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Array Bonding/Grounding



RGH03  
Loc: 35.2554, -78.9508



Rooftop Installation / Array Bonding/Grounding



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509



Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509



Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509



Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9508

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)




RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2552, -78.9514



Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9508

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9508

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509



Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9508

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2555, -78.9509



Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509



Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / Entire Attic Run



RGH03  
Loc: 35.2554, -78.9509



Rooftop Installation / LB entering home w/ duct seal



RGH03  
Loc: 35.5725, -78.5196

Rooftop Installation / LB entering home w/ duct seal



RGH03  
Loc: 35.5725, -78.5196

Rooftop Installation / Conduit run to BOS



RGH03  
Loc: 35.2553, -78.9513


Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)



RGH03  
Loc: 35.2555, -78.951




Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)




RGH03  
Loc: 35.2554, -78.9508

Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)



RGH03  
Loc: 35.2554, -78.9508

Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)



RGH03  
Loc: 35.2554, -78.9509



Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)




RGH03  
Loc: 35.2553, -78.9514

Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)



RGH03  
Loc: 35.2553, -78.9513

Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)



RGH03  
Loc: 35.2554, -78.9509


Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)



RGH03  
Loc: 35.2554, -78.9509



Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)




RGH03  
Loc: 35.2555, -78.951

Rooftop Installation / J-Box Completed W/ Lid Installed



RGH03  
Loc: 35.2555, -78.9508

Rooftop Installation / J-Box Completed W/ Lid Installed



RGH03  
Loc: 35.2554, -78.9509

Rooftop Installation / J-Box Completed W/ Lid Installed



RGH03  
Loc: 35.2554, -78.9512




Rooftop Installation / Appropriate Racking Markings




RGH03  
Loc: 35.2552, -78.951

Rooftop Installation / Appropriate Racking Markings



RGH03  
Loc: 35.2552, -78.951

Electrical Installation / Pullback of Main Panel with Dead front Removed  
\*Regardless of tie-in method\*



RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / Pullback of Main Panel with Dead front On \*Regardless  
of tie-in method\*



RGH03  
Loc: 35.2551, -78.9512



Electrical Installation / Close Up Main Breaker with Rating visible



RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / The Main Service Panel's GEC



RGH03  
Loc: 35.5725, -78.5196

Electrical Installation / The Main Service Panel's GEC



RGH03  
Loc: 35.5725, -78.5196


Electrical Installation / The Main Service Panel's GEC



RGH03  
Loc: 35.5725, -78.5196



Electrical Installation / Point of Interconnection




RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / Point of Interconnection



RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / Point of Interconnection



RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / Close Up Photo of the OCPD Rating for PV



RGH03  
Loc: 35.2551, -78.9512




Electrical Installation / Close Up Photo of the OCPD Rating for PV




RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / Inverter/Combiner Installed & Wired



RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / Inverter/Combiner Installed & Wired



RGH03  
Loc: 35.2551, -78.9512


Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component



RGH03  
Loc: 35.2551, -78.9512




Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component




RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component




RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component



RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component



RGH03  
Loc: 35.2551, -78.9512




Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component




RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component



RGH03  
Loc: 35.2551, -78.9512

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component



RGH03  
Loc: 35.2551, -78.9512

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.0378, -78.9658





RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658




RGH03  
Loc: 35.0378, -78.9658






RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658





RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658




RGH03  
Loc: 35.0378, -78.9658





RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658




RGH03  
Loc: 35.0378, -78.9658






RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658





RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658




Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.0378, -78.9658

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.0378, -78.9658

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders




RGH03  
Loc: 35.0378, -78.9658

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.0378, -78.9658





RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658



RGH03  
Loc: 35.0378, -78.9658






RGH03  
Loc: 35.2552, -78.951



RGH03  
Loc: 35.2554, -78.9509



RGH03  
Loc: 35.2554, -78.9511



RGH03  
Loc: 35.2554, -78.9509






RGH03  
Loc: 35.2554, -78.9508



RGH03  
Loc: 35.2554, -78.9508




RGH03  
Loc: 35.2548, -78.9511



RGH03  
Loc: 35.2554, -78.9509



Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2554, -78.9509

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2554, -78.9509

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2554, -78.9509

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2553, -78.9511



Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2554, -78.9511

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2554, -78.951

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2554, -78.951

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2554, -78.951





RGH03  
Loc: 35.2554, -78.951



RGH03  
Loc: 35.2554, -78.951



RGH03  
Loc: 35.2554, -78.951



RGH03  
Loc: 35.2554, -78.951



Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2554, -78.951

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders




RGH03  
Loc: 35.2549, -78.9508

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2554, -78.9508


Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.255, -78.9515



Crew Lead Review + Quality Assurance / Screenshot of Missing Addrs



RGH03  
Loc: 35.2554, -78.951

Crew Lead Review + Quality Assurance / Screenshot of Missing Addrs




RGH03  
Loc: 35.2549, -78.9515

Crew Lead Review + Quality Assurance / Screenshot of Missing Addrs



RGH03  
Loc: 35.2554, -78.9508

Crew Lead Review + Quality Assurance / Screenshot of Missing Addrs



RGH03  
Loc: 35.2554, -78.9509



Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2554, -78.9509

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2548, -78.9516

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2553, -78.9509

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2551, -78.9512



Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2553, -78.9509

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2553, -78.9512

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.255, -78.951

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2553, -78.9508



Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2552, -78.9518

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2553, -78.9512

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2554, -78.9509

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03  
Loc: 35.2553, -78.9511





RGH03  
Loc: 35.2551, -78.9509



RGH03  
Loc: 35.2554, -78.9511



RGH03  
Loc: 35.2553, -78.9509



RGH03  
Loc: 35.2554, -78.9511