

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

ITE \_\_\_\_\_


FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-22	0-18	0-26	0-26									
Texture Group	.1941(A)(1)	CL	CL	CL	CL									
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 2 DEPTH		22-36	18-36	26-36	26-36									
Texture Group	.1941(A)(1)	SC	SC	SC	SC									
Consistence	.1941	Fi/Fi	Fi	Fi/Fi	Fi									
Structure	.1941(A)(2)	SBK	SBK	SBK	SBK									
Mineralogy	.1941(A)(3)	SEP	SEP	SEP	SEP									
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942	-	-	-	-									
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/1956													
CLASSIFICATION	.1948	P <sub>2</sub>	P <sub>2</sub>	P <sub>5</sub>	P <sub>5</sub>									
LONG TERM ACCEPTANCE RATE	.1955	.4	.4	.4	.4									

Watch for well → Ash T.B.


where is neighbors drainfield

3x100' lines  
18-24' deep  
no fall → pump

check for well setback  
by legions out



30x60'  
for PP  
Repair



SITE PLAN APPROVAL  
 DISTRICT N/A USE SFD  
 #BEDROOMS 3  
12-10-99 Jerena Byrd  
 Date Zoning Administrator

*Plot Plan*  
**Price Construction Company**

*Sierra Villa Subdivision Section Nine*  
*PC # F Slide 266-B*  
*Anderson Creek*  
*Harnett* *Township*