

**Harnett County Central Permitting**

PO Box 65 Lillington, NC 27546 - Ph: 910-893-7525 - Fx: 910-893-2793 - www.harnett.org/permits

Certification of Work Performed By Owner/Contractor  
(Individual Trade Application)

Owner (s) of Structure: Howard Lindsley Phone: 919.275.9013

Owner (s) Mailing Address: 175 Jarrett Bay  
FV NC 27529

Land Owner Name (s): Howard Lindsley Phone: 919.275.9013

Construction or Site Address: 175 Jarrett Bay FV NC 27529

PIN # 0674-08-2353.000 Parcel # 040664 0157 06

Job Cost: \$3,291.50 Description of Work to be done Reconnect for replacement  
of heat pump sys. located Crawl.

Mechanical: New Unit With Ductwork \_\_\_ New Unit Without Ductwork \_\_\_ Gas Piping \_\_\_ Other \_\_\_

Electrical\*: 200 Amp \_\_\_ <200 Amp \_\_\_ Service Change \_\_\_ Service Reconnect X Other Heat pump sys  
\* For Progress Energy customers we need the premise number

Plumbing: Water/Sewer Tap \_\_\_ Number of Baths \_\_\_ Water Heater \_\_\_

Specific Directions to Job from Lillington:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subdivision: Alex Place Lot #: 6

I Bobby Baker will provide the Electrical labor on this structure.  
(Contractors Name) (Trade)

I am the building owner or my NC state license number is \_\_\_\_\_, which entitles me to perform such work on the above structure legally. All work shall comply with the State Building Code and all other applicable State and local laws, ordinances and regulations.

Progressive Home Services LLC  
Contractor's Company Name  
821 Purser Dr Raleigh NC 27603  
Address  
U. 07561  
License #

919.407.0050  
Telephone  
permits@callprogressive.com  
Email Address

Structure Owner / Contractor Signature: Bobby William Baker Date: 11-16-2021

By signing this application you affirm that you have obtained permission from the above listed license holder to purchase permits on their behalf. If doing the work as owner you understand that you cannot rent, lease or sell the listed property for 12 months after completion of the listed work.

\*Company name, address, & phone must match information on license